Appendix A

Air Emissions Calculations

Table A1
Maximum Daily Construction Emissions
Loomis-SPMUD Sewer Diversion Pipeline Project

Ma	aximum Da	aily Const	ruction En	nissions i	n 2018 (lbs	s/day)				
Emission Source	NOx	CO	ROG	SOx	PM ₁₀	PM _{2.5}	CO ₂	CH₄	N ₂ O	CO ₂ e
Onsite										
Mobile Equipment Engine Exhaust	12	6.1	1.08	0.024	0.61	0.59	2472	0.10	0.020	2480
Fugitive Dust from Mobile Equipment	-	-	-	-	4.08	0.73	-	-	-	-
Subtotal Onsite in 2018:	12	6.1	1.08	0.024	4.7	1.32	2,472	0.10	0.020	2,480
Offsite										
Worker Travel	0.26	2.0	0.078	0.0054	0.072	0.030	540	0.018	0.0044	542
Fugitive Dust from Worker Travel					4.8	1.17				
Construction Materials Deliveries	0.67	0.052	0.010	0.0016	0.015	0.0089	167	0.00060	0.0014	167
Fugitive Dust from Materials Delivery Trucks					0.92	0.23				
Subtotal Offsite in 2018:	0.93	2.07	0.09	0.0070	5.8	1.43	707	0.019	0.0057	709
Total Daily Construction Emissions in 2018 (rounded)	l 12.9 l	8.2	1.2	0.031	10.5	2.8	3,178	0.12	0.026	3,189

Table A2 2018 Construction Onsite Equipment Hours, Emission Factors, and Emissions Loomis/SPMUD Sewer Pipeline Project

												ARB Off-	Road or EP	A Nonroad	Emission	Factors (g/l	hp-hr)						Onroad	Emission	Factors (It	bs/VMT) (3)								Daily Offr	road Equip	ment Emis	ssions (lbs/	day)							Annı	al Offroad	Equipme	nt Emissior	is (tpy)				
	Loc Facto	Off- d Road (1) (-or On-	BS (lb.	C ⁽²⁾ Annual hp- Use	Daily Use ⁽⁴⁾	Average Speed ⁽⁴⁾	Distance Traveled	Distance		(2) CO	(2) VC	OC ⁽²⁾ S	SOx ⁽⁵⁾ [PM ₁₀ ⁽²⁾ F	M _{2.5} ⁽⁶⁾	CO ₂ ⁽⁷⁾	CH ₄ ^(8,9)	N ₂ O ^(8,10)	CO ₂ e ^{(11,12}	NOx	со	ROG	SOx	PM ₁₀	PM _{2.5}	CO ₂	CH ₄ ^(8,9)	N ₂ O ^(8,10)	⁰⁾ CO ₂ e	(11,12)	NOx	со	voc	SOx	PM ₁₀	PM _{2.5}	CO ₂	CH ₄ ^(8,9)) N ₂ O ⁽¹	(8,10) CC	O ₂ e ^(11,12)	łOx	со	voc	SOx	PM ₁₀	PM _{2.5}	CO ₂	CH ₄ ^(8,9)	N ₂ O ⁽⁸	10) CO ₂	Weigh (tons)	į N
Equipment	HP)	Road?	Tier 1) (hrs/yr) (hrs/day)	(mph)	(mi)	(mi)																																													_
Pickup trucks, three	300 (8)	On	-	173.3	2	5	10.0		-	-		-	-	-	-	-	-	-	-			6.31E-03 3.			2.16E-05 3	3.71E+00	0.000189	0.000030	30 3.7	73 7	7.81E-03 6		6.31E-02	3.72E-04	2.35E-04	2.16E-04	3.71E+01		3,19) 0.00030 (7 (21,22) 3.	38E-04			1.61E-05	1.02E-05	9.37E-0	6 1.61E+0	0.00007	0.0000		61	
Haul/Delivery trucks	400 (1)	On	-	21.7 (16)	0.5	5	2.5	108	-	-		-	-	-	- 1	-	-	-	-			3.69E-03 6.			2.80E-04 7	7.28E+00	0.07779	0.000059	59 9.2	- '		2.53E-02	9.23E-03	1.74E-04	7.30E-04	6.99E-04	1.82E+01	0.0007 (18	3,19) 0.00015 ((,==)	8 (21,22) 2.	76E-03	5.48E-04	2.00E-04	3.76E-06	1.58E-05	1.51E-0	3.94E-0	1 0.00002	0.0000		40	
Vater truck	400 (1) 0.38		-	693.3	8	5	40.0	3467	-			-	-	-	-	-		-	-	2.40E-02	5.63E-03	3.21E-03 4.	72E-05 4.	32E-04 4	1.13E-04 4	4.95E+00	0.00015	0.000040	10 4.9		9.59E-01 2	2.25E-01	1.28E-01	1.89E-03	1.73E-02	1.65E-02	1.98E+02	0.0080 (18	3,19) 0.0016	(10,20)	9 (21,22) 4	16E-02	9.77E-03	5.57E-03	8.19E-05	7.48E-04	7.16E-0	4 8.58E+0	0.00035	0.000		.6	
xcavator	163 (1) 0.38	.,	3 0.	67 347 (16)	8	-	-	-		2.5 0.	8667	0.1836	0.0050	0.22	0.21	531	0.022	0.0043	53	3 -	-	-	-	-	-	-	-	-	-		2.73E+00 9	9.47E-01	2.01E-01	5.46E-03	2.40E-01	2.33E-01	5.80E+02	0.024 (18	3,19) 0.0047	(18,20) 58	2 (21,22) 5.	92E-02	2.05E-02	4.35E-03	1.18E-04	5.21E-03	5.05E-0	1.26E+0	1 0.0005	0.000		2.6 #####	#
Boring machine	206 (1) 0.50		0 0.	67 347 (16)	8	-	-	-	2.1	5 (1) 1.07	73 (1) 0.1	545 (1) 0.0	.0048 (1) 0	.0608 (1)	0.056 (1) 484	.5605 (1)	0.1509 (1)	0.0039		- 0	-	-	-	-	-	-	-	-	-		3.91E+00 1	.95E+00	2.81E-01	8.72E-03	1.10E-01	1.02E-01	8.80E+02	0.0357 (18	3,19) 0.00714 ((18,20) 88	3 (21,22) 8.	48E-02	4.22E-02	6.08E-03	1.89E-04	2.39E-03	2.20E-0	1.91E+0	1 0.00077	0.0001		.14	
Backhoe	98 (1) 0.37		3B 0.	67 173.3 (16)	4	-	-	-		3.0 2.	3655	0.1836	0.0050	0.20	0.19	531	0.022	0.0043		3 -	-	-	-	-	- 1	-	-	-	-		9.59E-01 7		5.87E-02	1.60E-03	6.40E-02	6.20E-02	1.70E+02	0.0069 (18	3,19) 0.0014	(18,20) 17	0 (21,22) 2	08E-02	1.64E-02	1.27E-03	3.46E-05	1.39E-03	1.34E-0	3.68E+0	0.00015	0.000		.7 1.2	Т
Compactor	81 (1) 0.38		3B 0.	67 35	4	1.5	6.0	52		3.0 2.	3655	0.1836	0.0050	0.20	0.19	531	0.022	0.0043	53	3 -	-	-	-	-	- 1	- 1	-	-	-		8.14E-01 6		4.98E-02	1.36E-03	5.43E-02	5.27E-02	1.44E+02	0.0059 (18	3,19) 0.0012	(18,20) 14	5 (21,22) 3.	53E-03	2.78E-03	2.16E-04	5.87E-06	2.35E-04	2.28E-0	4 6.25E-0	1 0.00003	0.000	11 (.6	П
Vheeled Loader	98 (1) 0.37			67 346.7 (16)	8	-	-	-		2.45	0.843	0.10	0.0050	0.11	0.11	531	0.022	0.0043	53	3 -	-	-	-	-	- 1	- 1	-	T -	-	- 1.	.57E+00 5	5.39E-01	6.40E-02	3.19E-03	7.04E-02	6.82E-02	3.40E+02	0.0138 (18	3,19) 0.0028	(18,20) 34	1 (21,22) 3.	40E-02	1.17E-02	1.39E-03	6.92E-05	1.52E-03	1.48E-0	3 7.36E+0	0.00030	0.000	6 7	.4 14.2	Т
Velder	46 (1) 0.45	1) Off	4A 0.	08 173.3 (16)	4	-		-	4.60	7 (1) 5.09	92 (1)	1.21 (1)	0.007 (1)	0.311 (1)	0.311 (1) 56	8.299 (1)	0.109 (1)	***********	572 (21,22) -	-	-	-	-	-	-	-	-	-	- 8	8.41E-01 9	9.30E-01	2.21E-01	1.28E-03	5.68E-02	5.68E-02	1.04E+02	0.004 (18	3,19) 0.0008		4 (21,22) 1.	82E-02	2.01E-02	4.79E-03	2.77E-05	1.23E-03	1.23E-0	3 2.25E+0	0.00009	0.000	2 2	26	⊥
	Total:	-	-	2,310	-	-		-	-	-		-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	11.9	6.1	1.08	0.024	0.61	0.59	2,472	0.10	0.02	20	2,480 ().27	0.13	0.027	0.00055	0.013	0.012	56	0.0023	0.000	6 :	i6	
EMFAC2014 for part of Placer Estimated	Emission Factors for Nonroad En County in the Sacramento Valley								ly 2010																																												
	ng 15 ppmw sulfur in Diesel fuel.																																																				
PM _{2.5} /PM ₁₀ ratio (Footnote 2) Density of Distillate Fuel No. 2 CO ₂ emission factor for Distillat			.1346	(CFR Part 98 (CFR Part 98																																																	
CO ₂ emission factor for gasoline	e (metric tons CO2/bbl fuel) =		3686	(CFR Part 98	Subpart M	IM, Table M	MM-1)																																														
Diesel fuel CO ₂ emission facto	r (kg CO ₂ /MMBtu) = 73.96	(EPA, 20	3 Revisions	to the Greenhouse	Gas Repo	rting Rule a	and Final C	Confidentialit	ity Determin	nations for Ne	w or Subst	antitally Revi	rised Data Ele	ments: Final	Rule. Federal	Register, Vo	ume 78. Nur	nber 230. Tabl	e C-1 to Sub	part C. p. 719	51. November	29. 2013.)																															
Diesel fuel CH ₄ emission facto	r (kg CH _a /MMBtu) = 0.003			to the Greenhouse																																																	
Diesel fuel N ₂ O emission fact	or (kg N ₂ O/MMBtu) = 0.0006			to the Greenhouse																																																	
CH ₄ Global Warming Potenti				to the Greenhouse																																																	
N ₂ O Global Warming Potenti	al (-) = 298			to the Greenhouse																																																	
Caterpillar, Cat Resource Ce	nter , http://www.catresourcecente								,						,		,		,																																		
Assumed same as off-highwa	y trucks in CalEEMod Appendix I	Table 3.3.																																																			

14)

15) Assumed same as off-highway trucks in CaliEEMod Appendix D Table 3.3.

16) Equipment used for half the period of Phase 3 because other activities occupy the other half (e.g., mobilization/demobilization/maintenance/weather delay).

Table A3 Construction Fugitive Dust Emission Summary Loomis-SPMUD Sewer Diversion Pipeline Project

Daily Constituction	n Fugitive Dust Emis	,,,,,,,,		Annual Construction		110010113	
	PM _{2.5} (lb/day)				PM _{2.5} (tpy)		
		Daily Fug Emiss	ion by			Emiss	igitive Dus
		Construct					tion Phase
Equipment	Project Year:	2017	2018	Equipment	Project Year:	2017	2018
Pickup trucks, th		0.031	0.031	Pickup trucks, three		0.0037	0.0014
Haul/Delivery tru	icks	0.020	0.020	Haul/Delivery trucks		0.0024	0.0004
Water truck		0.27	0.27	Water truck		0.032	0.011
Dump truck		0.16	0	Dump truck		0.019	0
Excavator		0.11	0.11	Excavator		0.013	0.0023
• , ,	ring(2018) Machine	0.014	0.11	Paving(2017)/Boring	(2018) Machine	0.00016	0.0023
Backhoe		0.053	0.053	Backhoe		0.0063	0.0012
Compactor		0.073	0.036	Compactor		0.00058	0.0001
Wheeled Loader	0 1:4:4:1 (11:41:1)	0.11	0.11	Wheeled Loader	0.14.4.176.	0.013	0.0023
PM _{2.5}	Subtotal (lbs/day) =	0.83	0.73	PW _{2.5}	Subtotal (tpy) =	0.09	0.021
	PM ₁₀ (lb/day)				PM ₁₀ (tpy)		
	10 ()	Daily Fug	itive Dust		· ···· (0 (-P3)	Annual Fu	aitive Du
		Emiss					sion by
		Construct				Construc	-
Equipment	Project Year:	2017	2018	Equipment	Project Year:	2017	2018
Pickup trucks, th		0.31	0.31	Pickup trucks, three		0.0375	0.0014
Haul/Delivery tru		0.20	0.20	Haul/Delivery trucks		0.0237	0.0004
Water truck		2.65	2.65	Water truck		0.316	0.011
Dump truck		1.59	2.00	Dump truck		0.189	0.011
•			0.40	· · · · · · · · · · · · · · · · · · ·			
Excavator		0.19	0.19	Excavator		0.023	0.0023
<u> </u>	ring(2018) Machine	0.048	0.19	Paving(2017)/Boring	(2018) Machine	0.00162	0.002
Backhoe		0.10	0.10	Backhoe		0.0115	0.001
Compactor		0.48	0.24	Compactor		0.00577	0.0001
Wheeled Loader		0.19	0.19	Wheeled Loader		0.023	0.0023
PM ₁₀	Subtotal (lbs/day) =	5.77	4.08	PM ₁₀	Subtotal (tpy) =	0.63	0.021
	PM _{2.5} (lb/day)			-	PM _{2.5} (tpy)		
	1 m _{2.5} (15/44)	Daily Fug	itivo Duet		1 III2.5 (tp3)	Annual Fu	aitivo Du
		Emiss					sion by
		Construct	,			Construc	•
Cauras	Dualant V	2017	2018	Sauraa	Duoiset Verm	2017	2018
Source	Project Year:	-		Source	Project Year:		
	active construction	0.00022	0.00022	Windblown Dust (acti		0.000027	0.0000
	Subtotal (lbs/day) = M _{2.5} Total (lbs/day) =	0.00022	0.00022		Subtotal (tpy) =	0.000027	0.0000
PI	W _{2.5} Total (IDS/day) =	0.83	0.73	P	M _{2.5} Total (tpy) =	0.089	0.021
	PM ₁₀ (lb/day)				PM ₁₀ (tpy)		
		Daily Fug	itive Dust			Annual Fu	gitive Du
		Emiss	ion by			Emiss	sion by
		Construct	ion Phase			Construc	tion Phas
Source	Project Year:	2017	2018	Source	Project Year:	2017	2018
Windblown Dust (active construction	0.00056	0.00056	Windblown Dust (acti	•	0.000067	0.00002
	Subtotal (lbs/day) =	0.00056	0.00056		Subtotal (tpy) =	0.000067	0.00002
	M ₁₀ Total (lbs/day) =	5.8	4.1		M ₁₀ Total (tpy) =	0.63	0.021
• •	10 (0.0	7.1		10 (-1-3/	0.00	0.021

Table A4 Construction Offsite On-Road Vehicle Emissions Loomis-SPMUD Sewer Diversion Pipeline Project

Construction Offsite On-Road Vehicle Emissions in 2018

Materials DeliveryTruck Emissions in 2018

							Material	s Delivery ⁻	Truck Pea	ak Daily Emis	ssions in 20	018									
Maximum Number of Deliveries per	Trip Haul Distance	Vehicle-Miles Traveled per				Emissio	n Factors	(lbs/VMT)							Da	ily Emiss	ions (lbs/	day)			
Day	(miles)	Day	NOx	СО	VOC	SOx	PM ₁₀	PM _{2.5}	CO ₂	CH ₄ ^(2,3)	N ₂ O ^(2,4)	NOx	co	VOC	SOx	PM ₁₀	PM _{2.5}	CO ₂	CH₄	N ₂ O	CO ₂ e ^(5,6)
1	46	46	0.0121	0.00077	0.00015	0.000031	0.00033	0.00019	3.29	0.0000088	0.000027	0.67	0.052	0.010	0.0016	0.015	0.0089	167	0.00060	0.0014	167
Paved-Road Fugitiv	e Dust						0.020	0.0049			·					0.92	0.23				

							Materi	als Deliver	y Truck A	nnual Emiss	ions in 20	18									
Number of Deliveries per	Trip Haul Distance	Annual Vehicle-Miles				Emissio	n Factors	(lbs/VMT)							An	nual Emis	ssions (to	ns/yr)			
Year	(miles)	Traveled	NOx	со	voc	SOx	PM ₁₀	PM _{2.5}	CO ₂	CH₄	N ₂ O	NOx	СО	voc	SOx	PM ₁₀	PM _{2.5}	CO ₂	CH₄	N ₂ O	CO ₂ e ^(5,6)
18	46	828	0.0121	0.00077	0.00015	0.000031	0.00033	0.00019	3.29	0.0000088	0.000027	0.0061	0.00047	0.00010	0.000014	0.00014	0.000080	1.50	0.0000054	0.000012	1.50
Paved-Road Fugitiv	18 46 8 I-Road Fugitive Dust						0.019	0.0046								0.0078	0.0019				

2) Diesel fuel CO₂ emission factor (kg CO₂/MMBtu) = (EPA. 2013 Revisions to the Greenhouse Gas Reporting Rule and Final Confidentiality Determinations for New or Substantitally Revised Data Elements; Final Rule, Federal Register, Volume 73.96 (EPA. 2013 Revisions to the Greenhouse Gas Reporting Rule and Final Confidentiality Determinations for New or Substantitally Revised Data Elements; Final Rule, Federal Register, Volume 73.96

3) Diesel fuel CH₄ emission factor (kg CH₄/MMBtu) = (EPA. 2013 Revisions to the Greenhouse Gas Reporting Rule and Final Confidentiality Determinations for New or Substantitally Revised Data Elements; Final Rule, Federal Register, Volume 0.0030 78, Number 230, Table C-2 to Subpart C, p. 71952, November 29, 2013.)

4) Diesel fuel N_2O emission factor (kg $N_2O/MMBtu$) = 0.0006 Ibid

5) CH₄ Global Warming Potential (-) = (EPA. 2013 Revisions to the Greenhouse Gas Reporting Rule and Final Confidentiality Determinations for New or Substantitally Revised Data Elements; Final Rule, Federal Register, Volume 78, Number 25 (EPA. 2013 Revisions to the Greenhouse Gas Reporting Rule and Final Confidentiality Determinations for New or Substantitally Revised Data Elements; Final Rule, Federal Register, Volume 78, Number 230, Table 2, p. 71909, November 29, 2013.)

6) N₂O Global Warming Potential (-) = 298 Ibid

Table A4 Construction Offsite On-Road Vehicle Emissions Loomis-SPMUD Sewer Diversion Pipeline Project

Construction Worker Vehicle Emissions in 2018

								W	orker Trave	l Daily Emi	issions in 20	018 (Maxin	num)											
	Average	Total	Average		Worker																			
	Number of	Number of	Worker	Carpool	Vehicle																			
Maximum	Worker	Worker	Round Trip	Factor (No.	Distance					_														
Number of	Round Trips	Round Trips	Distance	People per	Traveled per				Emissi	on Factors	(lbs/vmt)							Dail	y Emissio	ns (lbs/day)			
Workers per Day	Per Day	per Day	(Miles)	Vehicle)	Day (miles)	NOx	CO	VOC	SOx	PM ₁₀	PM _{2.5}	CO ₂	CH ₄ ^(2,3)	$N_2O^{(2,4)}$	NOx	СО	voc	SOx	PM ₁₀	PM _{2.5}	CO ₂	CH₄	N ₂ O	CO ₂ e ^(5,6)
15	1	15	46	1	690	0.00036	0.0028	0.000094	0.0000078	0.00010	0.000044	0.78	0.000025	0.0000063	0.26	2.0	0.078	0.0054	0.0718	0.0305	539.9	0.0179	0.00438	542
Paved-Road Fugit	tive Dust									0.0069	0.0017								4.75	1.17				

									Wo	orker Travel	Annual En	nissions in 2	2018												
Annual Average (Weighted) Number of	Average Number of Worker Round Trips	Total Number of Worker	Average Worker Round Trip Distance	Carpool Factor (No. People per	Number of Construction	Vehicle Miles				Emissi	on Factors	s (lbs/vmt)							Ann	nual Emiss	ions (tons/	yr)			
Workers Per Day	•	per Day	(Miles)	Vehicle)		Per Year		СО	VOC	SOx	PM ₁₀	PM _{2.5}	CO ₂	CH₄	N ₂ O	NOx	СО	VOC	SOx	PM ₁₀	PM _{2.5}	CO ₂	CH₄	N ₂ O	CO ₂ e ^(5,6)
15.0	1	15.0	46	1	87	59,800	0.00036	0.0028	0.000094	0.0000078	0.00010	0.000044	0.78	0.000025	0.0000063	0.011	0.087	0.010	0.00023	0.0031	0.0013	23.4	0.00083	0.00019	23.5
Paved-Road Fugitive	/e Dust										0.0065	0.0016								0.19	0.047				

Table A5
Assumptions for Construction Emission Analysis
Loomis-SPMUD Sewer Diversion Pipeline Project

Assumption	Units	Value	Reference
Number of construction days per week	days/week	5	Project Description, page 14
Construction period, CY 2017	days/year	238	48 weeks for Phases 1 and 2
Construction period, CY 2018	days/year	87	17 weeks for Phase 3
Construction schedule, daily	hrs/day	8	Estimated
Number of construction workers commuting to job site	number	15	Estimated
Number of daily round-trips by each construction worker	trips/day	1	Assumes no travel home for lunch
Construction worker average one-way commute distance	miles	23	Distance to center of Sacramento
Number of construction materials deliveries in CY 2017	number	48	Assumes weekly
Number of construction materials deliveries in CY 2018	number	17	Assumes weekly
Construction materials average one-way delivery distance	miles	23	Distance to center of Sacramento
Number of paving days, 2017	days/year	24	Assumed to be 10% construction days.
Number of paving days, 2018	days/year	9	Assumed to be 10% construction days.
Total project area disturbed	acres	6.7	Project Description, page 1, March 15
Area disturbed, 2017	acres	4.9	Assumed proportional to number of construction days
Area disturbed, 2018	acres	1.8	Assumed proportional to number of construction days
Onsite speed of water and dump trucks	mph	5	Estimated
Maximum water capacity of water trucks	gallons	4,000	Standard capacity

Note: Values are conservative maxima to assure no underestimation of construction emissions.

Table A6 Construction Equipment Speed Loomis-SPMUD Sewer Diversion Project

Construction Equipment Speeds

	Average
	Vehicle
	Speed ¹
Equipment	(mph)
PICKUP 3/4 TON 4X4 CREW CAB	5
TRUCK DUMP TANDEM AXLE 13-15 CY D	5
TRUCK WATER 3600-4000GAL F-R SPRAY BARS / MONITOR	
2AXLE D	5
EXCAVATOR	0.5
BACKHOE	0.5
COMPACTOR VIB SMOOTH 66" 7.7T 75HP D	1.5
WHEELED LOADER	2.0
PAVING MACHINE	0.5


¹⁾ Estimated

Appendix B

Biological Features and Preferred Alignment Map and Biological Resources Reports

Biological Features and Preferred Alignment Map 2014 Biological Resources Assessment 2014 Delineation of Waters of the United States 2014 Arborist Report

Portions of the Biological Resources Assessment (January 21, 2014), Arborist Report (January 21, 2014), and Delineation of Waters of the United States (March 27, 2014) are included in this appendix. The complete reports are available for review on the website (http://www.loomis.ca.gov/loomis_projects.html) and at the Town office: 3665 Taylor Road, Loomis, CA 95650.



Biological Resources Assessment

6201 Horseshoe Bar Road Placer County, California

Prepared for: Tulip Asset LLC

January 21, 2014



Table of Contents

1.0	Executive Summary	1
2.0	Introduction	2
3.0	Regulatory Framework	3
3.1	•	
3.2	· ·	
3.3		
3.4	• •	
3.5	California Native Plant Society	4
3.6	Jurisdictional Waters of the United States	5
_	3.6.1 Federal Jurisdiction	
	3.6.2 CDFW Jurisdiction	
3.7		
3.8		
3.9	Town of Loomis Tree Ordinance	10
4.0	Methods	11
5.0	Results	12
5.1	Site Location and Description	12
5.2	•	
5	5.2.1 Topography and Drainage	12
	5.2.2 Soils 12	
	Biological Communities	
_	5.3.1 Annual Grassland	
_	5.3.2 Oak Woodland	
_	5.3.3 Great Valley Mixed Riparian Forest	
5.4	-y	
	5.4.1 Listed and Special-Status Plants	
_	5.4.2 Listed and Special-Status Animals	
5.5	•	
	5.5.1 Potential Jurisdictional Waters of the U.S	
5	5.5.2 Protected Trees	
6.0	Discussion and Recommendations	31
6.1	Special-Status Plants	31
6.2	1	
6.3	· · · · · · · · · · · · · · · · · · ·	
6.4	*	
6.5		
6.6	•	
6.7	•	
6.8		
6.9		
6.1		
6.1		
	•	

7.0 References	36
List of Tables	
Table 1 — Listed and Special-Status Species Potentially Occurring on the Site	17
List of Figures	
Figure 1 — Site and Vicinity	38
Figure 2 — Soils	39
Figure 3 — CNDDB	
Figure 4 — Biological Constraints	
Figure 5 — Conceptual Development Plan	

List of Appendices Appendix A — 2007 Elderberry Shrub Data

1.0 EXECUTIVE SUMMARY

The purpose of this document is to document the results of a biological resource assessment on the project site located at 6201 Horseshoe Bar Road in the Town of Loomis, California. A biological assessment was previously prepared for this property in 2007 by Foothill Associates. The project site is located immediately south of Interstate 80 and is bisected by Horseshoe Bar Road. This report summarizes the general biological resources on the site, assesses the suitability of the site to support special-status species and sensitive habitat types, and provides recommendations for regulatory permitting or further analysis that may be required prior to development activities occurring on the site. Foothill Associates' biologists conducted biological resources site assessment surveys on July 10 and July 11, 2006, November 15, 2007, and on November 19 and 20, 2013.

The project site consists of ± 63 acres of land that currently contains primarily annual grassland, oak woodland, and mixed riparian forest. Land uses and vegetation communities surrounding the site include Interstate 80 to the north, single-family residential areas and annual grassland and oak woodland to the east, single-family residential areas and Brace Road to the south, and single-family residential and annual grassland to the west. Known or potential biological constraints on the site include the following:

- Potential habitat for special-status plant species (including big-scale balsamroot, Brandegee's clarkia, dubious pea, and Sanford's arrowhead);
- Potential habitat for valley elderberry longhorn beetle;
- Potential special-status fish habitat;
- Potential habitat for western pond turtle;
- Potential habitat for spadefoot;
- Potential nesting habitat and foraging habitat for raptors (including Cooper's hawk, osprey, white-tailed kite, and Swainson's hawk) and other species protected by the MBTA (including purple martin, song sparrow, and grasshopper sparrow);
- Potential western burrowing owl habitat;
- Potential special-status bat habitat;
- Sensitive habitats (wetlands including seasonal wetlands, mixed riparian forest, perennial drainage, and oak woodland); and
- Protected trees.

2.0 INTRODUCTION

This report summarizes the findings of a biological resources assessment completed for the ± 63 -acre 6201 Horseshoe Bar Road site, located within the Town of Loomis, California. This document addresses the on-site physical features as well as plant communities present and the common plant and wildlife species occurring, or potentially occurring on the site. Furthermore, the suitability of habitats to support special-status species and sensitive habitats are analyzed and recommendations are provided for any regulatory permitting or further analysis that may be required prior to development activities occurring on the site.

A wetland delineation was conducted on the site. A detailed analysis of wetlands and other waters of the U.S. is provided under separate cover in the wetland delineation report for the site. The acreages of wetland features and general characteristics of those features are summarized in this biological resources assessment.

A tree survey was conducted on the site documenting all trees protected by the Town of Loomis Tree Ordinance. The results of this survey are documented in an Arborist Report under separate cover.

3.0 REGULATORY FRAMEWORK

The following describes federal, State, and local environmental laws and policies that are relevant to the California Environmental Quality Act (CEQA) review process. The CEQA significance criteria are also included in this section.

3.1 Federal Endangered Species Act

The United States Congress passed the Federal Endangered Species Act (FESA) in 1973 to protect those species that are endangered or threatened with extinction. FESA is intended to operate in conjunction with the National Environmental Policy Act (NEPA) to help protect the ecosystems upon which endangered and threatened species depend.

FESA prohibits the "take" of endangered or threatened wildlife species. "Take" is defined to include harassing, harming, pursuing, hunting, shooting, wounding, killing, trapping, capturing, or collecting wildlife species or any attempt to engage in such conduct (FESA Section 3 [(3)(19)]). Harm is further defined to include significant habitat modification or degradation that results in death or injury to listed species by significantly impairing behavioral patterns (50 CFR §17.3). Harassment is defined as actions that create the likelihood of injury to listed species to such an extent as to significantly disrupt normal behavior patterns (50 CFR §17.3). Actions that result in take can result in civil or criminal penalties.

FESA and Clean Water Act (CWA) Section 404 guidelines prohibit the issuance of wetland permits for projects that jeopardize the continued existence of any endangered species or threatened species or result in the destruction or adverse modification of habitat of such species. The U.S. Army Corps of Engineers (Corps) must consult with the U.S. Fish and Wildlife Service (USFWS) and/or the National Marine Fisheries Service (NMFS) when threatened or endangered species under their jurisdiction may be affected by a proposed project. In the context of the proposed project, FESA would be initiated if development resulted in take of a threatened or endangered species or if issuance of a Section 404 permit or other federal agency action could result in take of an endangered species or adversely modify critical habitat of such a species.

3.2 Migratory Bird Treaty Act (MBTA)

Raptors (birds of prey), migratory birds, and other avian species are protected by a number of state and federal laws. The federal MBTA prohibits the killing, possessing, or trading of migratory birds except in accordance with regulations prescribed by the Secretary of Interior. Section 3503.5 of the California Fish and Game Code states that it is "unlawful to take, possess, or destroy any birds in the order Falconiformes or Strigiformes or to take, possess, or destroy the nest or eggs of any such bird except as otherwise provided by this code or any regulation adopted pursuant thereto."

3.3 California Endangered Species Act

The State of California enacted the California Endangered Species Act (CESA) in 1984. CESA is similar to FESA but pertains to state-listed endangered and threatened species. CESA requires state agencies to consult with the California Department of Fish and Wildlife (CDFW), formerly California Department of Fish and Game (CDFG) when preparing CEQA documents. The purpose is to ensure that the lead agency's actions do not jeopardize the continued existence of a listed species or result in the destruction, or adverse modification of habitat essential to the continued existence of those species if there are reasonable and prudent alternatives available (Fish and Game Code §2080). CESA directs agencies to consult with CDFW on projects or actions that could affect listed species, directs CDFW to determine whether jeopardy would occur, and allows CDFW to identify "reasonable and prudent alternatives" to the project consistent with conserving the species. CESA allows CDFW to authorize exceptions to the state's prohibition against take of a listed species if the "take" of a listed species is incidental to carrying out an otherwise lawful project that has been approved under CEQA (Fish & Game Code § 2081).

3.4 CDFW Species of Concern

In addition to formal listing under FESA and CESA, species receive additional consideration by CDFW and lead agencies during the CEQA process. Species that may be considered for review are included on a list of "Species of Special Concern," developed by CDFW. It tracks species in California whose numbers, reproductive success, or habitat may be threatened.

3.5 California Native Plant Society

The California Native Plant Society (CNPS) maintains a list of plant species native to California that have low population numbers, limited distribution, or is otherwise threatened with extinction. This information is published in the Inventory of Rare and Endangered Vascular Plants of California. Potential impacts to populations of CNPS-listed plants receive consideration under CEQA review. The following identifies the definitions of the CNPS listings:

- Rank 1A: Plants presumed Extinct in California
- Rank 1B: Plants Rare, Threatened, or Endangered in California and elsewhere
- Rank 2: Plants Rare, Threatened, or Endangered in California, but more numerous elsewhere
- Rank 3: Plants about which we need more information A Review List
- Rank 4: Plants of limited distribution A Watch List

3.6 Jurisdictional Waters of the United States

3.6.1 Federal Jurisdiction

The Corps regulates discharge of dredged or fill material into waters of the United States under Section 404 of the CWA. "Discharges of fill material" are defined as the addition of fill material into waters of the U.S., including, but not limited to the following: placement of fill that is necessary for the construction of any structure, or impoundment requiring rock, sand, dirt, or other material for its construction; site-development fills for recreational, industrial, commercial, residential, and other uses; causeways or road fills; fill for intake and outfall pipes and subaqueous utility lines [33 C.F.R. §328.2(f)]. In addition, Section 401 of the CWA (33 U.S.C. 1341) requires any applicant for a federal license or permit to conduct any activity that may result in a discharge of a pollutant into waters of the United States to obtain a certification that the discharge will comply with the applicable effluent limitations and water quality standards.

Waters of the U.S. include a range of wet environments such as lakes, rivers, streams (including intermittent streams), mudflats, sandflats, wetlands, sloughs, and wet meadows. Boundaries between jurisdictional waters and uplands are determined in a variety of ways depending on which type of waters is present. Methods for delineating wetlands and non-tidal waters are described below.

- Wetlands are defined as "those areas that are inundated or saturated by surface or groundwater at a frequency and duration sufficient to support and under normal circumstances do support, a prevalence of vegetation typically adapted for life in saturated soil conditions" [33 C.F.R. §328.3(b)]. Presently, to be a wetland, a site must exhibit three wetland criteria: hydrophytic vegetation, hydric soils, and wetland hydrology existing under the "normal circumstances" for the site.
- The lateral extent of non-tidal waters is determined by delineating the ordinary high water mark (OHWM) [33 C.F.R. §328.4(c)(1)]. The OHWM is defined by the Corps as "that line on shore established by the fluctuations of water and indicated by physical character of the soil, destruction of terrestrial vegetation, the presence of litter and debris, or other appropriate means that consider the characteristics of the surrounding areas" [33 C.F.R. §328.3(e)].

3.6.2 CDFW Jurisdiction

CDFW is a trustee agency that has jurisdiction under Section 1600 *et seq.* of the California Fish and Game Code. Under Section 1602, a private party must notify CDFW if a proposed project will "substantially divert or obstruct the natural flow or substantially change the bed, channel, or bank of any river, stream, or lake designated by the department, or use any material from the streambeds...except when the department has been notified pursuant to Section 1601." If an existing fish or wildlife resource may be substantially adversely affected by the activity, CDFW may propose reasonable measures that will allow protection of those resources. If these measures are agreeable to the parties involved, they may enter into an agreement with CDFW identifying the approved activities and associated mitigation measures.

3.7 CEQA Significance Criteria

Section 15064.7 of the CEQA Guidelines encourages local agencies to develop and publish the thresholds that the agency uses in determining the significance of environmental effects caused by projects under its review. However, agencies may also rely upon the guidance provided by the expanded Initial Study checklist contained in Appendix G of the CEQA Guidelines. Appendix G provides examples of impacts that would normally be considered significant. Based on these examples, impacts to biological resources would normally be considered significant if the project would result in any of the following:

- Have a substantial adverse effect, either directly or through habitat modifications, on any species identified as a candidate, sensitive, or special-status species in local or regional plans, policies, or regulations, or by CDFW or USFWS;
- Have a substantial adverse effect on any riparian habitat or other sensitive natural community identified in local or regional plans, policies, regulations or by CDFW or USFWS;
- Have a substantial adverse effect on federally protected wetlands as defined by Section 404 of the CWA (including, but not limited to, marsh, vernal pool, coastal, etc.) through direct removal, filling, hydrological interruption, or other means;
- Interfere substantially with the movement of any native resident or migratory fish or wildlife species, or with established native resident or migratory wildlife corridors, or impede the use of native wildlife nursery sites;
- Conflict with any local policies or ordinances protecting biological resources, such as a tree preservation policy or ordinance; and
- Conflict with the provisions of an adopted Habitat Conservation Plan (HCP), Natural Community Conservation Plan (NCCP), or other approved local, regional or state habitat conservation plan.

An evaluation of whether or not an impact on biological resources would be substantial must consider both the resource itself and how that resource fits into a regional or local context. Substantial impacts would be those that would diminish, or result in the loss of, an important biological resource, or those that would obviously conflict with local, state, or federal resource conservation plans, goals, or regulations. Impacts are sometimes locally important but not significant according to CEQA. This is necessary because although the impacts would result in an adverse alteration of existing conditions, they would not substantially diminish, or result in the permanent loss of, an important resource on a population-wide or region-wide basis.

3.8 Town of Loomis General Plan

The Town of Loomis provides guidance on development and design through its General Plan. The following excerpts summarize applicable policies from Section VII - Conservation of Resources:

- 2. Biotic resources evaluation. Prior to approval of discretionary development permits involving parcels near significant ecological resource areas, the Town shall require, as part of the environmental review process, a biotic resources evaluation by a qualified biologist. The biologist shall follow accepted protocols for surveys (if needed) and subsequent procedures that may be necessary to complete the evaluation. "Significant Ecological Areas" shall include, but not be limited to:
 - *Wetland areas*:
 - Stream environment zones;
 - Suitable habitat for rare, threatened or endangered species, and species of concern;
 - Large areas of non-fragmented habitat, including oak woodlands and riparian habitat;
 - Potential wildlife movement corridors; and
 - Important spawning areas for anadramous fish.
- 5. Native tree protection. Individual heritage trees and significant stands of heritage trees shall be preserved. Healthy heritage trees shall be removed or significantly trimmed only when necessary because of safety concerns, conflicts with utility lines and other infrastructure, the need for thinning to maintain a healthy stand of trees, or where there is no feasible alternative to removal. Proposed development shall be designed, constructed, and maintained to preserve individual heritage trees and significant stands of heritage trees, and provide for the protection of root zones and the continuing health of the trees. When trees are removed, they shall be replaced in sufficient numbers to maintain the volume of the Town's overall tree canopy over a 20-year period. Tree removal within stream corridors is also subject to the above policy on stream corridor protection.
- 6. Stream corridor protection. The streams of Loomis are among the most significant and valuable of the Town's natural resources. Development adjacent to streams shall be designed, constructed, and maintained to avoid adverse impacts on riparian vegetation, stream bank stability, and stream water quality to the maximum extent feasible. These policies shall apply to all watercourses shown as blue lines on the most recent United States Geological Survey (USGS) 7.5-minute topographic quadrangle maps applicable to the Town. See also the policies for wetland protection below.
 - a. Proposed structures and grading shall be set back the greater of: 100 feet from the outermost extent of riparian vegetation as defined in the Zoning Ordinance, or outside of the 100-year flood plain. Lesser setbacks may be approved where site-specific studies of biology and hydrology, prepared by qualified professionals

- approved by the Town, demonstrate that a lesser setback will provide equal protection for stream resources. Development shall be set back from ephemeral or intermittent streams a minimum of 50 feet, to the extent of riparian vegetation, or to the 100-year floodplain, whichever is greatest.
- b. Land uses and development within the setback areas required by this policy shall be limited to: the grazing of livestock at half or less of the animal densities allowed by the Zoning Ordinance; open wire fencing to confine livestock; bridges; public utilities and infrastructure; and other uses allowed by the applicable zoning district as permitted or conditional uses, with conditional use permit approval.
- c. The following activities are prohibited within stream corridor setbacks: filling or dumping; the disposal of agricultural wastes; channelization or dams; the use of pesticides that may be carried into stream waters; grading, or the removal of natural vegetation within the required setback area, except with grading permit approval. This is not intended to prevent the reasonable maintenance of natural vegetation to improve plant health and habitat value.
- d. The Town shall require that development projects proposing to encroach into a creek corridor or creek/wetland setback to do one or more of the following, in descending order of desirability:
 - a. Avoid the disturbance of riparian vegetation;
 - b. Replace riparian vegetation (on-site, in-kind);
 - c. Restore another section of creek (in-kind); and/or
 - d. Pay a mitigation fee for restoration elsewhere (e.g., wetland mitigation banking program).
- e. The Town shall require that newly-created parcels include adequate space outside of wetland and riparian setback areas to ensure that property owners will not place improvements within areas that require protection.
- f. Proposed development shall include surface water drainage facilities that are designed, constructed, and maintained to ensure that the increased runoff caused by development does not contribute to the erosion of stream banks, or introduce pollutants into watercourses.

- g. The Town shall encourage the use of natural stormwater drainage systems to preserve and enhance existing natural features. The Town shall promote flood control efforts that maintain natural conditions within riparian areas.
- h. Where creek or wetland protection is required or proposed, the Town shall require public and private development to:
 - Preserve creek corridors and setbacks through easements or dedications. Parcel lines or easements shall be located to optimize resource protection;
 - Designate easement or dedication areas as open space;
 - Protect creek corridors and their habitat value by:
 1) providing adequate setbacks; 2) maintaining creek corridors in their natural state; 3) employing restoration techniques, where necessary and appropriate; 4) using riparian vegetation within creek corridors; 5) prohibit the planting of invasive, non-native plants within creek setbacks; and 6) avoiding tree removal within creek corridors.
 - Use techniques that ensure development will not cause or worsen natural hazards near creeks, and will include erosion and sediment control practices such as: 1) turbidity screens (to minimize erosion and siltation); and 2) temporary vegetation sufficient to stabilize disturbed areas.

Wetlands. The following policies apply to properties with wetland areas. Additional applicable policies may be found under "stream corridor protection," above.

- a. The environmental review of development on sites with wetlands shall include a wetlands delineation, and the formulation of appropriate mitigation measures. The Town shall support the "no net loss" policy for wetland areas regulated by the U.S. Army Corps of Engineers, the U.S. Fish and Wildlife Service, and the California Department of Fish and Game. Coordination with these agencies at all levels of project review shall continue to ensure that appropriate mitigation measures and the concerns of these agencies are adequately addressed.
- b. The Town shall require new development to mitigate wetland loss in both regulated and non-regulated wetlands to achieve "no net loss" through any combination of the following, in descending order of desirability:
 - (1) Avoidance of riparian habitat;

- (2) Where avoidance is not feasible, minimization of impacts on the resource;
- (3) Compensation, including use of a mitigation banking program that provides the opportunity to mitigate impacts to rare, threatened, and endangered species and/or the habitat which supports these species in wetland and riparian areas, that are encouraged to be located within the Town; or
- (4) Replacement of a degraded or destroyed wetland at a ratio of from 1:1 to 4:1, based on the biotic value of the wetland, as determined by the required environmental analysis. The review authority may reduce the replacement ratio as an incentive, where replacement wetlands are proposed to be located within or in close proximity to the Town.

The Town shall cooperate with regulating agencies to ensure that concerns are adequately addressed.

- c. The Town will require project-by-project review of sites where vernal pools exist, to assess threatened and endangered pool plant species and identify appropriate mitigation measures.
- d. The Town will require the preservation of native riparian and wetland areas as open space to the maximum extent feasible, using fee title or conservation easement acquisition, land conservancy participation, and/or other measures as appropriate.

3.9 Town of Loomis Tree Ordinance

The Town of Loomis ordinance for the Preservation of Heritage Trees regulates the removal of protected trees. Heritage trees include all native oak trees with a trunk diameter of at least six inches and other tree species with a trunk diameter of 19 inches at 54 inches above the ground. Eucalyptus (*Eucalyptus* sp.), alder (*Alnus rhombifolia*), cottonwood (*Populus fremontii*), pine (*Pinus* spp.), fruit trees, and willow (*Salix* spp.) trees of any size are exempted from the ordinance. A tree permit is required prior to removal of a protected tree or encroachment with ground disturbing activity into more than 20% of its root zone. Replacement planting may be required as a condition of the permit. Generally, trees removed should be replaced with trees of the same species. The number of replacement plantings depends on the trunk diameter of the tree removed. Although on-site replacement planting is preferred, payment of an in-lieu fee is an option if on-site replanting is not feasible.

4.0 METHODS

Available information pertaining to the natural resources of the region was reviewed. All references reviewed for this assessment are listed in the **References** section of this document. Site-specific information was reviewed including the following:

- California Department of Fish and Wildlife (CDFW). 2013. *California Natural Diversity Data Base* (CNDDB). Sacramento, CA;
- Natural Resource Conservation Service (NRCS). 1980. Soil Survey of Placer County, Western Part, California. U.S. Department of Agriculture;
- U.S. Fish and Wildlife Service. 2013. Federal Endangered and Threatened Species that may be affected by Projects in the Rocklin 7.5 minute series quadrangle and Placer County. Sacramento, CA; and
- U.S. Geological Survey (USGS). 1967 (Photorevised 1981). "Rocklin, California. 7.5-minute series topographic quadrangle." United States Department of Interior.

Foothill Associates' biologists conducted field surveys on the site on July 10 and July 11, 2006 and on November 19 and 20, 2013. The site was systematically surveyed on foot and using existing roads within the site to ensure total search coverage, with special attention given to identifying those portions of the site with the potential for supporting special-status species and sensitive habitats. During the field surveys, biologists recorded plant and animal species observed and characterized biological communities occurring on the site.

As part of this assessment, Foothill Associates' biologists prepared a wetland delineation utilizing the Corps 1987 three-parameter methodology to delineate potentially jurisdictional waters of the U.S. This methodology requires the collection of hydric soils, hydrophytic vegetation, and hydrologic data at several locations to establish the jurisdictional edge of waters of the U.S. The complete results of this delineation are provided under separate cover. The acreages and types of wetland features delineated on the site are summarized in this biological resource assessment.

Foothill Associates' ISA-Certified Arborists also surveyed all protected trees on the project site. The species, trunk diameter, dripline radius, health, and structure of all protected trees were recorded and each tree was tagged with a pre-printed aluminum tag. The complete results of this survey are provided under separate cover. The results of the survey are summarized in this report.

5.1 Site Location and Description

The project site consists of ± 63 acres of land that is a mixture of annual grassland, oak woodland, and mixed riparian forest. Within these communities are various wetland features. Land uses and vegetation communities surrounding the site include Interstate 80 to the north, single-family residential areas and annual grassland and oak woodland to the east, single-family residential areas and Brace Road to the south, and single-family residential and annual grassland to the west. The site is located within Township 11 North, Range 7 East, Section 10 of the USGS 7.5-minute series *Rocklin*, *California* quadrangle (**Figure 1**).

5.2 Physical Features

5.2.1 Topography and Drainage

Topography on the site varies from level to slightly sloped on the margins of Secret Ravine in the southern and eastern portions of the site. Elevations on the site range from approximately 340 to 375 feet above mean sea level (MSL). Surface runoff tends to flow into Secret Ravine which forms the southern and eastern boundary of the site. Seasonal wetlands also capture some surface flow on the site.

5.2.2 Soils

The Natural Resources Conservation Service (NRCS) has mapped three soil units on the site (**Figure 2**). The soil units that occur on the site include the following: **Andregg coarse sandy loam, 2 to 9 percent slopes**; **Xerorthents, cut and fill**; and **Xerorthents, Placer Areas**. General characteristics associated with these soils types are described below.

- Andregg coarse sandy loam, 2 to 9 percent slopes: This soil type is found on low hills in the Loomis Basin between 200 and 1,000 feet above MSL. The soil is moderately deep and well-drained. Natural vegetation includes annual grasses, herbaceous species, blue and live oak, and scattered pines. Permeability in this soil is moderately rapid and surface runoff is medium. The hydric soils list for Placer County identifies one unnamed hydric inclusion located within drainageways of this soil type.
- **Xerorthents, cut and fill**: This soil unit consists of mixed soil material that no longer contains discernable horizons. Cut and fill areas are typically well-drained and surface runoff is very rapid. Permeability and water capacity are variable. These areas are typically used for highways and urban development. The hydric soils list for Placer County does not identify hydric components or inclusions occurring within this soil type.

Xerorthents, Placer Areas: This soil unit consists of stony, cobbly, and gravelly
materials adjacent to streams that have been placer mined. Natural vegetation
typically includes annual grasses, oaks, willows, alders, and cottonwoods.
Permeability, runoff, and drainage are variable. The hydric soils list for Placer
County identifies one unnamed hydric inclusion located within drainageways of
this soil type.

5.3 Biological Communities

Three major biological communities occur on the 6201 Horseshoe Bar Road site including annual grassland, oak woodland, and mixed riparian forest. Within these communities are various wetland communities. These communities provide habitat to a number of common species of wildlife and may provide suitable habitat for special-status species. Each of the biological communities are described below including associated common plant and wildlife species observed, or that are expected to occur within these communities.

5.3.1 Annual Grassland

Annual grassland is characterized primarily by an assemblage of non-native grasses and forbs. This vegetation community is found in the western half of the property adjacent to Interstate 80. Much of the vegetation in this community is common to the Central Valley. Dominant grass species within this community consist of soft chess (*Bromus hordeaceous*), ripgut brome (*Bromus diandrus*), wild oat (*Avena fatua*), Italian rye grass (*Festuca perennis*), medusahead (*Elymus caput-medusae*), and little quaking grass (*Briza minor*). Other herbaceous vegetation present were California poppy (*Eschscholzia californica*), clustered dock (*Rumex conglomerates*), rose clover (*Trifolium hirtum*), tarweed (*Centromadia pungens*), star thistle (*Centaurea solstitialis*), Italian thistle (*Carduus pycnocephalus*), milkvetch (*Astragalus* spp.), bindweed (*Convolvulus arvensis*), elegant broadiaea (*Brodiaea elegans*), and wild mustard (*Hirschfeldia incana*).

Annual grassland habitat supports breeding, foraging, and shelter habitat for several species of wildlife. Species observed in this habitat during the biological assessment included the following: golden-crowned sparrow (*Zonotrichia atricapilla*), western meadowlark (*Sturnella neglecta*), coyote (*Canis latrans*), and black-tailed jackrabbit (*Lepus californicus*).

5.3.2 Oak Woodland

This community covers primarily the southern portion of the site adjacent to Secret Ravine. The overstory of this community is dominated by interior live oaks (*Quercus wislizeni*) with scattered valley oaks (*Quercus lobata*), blue oaks (*Quercus douglasii*), and foothill pines (*Pinus sabiniana*). The understory contains scattered toyon (*Adenostoma fasiculata*), California buckeye (*Aesculus californica*), coyotebrush (*Baccharis pilularis*), California blackberry (*Rubus ursinus*), whitethorn ceanothus (*Ceanothus cordulatus*), and poison oak (*Toxicodendron diversilobum*). Several blue elderberry shrubs (*Sambucus mexicana*) were found within the oak woodland as well.

Naturalized fruit trees within the oak woodland habitat included apple (*Malus* spp.), pear (*Pyrus* spp.) and common fig (*Ficus carica*).

Oak woodland habitats support a variety of wildlife species. Species observed in this habitat during the biological assessment include the following: red-tailed hawk (*Buteo jamaicensis*), oak titmouse (*Baeolophus inornatus*), bushtit (*Psaltriparus minimus*), western scrub-jay (*Aphelocoma californica*), mourning dove (*Zenaida macroura*), Anna's hummingbird (*Calypte anna*), lesser goldfinch (*Carduelis psaltria*), northern mockingbird (*Mimus polyglottos*), acorn woodpecker (*Melanerpes formicivorus*), Nuttall's woodpecker (*Picoides nuttallii*), turkey vulture (*Cathartes aura*), and mule deer (*Odocoileus hemionus*).

5.3.3 Great Valley Mixed Riparian Forest

This community is associated primarily with the margins of Secret Ravine on the southern and eastern portions of the site. The overstory of this community contains willows (*Salix* sp.), Fremont's cottonwood (*Populus fremontii*), and white alders (*Alnus rhombifolia*). The shrub layer contains Himalayan blackberry (*Rubus armeniacus*) and poison oak.

This vegetation community supports a high diversity of wildlife species. This community is also an important stopover for migrating bird species during the spring and fall months in the Central Valley. Species observed within this habitat type during the biological assessment include the following: spotted towhee (*Pipilo maculatus*), song sparrow (*Melospiza melodia*), green heron (*Butorides virescens*), oak titmouse, and coyote.

5.3.4 Wetlands and Other Waters of the U.S.

Riverine Seasonal Wetland

Approximately **0.53** acre of riverine seasonal wetlands has been delineated within the site. Riverine seasonal wetlands are defined by a hydrologic regime dominated by a unidirectional flow of water. Riverine seasonal wetlands typically occur in topographic folds or swales and represent natural drainages that convey sufficient water to support wetland vegetation. Riverine seasonal wetlands typically convey water during and shortly after storm events. Riverine seasonal wetlands have a moderately defined bed and bank and often exhibit sufficient gradient to convey water off of the site. As in depressional seasonal wetlands, plant species found within riverine seasonal wetlands are typically adapted to a hydrologic regime dominated by saturation rather than inundation.

Depressional Seasonal Wetlands

A total of **0.15** acre of depressional seasonal wetlands have been delineated within the site. Depressional seasonal wetlands are defined by a hydrologic regime that is dominated by saturation, rather than inundation. Depressional seasonal wetlands were identified on the site as inundated depressions within the topography capable of supporting hydrophytic plant species and hydric soils. At the time of the survey, the

depressional seasonal wetlands were inundated and supported plant species that are adapted to withstand periods of saturation or saturated soils conditions.

Perennial Drainage

A total of **0.44** acre of perennial drainage (Secret Ravine) has been delineated within the site. Flows in these systems persist throughout the year. Perennial drainages are features that do not meet the three-parameter wetland criteria for vegetation, hydrology and soils, but do convey water and exhibit an "ordinary high-water mark." Perennial drainages generally convey unidirectional water flows throughout the entire year. Perennial drainages typically consist of a channel, bed, and bank and are devoid of vegetation due to the scouring effect of flowing water. Perennial drainages are often bordered by wetland vegetation communities of various composition and cover depending on flow rates, duration flows, and soil types.

Pond

A portion of a pond (**0.01** acre) was delineated along the northeastern border. The pond on the site is charged by the perennial drainage that traverses the central portion of the northern half of the site and flow east towards the west side of the pond. Ponds are often a result of the placement of a dam within jurisdictional waters, as is the suspected origin of the feature onsite. Since the supply of water is from a perennial drainage that is likely jurisdictional, the close proximity of the pond to Secret Ravine, and likelihood that the pond flows into Secret Ravine; this feature is expected to be subject to Corps jurisdiction.

5.4 Special-Status Species

Special-status species are plant and animal species that have been afforded special recognition by federal, State, or local resource agencies or organizations. Special-status species are defined as:

- Listed or proposed for listing under CESA and/or FESA;
- Protected under other regulations (e.g. Migratory Bird Treaty Act);
- Listed by CDFW as a Species of Special Concern;
- Listed by CNPS as being rare (a ranking of 1A, 1B, or 2); or
- Any other species that would receive consideration according to the CEQA Guidelines.

Special-status species considered for this analysis are based on queries of the CNDDB for the Rocklin quadrangle and the surrounding 8 quadrangles, the USFWS Online Species List for the Rocklin quadrangle and the surrounding 8 quadrangles and Placer County, and the CNPS Inventory of Rare and Endangered Plants list for the Rocklin quadrangle and the surrounding 8 quadrangles (online version). **Table 1** includes the common name and scientific name for each species, regulatory status (federal, state, local, CNPS), habitat descriptions, and potential for occurrence on the project site. **Figure 3** depicts the locations of special-status species recorded in the CNDDB within five miles of the site.

The following set of criteria has been used to determine each species' potential for occurrence on the site:

- **Present**: Species is known to occur on the site, based on CNDDB records, and/or was observed on the site during the field survey(s).
- **High**: Species is known to occur on or near the site (based on CNDDB records within five miles, and/or based on professional expertise specific to the site or species) and there is suitable habitat on the site.
- Low: Species is known to occur in the vicinity of the site, and there is marginal habitat on the site.-OR-Species is not known to occur in the vicinity of the site; however there is suitable habitat on the site.
- **None**: There is no suitable habitat for the species on the site.-**OR**-Species was surveyed for during the appropriate season with negative results.

Only those species that are known to be present or that have a high or low potential for occurrence will be discussed further following **Table 1**.

16

 ${\bf Table~1-Listed~and~Special\hbox{-}Status~Species~Potentially~Occurring~on~the~Site}$

Special-Status Species	Regulatory Status (Federal; State; Local; CNPS)	Habitat Requirements	Identification Period	Potential for Occurrence
Plants				
Adobe navarretia Navarretia nigelliformis ssp. nigelliformis	;;4.2	Found in clay, sometimes serpentine mesic soil, valley and foothill grassland habitats.	April – June	None; there is no suitable habitat on the site for this species.
Ahart's dwarf rush Juncus leiospermus var. ahartii	;;1B.1	Found on margins of vernal pools.	March – May	None; there is no suitable habitat on the site for this species.
Big-scale balsamroot Balsamorhiza macrolepis var. macrolepis	;;1B.2	Grasslands and rocky hillsides, as well as on serpentine soils, up to 2,000 feet elevation.	March – June	Low; there is suitable habitat for this species on site, but the one known occurrence within 5 miles of the site is from 1957.
Bisbee Peak rush-rose Helianthemum suffrutescens	;;3.2	Found in chaparral habitat between 440 and 660 meters.	April – June	None; there is no suitable habitat on the site for this species.
Boggs Lake hedge- hyssop Gratiola heterosepala	;CE;;1B.2	Shallow ponds and margins of vernal pools.	April – June	None; there is no suitable habitat on the site for this species.
Brandegee's clarkia Clarkia biloba ssp. brandegeae	;;4.2	Foothill woodlands and conifer habitats usually in dry areas.	May – July	Low.
Brewer's calandrinia Calandrina breweri	;;4.2	Chaparral, northern coastal scrub, coastal sage scrub.	March – June	None; there is no suitable habitat on the site for this species.
Butte County fritillary Fritillaria eastwoodiae	;;3.2	Found in openings in yellow pine forest, foothill woodland, chaparral on serpentine soil.	March – June	None; there is no suitable habitat on the site for this species.
Dubious pea Lathyrus sulphureus var. argillaceus	;;3	Found in foothill woodland, lodgepole forest, red fir forest, yellow pine forest.	April – May	Low.
Dwarf downingia Downingia pusilla	;;2B.2	Found on the edges of vernal pools in alkaline and non-alkaline soils.	March – May	None; there is no suitable habitat on the site for this species.
Jepson's onion Allium jepsonii	;;1B.2	Found in woodlands of broadleaved (especially oak) and coniferous trees between 980 and 2,000 feet.	May – June	None; site is out of elevation range for this species.

Special-Status Species	Regulatory Status (Federal; State; Local; CNPS)	Habitat Requirements	Identification Period	Potential for Occurrence
Jepson's woolly sunflower Eriophyllum jepsonii	;;4.3	Chaparral, foothill woodland, northern coastal scrub, coastal sage scrub in serpentine soil.	April – June	None; there is no suitable habitat on the site for this species.
Hispid bird's-beak Chloropyron molle ssp hispidum	;;1B.1	Found in moist alkaline meadows and playas and coastal salt marshes.	March – June	None; there is no suitable habitat on the site for this species.
Humboldt lily Lilium humboldtii ssp. humboldtii	;;4.2	Found in chaparral, yellow pine forest.	May – July	None; there is no suitable habitat on the site for this species.
Layne's ragwort Packera layneae	FT;;;1B.2	Dry pine woodlands, oak woodlands, or chaparral areas associated with serpentine soils.	April – June	None; there are no serpentine soils expected on the site.
Legenere Legenere limosa	;;1B.1	Vernal pools.	May – June	None; there is no suitable habitat on the site for this species.
Oval-leaved viburnum Viburnum ellipticum	;;2B.3	Found in yellow pine forest and chaparral.	May – June	None; there is no suitable habitat on the site for this species.
Pincushion navarretia Navarretia myersii ssp. Myersii	;;1B.1	Found on the margins of vernal pools.	May – June	None; there is no suitable habitat on the site for this species.
Pine Hill ceanothus Ceanothus roderickii	FE;CR;;1B.2	Chaparral, foothill woodland on serpentine soil between 250 to 610 meters.	April – June	None; there is no suitable habitat on the site for this species.
Pine Hill flannelbush Fremontodendron decumbens	FE;CR;;1B.2	Found in chaparral habitats between 540 to 1190 meters.	April – July	None; there is no suitable habitat on the site for this species.
Red Bluff dwarf rush Juncus leiospermus var. leiospermus	;;1B.1	Occurs in vernally mesic chaparral, cismontane woodland, meadows, seeps, valley and foothill grassland, and vernal pools from 105 to 3,060 feet elevation.	March – May	None; the nearest recorded occurrence is considered erroneous and the site is far outside the known range of the species (CDFW 2013).
Red Hills soaproot Chlorogalum grandiflorum	;;1B.2	Open hillsides in chaparral communities. Usually associated with gabbro or serpentine soils.	May – June	None; there is no suitable habitat on the site for this species.
Sacramento Orcutt grass Orcuttia viscida	FE;;;1B.1	Found in deep vernal pools. Populations known from eastern Sacramento County.	April – July	None; there is no suitable habitat on the site for this species.

18

Special-Status Species	Regulatory Status (Federal; State; Local; CNPS)	Habitat Requirements	Identification Period	Potential for Occurrence
Sanborn's onion Allium sanbornii var. sanbornii	;;4.2	Found in chaparral, foothill woodland and yellow pine forest associated with serpentine soils.	May – September	None; there are no suitable serpentine soils on the site for this species.
Sanford's arrowhead Sagittaria sanfordii	;;1B.2	Shallow freshwater marshes and pond habitats.	May – October	Low; margins of Secret Ravine provide potential habitat. However, this species was previously surveyed for on the site with negative results.
Stebbins' morning glory Calystegia stebbinsii	FE; CE;;1B.1	Found in openings within chaparral, foothill and woodland habitats above 290 meters.	April – July	None; species occurs at higher elevations.
Stinkbells Fritillaria agrestis	;;4.2	Found on wetland- riparian serpentine soils on chaparral, valley grassland, foothill woodland habitats.	May – June	None; there is no suitable habitat on the site for this species.
Streambank spring beauty Claytonia parviflora ssp. grandiflora	;;4.2	Rocky mismontane woodlands, above 290 meters.	February – April	None; there is no suitable habitat on the site for this species.
Wildlife				
Invertebrates				,
California linderiella Linderiella occidentalis	;;	Vernal pools, swales, and ephemeral freshwater habitat.	Wet season	None; there is no suitable habitat on the site for this species.
Conservancy fairy shrimp Branchinecta lynchi	FE;;;-	Vernal pools, swales, and ephemeral freshwater habitat.	Wet season	None; there is no suitable habitat on the site for this species.
Valley elderberry longhorn beetle Desmocerus californicus dimorphus	FT;;	Blue elderberry shrubs usually associated with riparian areas.	Year-round	High; 27 elderberry shrubs have been located on the site, with some showing evidence of possible exit holes and there are 5 occurrences within 5 miles.
Vernal pool fairy shrimp Branchinecta lynchi	FT;;	Vernal pools, swales, and ephemeral freshwater habitat.	Wet season	None; there is no suitable habitat on the site for this species.
Vernal pool tadpole shrimp <i>Lepidurus packardi</i>	FE;;	Vernal pools, swales, and ephemeral freshwater habitat.	Wet season	None; there is no suitable habitat on the site for this species.

19

	Dagulatawy Status				
Special-Status Species	Regulatory Status (Federal; State; Local; CNPS)	Habitat Requirements	Identification Period	Potential for Occurrence	
Amphibians/Reptiles					
California red-legged frog Rana draytonii	FT; CSC;;	Requires a permanent water source and is typically found along quiet slow moving streams, ponds, or marsh communities with emergent vegetation.	Optimal detection is through aquatic sampling during the summer months.	None; there is potential dispersal habitat for this species on site, but there is no breeding habitat and there are no known occurrences within 5 miles of the site.	
California tiger salamander Ambystoma californiense	FT;CSC;;	Ponded water required for breeding. Adults spend summer in small mammal burrows.	November – February (Active following relatively warm rains).	None; the site is outside the known range for this species and there is only marginal breeding habitat on the site.	
Giant garter snake Thamnophis gigas	FT; CT;;	Agricultural wetlands and other wetlands such as irrigation and drainage canals, low gradient streams, marshes, ponds, sloughs, small lakes, and their associated uplands.	Optimal detection early spring through mid fall (about mid March – early November) during their active period.	None; there is no suitable habitat on the site for this species.	
Western pond turtle Clemmys marmorata	;CSC;;	Agricultural wetlands and other wetlands such as irrigation and drainage canals, low gradient streams, marshes, ponds, sloughs, small lakes, and their associated uplands.	Year-round	Low; Secret Ravine provides areas of suitable habitat.	
Western spadefoot Spea hammondii	;CSC;;	Open grasslands and woodlands. Requires vernal pools or seasonal wetlands for breeding.	Active following relatively warm rains in spring and fall.	Low; the seasonal wetlands and margins of Secret Ravine may provide suitable breeding habitat.	
Fish					
Central Valley fall/late fall-run Chinook salmon Oncorhynchus tshawytscha	; CSC;;	Sacramento and San Joaquin Rivers and their tributaries.	Year-round	High; Secret Ravine provides suitable habitat for this species.	
Central Valley winter- run Chinook salmon Oncorhynchus tshawytscha	FE;CE;;	Spawn in northern Sacramento River (Redding to Red Bluff) and its tributaries. Juveniles may journey up to 5 miles upstream in other tributaries.	Year-round	None; winter-run Chinook salmon are not known to spawn in Secret Ravine and the site is located over 25 miles from the Sacramento River.	

Special-Status Species	Regulatory Status (Federal; State; Local; CNPS)	Habitat Requirements	Identification Period	Potential for Occurrence
Central Valley spring- run Chinook salmon Oncorhynchus tshawytscha	FT; CT;;	Spawn in Mill, Deer, and Butte Creeks and in Yuba River and Feather River watersheds. Juveniles may journey up to 5 miles upstream in Sacramento River tributaries.	Year-round	None; spring-run Chinook salmon are not known to spawn in Secret Ravine and the site is located over 25 miles from the Sacramento River.
Central Valley steelhead Oncorhynchus mykiss	FT;;	Rivers and streams tributary to the Sacramento-San Joaquin Rivers and Delta ecosystems.	Year-round	High ; Secret Ravine provides suitable habitat for this species.
Delta smelt Hypomesus transpacificus	FT;CE;;	Shallow fresh or brackish water tributary to the Delta ecosystem; spawns in freshwater sloughs and channel edgewaters.	Year-round	None; this species does not typically occur upstream from the Delta area.
Birds				
Bald eagle Haliaeetus leucocephalus	FT;CE;;	Nesting restricted to the mountainous habitats near permanent water sources in the northernmost counties of California, the Central Coast Region, and on Santa Catalina Island. Winters throughout most of California at lakes, reservoirs, river systems, and coastal wetlands.	Wintering: September – January	None; there is no suitable habitat on the site for this species.
Bank swallow Riparia riparia	; CT;;	Nests in riverbanks and forages over riparian areas and adjacent uplands.	Spring and summer migration	None; there is no suitable nesting habitat on the site for this species.
California black rail Laterallus jamaicensis coturniculus	;CT;;	Nests in higher areas of coastal salt and brackish or freshwater marshes dominated by rushes, grasses, and sedges.	Year-round	None; there is no suitable habitat on the site for this species.
Cooper's hawk Accipiter cooperii	;CSC;; (Nesting)	Nests in riparian corridors. Forages in woodlands and riparian areas.	Year-round Nesting: March – August	High; riparian woodland along Secret Ravine provides suitable habitat for this species.
Grasshopper sparrow Ammodramus savannarum	;CSC,; (Nesting)	Found in short to middle- height, moderately open grasslands with scattered shrubs.	March - May	Low; although the site supports habitat, no sightings have occurred within 5 miles.

Special-Status Species	Regulatory Status (Federal; State; Local; CNPS)	Habitat Requirements	Identification Period	Potential for Occurrence
Osprey Pandion haliaetus	;-CSC;; (Nesting)	Large nests built in tree- tops within 15 miles of a good fish-producing body of water.	March - October	High; site supports nesting habitat and 1 occurrence within 5 miles.
Purple martin Progne subis	;CSC;; (Nesting)	Nests in old woodpecker cavities mostly, also in human-made structures. Nest often located in tall, isolated tree/snag.	May - July	High ; snag nesting habitat probable on site and 1 occurrence within 5 miles.
Song sparrow ("Modesto" population) Melospiza melodia	;CSC;;	Requires low, dense vegetation for protective cover, usually near water, in emergent vegetation, or in other moist areas.	Year-round	Low; although the site supports habitat, no sightings have occurred within 5 miles.
Swainson's hawk Buteo swainsoni	; CT;;	Nests in isolated trees or riparian woodlands adjacent to suitable foraging habitat (agricultural fields, grasslands, etc.)	Nesting: early March – early September	Low; although the site supports marginal habitat, no sightings have occurred within 5 miles.
Tricolored blackbird Agelaius tricolor	;CSC;; (Nesting colony)	Nests in dense blackberry, cattail, tules, willow, or wild rose within emergent wetlands throughout the Central Valley and foothills surrounding the valley.	Nesting: mid- April – late July	None; there is no suitable nesting habitat on the site for this species.
Western burrowing owl Athene cunicularia hypugaea	;CSC;;; (burrow sites and some wintering sites)	Nests in burrows in the ground, often in old ground squirrel burrows or badger, within open dry grassland and desert habitat.	Year-round	Low; although the site supports marginal habitat, no sightings have occurred within 5 miles.
White-tailed kite Elanus leucurus	;CFP;;	Nests in isolated trees or woodland areas with suitable open foraging habitat.	Year-round	High ; Site supports suitable habitat and there is 1 occurrence within 5 miles of the site.
Other Raptors (Hawks, Owls and Vultures)	MBTA and §3503.5 Department of Fish and Game Code	Nests in a variety of communities including cismontane woodland, mixed coniferous forest, chaparral, montane meadow, riparian, and urban communities.	February – September	Present.
Mammals				
Pallid bat Antrozous pallidus	;CSC;;	Common roost sites are rock crevices, old buildings, bridges, caves, mines, and hollow trees.	Year-round	Low; there is potential suitable nesting habitat but no known occurrences within 5 miles of the site.

Special-Status Species	Regulatory Status (Federal; State; Local; CNPS)	Habitat Requirements	Identification Period	Potential for Occurrence
Townsend's big-eared bat Corynorhinus townsendii	;CT;;	Requires caves, mines, tunnels, buildings or other human-made structures for roosting.	Year-round	None; there is no suitable roosting habitat for this species on the site.
	Federally Listed Species:	California State Listed Species:	CNPS* Rank Categories: 1A = plants presumed extinct in California 1B = plants rare, threatened, or endangered in California and elsewhere 2 = plants rare, threatened, or endangered in California, but common elsewhere 3 = plants about which we need more information 4 = plants of limited distribution Other Special-Status Listing:	
	FE = federal endangered	CE = California state endangered		
	FT = federal threatened	CT = California state threatened		
	FC = candidate	CR = California state rare		
	PT = proposed threatened	CSC = California Species of Special Concern		
	FPD = proposed for delisting	CFP = California Fully Protected		
	FD = delisted			
Source: Foothill Associates			SLC = species of local or conservation significance	

5.4.1 Listed and Special-Status Plants

Based on a records search of the CNDDB and the USFWS list, special-status plant species have the potential to occur on the site or in the vicinity of the site. Based on field observations and literature review specific to the special-status plants listed in **Table 1**, the potential for occurrence has been determined for each species. No special-status plant species are known to be present or considered to have a high potential to occur on the site due to the high level of soil manipulation on the site from historical placer mining. The species that are considered to have a low potential to occur on the site include the following: big-scale balsamroot (*Balsamorhiza macrolepis* var. *macrolepis*), Brandegee's clarkia (*Clarkia biloba* ssp. *brandegeae*), dubious pea (*Lathyrus sulphureus* var. *argillaceus*), and Sanford's arrowhead (*Sagittaria sanfordii*).

Species with a Low Potential for Occurrence

Big-Scale Balsamroot

Big-scale balsamroot is a perennial herb native to California that blooms from March through June. Big-scale balsamroot occurs in grassland, rocky hillsides, and serpentine soils. There is one CNDDB record within five miles of the site (**Figure 3**) (CDFW 2013), although it is from 1957. This species was not observed during the biological assessment, although the field survey was not performed during the identification period for this species. Although serpentine soils are not documented to occur within the site, the annual grassland is potential habitat for this species. Because there is one CNDDB record for this species within five miles of the site, and suitable habitat occurs, big-scale balsamroot has a low potential to occur onsite.

Brandegee's Clarkia

Brandegee's clarkia is typically found in foothill woodlands and low elevation conifer forests. This species blooms from May through June. There is one record of this species occurring within five miles of the project site (**Figure 3**) (CDFW 2013). This species was not observed onsite during the biological assessment. However, the biological assessment was performed outside of the typical blooming period for this species. The oak woodlands on the site contain potential habitat for this species. Therefore, this species has a low potential to occur on the site.

Dubious Pea

Dubious pea is a perennial herb that is native to California and blooms from April through May. Dubious pea is found in habitats including foothill woodland at elevations between 160 to 1130 meters. There are no records of this species occurring within five miles of the project site (CDFW 2013). The biological assessment was performed outside of the typical blooming period for this species. The oak woodlands on the site contain potential habitat for this species. Therefore, this species has a low potential to occur on the site.

Sanford's Arrowhead

Sanford's arrowhead is a perennial herb that blooms from May through October and occurs in shallow, fresh-water conditions. Secret Ravine may have areas considered marginal habitat for this species. There are no CNDDB records of this species within five miles of the site (CDFW 2013), and this species was not observed during the biological assessment. However, there are some suitable habitats associated with Secret Ravine. Therefore, the potential for this species to occur on the site is low.

5.4.2 Listed and Special-Status Animals

Based on a records search of the CNDDB and the USFWS list, special-status animal species have the potential to occur on the site or in the vicinity. Based on field observations and literature review specific to the special-status animals listed in **Table 1**, the potential for occurrence has been determined for each species.

Species that are known to be present or that are considered to have a high potential to occur on the site include the following: valley elderberry longhorn beetle (*Desmocerus californicus dimorphus*), Central Valley fall-run Chinook salmon (*Oncorhynchus tshawytscha*), Central Valley steelhead (*Oncorhynchus mykiss*), Cooper's hawk (*Accipiter cooperii*), osprey (*Pandion haliaetus*), purple martin (*Progne subis*), white-tailed kite (*Elanus leucurus*), and various other raptor species.

The species that are considered to have a low potential to occur on the site include the following: western pond turtle (*Clemmys marmorata*), western spadefoot (*Spea hammondii*), grasshopper sparrow (*Ammodramus savannarum*), song sparrow, "Modesto population" (*Melospiza melodia*), Swainson's hawk (*Buteo swainsonii*), western burrowing owl (*Athene cunicularia hypugaea*), and Pallid bat (*Antrozous pallidus*).

Species with a High Potential for Occurrence

Valley Elderberry Longhorn Beetle

The USFWS has determined the range of the beetle to include the watersheds of the American, San Joaquin, and Sacramento rivers and their tributaries up to approximately 3,000 feet above MSL (USFWS 1980). Typically, the beetles are found on elderberry shrubs within riparian plant communities. Some studies have found that multiple elderberry shrubs clumped together provide superior habitat for the beetle, while isolated elderberry shrubs are less likely to support beetle populations (Collinge et al. 2001). Typical plant species that co-occur with the elderberry shrubs include California sycamore (*Platanus racemosa*), willows, blackberry (*Rubus* spp.), and poison oak (USFWS 1984). Beetles require elderberry stems with a basal diameter of at least 1 inch in order for the larvae to utilize the stems (USFWS 1999). The valley elderberry longhorn beetle depends on elderberry shrubs for its entire lifecycle. Adults are typically active from March through May during the flowering period of the elderberry shrub. The female lays its eggs on the leaves and stems of the elderberry shrub. The larvae emerge within a few days and burrow into the elderberry stem. The larvae feed on the stem pith until they pupate. When the host shrub begins flowering, the pupa emerges from the stem as an adult (Barr 1991).

There are five records in the CNNDB for this species within five miles of the site, including one downstream within the Secret Ravine watershed (**Figure 3**) (CDFW 2013), and 27 elderberry shrubs with stems large enough to provide suitable VELB habitat were documented on the site in 2007 (**Figure 4**). Thirteen of the shrubs on the southern half of the site showed evidence of beetle exit holes (**Appendix A**), although no beetles have been observed on the site. Based on the presence of numerous elderberries with evidence of past beetle occupation and suitable elderberry habitat, the valley elderberry longhorn beetle has a high potential to occur on the site.

Special-Status Fish Species

Chinook salmon is the largest of the Pacific salmon and has a distribution historically ranging from the Ventura River in California to Point Hope, Alaska in North America, and in northeastern Asia from Hokkaido, Japan to the Anadyr River in Russia.

The "runs" of Chinook salmon in California are differentiated by the maturity of fish entering freshwater, time of spawning migrations, spawning areas, incubation times, incubation temperature requirements, and migration timing of juveniles. The differences in life histories effectively isolate the various runs (Moyle *et. al.* 1995). Only fall and late fall-run Chinook salmon are expected to be found on the project site because spring and winter run salmon spawn far north of the project area.

Fall/late-fall run Chinook salmon enter the Sacramento-San Joaquin River system from October through February, and spawning occurs in January, February, and March, although it may extend into April in some years (Molye *et. al.* 1995). While migrating and holding in the rivers and tributaries, fall/late fall-run Chinook salmon do not feed, relying instead on stored body fat reserves for maintenance. Eggs are laid in large depressions (redds) excavated in gravel beds and the embryos hatch following a 3 to 4

month incubation period. The fry remain in the gravel for another 2 to 3 weeks and once their yolk sac is absorbed, they emerge and begin feeding. Juveniles hold within the rivers and tributaries for nearly a year before migrating to the ocean the following December through March (Moyle *et. al* 1995).

Central Valley steelhead rely on streams, rivers, estuaries and marine habitat during their lifecycle. In freshwater and estuarine habitats, steelhead feed on small crustaceans, insects and small fishes. Eggs are laid in small and medium gravel and need good water flow (to supply oxygen) to survive. After emerging from the redds, steelhead remain in streams and rivers for 1 to 4 years before migrating through the estuaries to the ocean. Unlike salmon, steelhead migrate individually rather than in schools. Steelhead spend 1 to 5 years at sea before returning to natal streams or rivers. At least two specific storages of steelhead have developed: those that enter fresh water during fall, winter and early spring (the winter run); and those that enter in spring, summer and early fall (the summer run). Steelhead do not always die after spawning, but will migrate downstream through estuaries to the ocean.

Although there are no CNDDB records for these species within five miles of the site (CDFW 2013) and they were not observed during the field surveys, Secret Ravine is known salmonid habitat and is designated as Essential Fish Habitat for Chinook salmon. Therefore, the potential for this species to occur in the perennial drainage on the site is high.

Cooper's Hawk

Cooper's hawks are usually found in riparian woodlands near stream courses or other water. The breeding season for this species is typically between March and August (Zeiner *et al.* 1990). There are no records in the CNDDB for this species within five miles of the project site (CDFW 2013), although the CNDDB database tends to underrepresent the species. This species was not observed onsite during the biological assessment. However, the riparian community associated Secret Ravine on the southern portion of the site provides good potential nesting and foraging habitat for this species. Therefore, the potential for this species to occur on the site is high.

Osprey

Osprey are found within 15 miles of a good fish-producing body of water, such as rivers, lakes, reservoirs, bays, estuaries, and surf zones. Ospreys use large trees, snags and dead-topped trees in open forest habitats for cover and nesting. There is one record of osprey within five miles of the project site (**Figure 3**) (CDFW 2013). The riparian community associated with Secret Ravine may provide potential nesting habitat for this species. Therefore, the potential for this species to occur on the site is high.

Purple Martin

Purple martins are summer residents of California, nesting mostly in old woodpecker cavities but also in human-made structures. Nests are often located in tall, isolated trees or snags. There is one record of this species within five miles of the project site (**Figure 3**) (CDFW 2013). Because the potential for nesting sites in snags or isolated trees is

high, and because this species has been recorded within five miles of the project site, the potential for this species to occur onsite is high.

White-Tailed Kite

The white-tailed kite is a medium sized raptor that is a yearlong resident in coastal and valley lowlands in California. White-tailed kites are monogamous and breed from February to October, peaking from May to August (Zeiner *et al.*, 1990). This species nests near the top of dense oak, willow, or other large trees. There is one CNDDB record for white-tailed kite listed within five miles of the project site (**Figure 3**) (CDFW 2013). This species was not observed on the site during the biological assessment. However, the grassland habitat on the site provides potential foraging habitat for this species and there are trees associated with the oak woodland community on the site that could provide potential nesting habitat. Therefore, the potential for this species to occur on the site is high.

Raptor and Other Migratory Bird Species

Raptor species forage and nest in a variety of habitats throughout Placer County. The nests of raptors and most other birds are protected under the MBTA. Raptors are also protected by Section 3503.5 of the California Fish and Game Code, which makes it illegal to destroy any active raptor nest. The oak woodland, riparian forest, and annual grassland on the project site may provide potential nesting and foraging habitat for raptors and other protected bird species. Although no active nests were observed on the site, one red-tailed hawk was heard vocalizing on the site July 2006 and a turkey vulture was also observed in flight over the site. Raptors and other protected migratory birds have a *high* potential to occur on the site.

Species with a Low Potential for Occurrence

Western Pond Turtle

Western pond turtles require slow moving perennial aquatic habitats with suitable basking sites. Pond turtles have sometimes adapted to using irrigation ditches. Suitable aquatic habitat typically has a muddy or rocky bottom and has emergent aquatic vegetation for cover (Stebbins 2003). There is one CNDDB record for this species within five miles of the project site (**Figure 3**) (CDFW 2013). No turtles were observed on the project site during the biological assessment. However, there is some potential habitat for this species within Secret Ravine. Therefore, the potential for this species to occur on the site is low.

Western Spadefoot

The western spadefoot is found throughout the Central Valley south to Baja Mexico. It is found in a variety of habitats including grasslands, washes, and floodplains. It breeds in seasonal depressional wetlands and deep vernal pools (Stebbins 2003). During the summer months, adults will seek out upland refugia such as small mammal burrows. The breeding period is typically January through May (Stebbins 2003). There is one record for this species in the CNDDB within five miles of the project site (**Figure 3**) (CDFW 2013). This species was not observed on the site during the biological assessment.

However, the limited depressional seasonal wetlands and some areas along Secret Ravine on the site provide some potential breeding habitat for this species and there are small mammal burrows on the site suitable for use as upland refugia. Therefore, the potential for this species to occur on the site is low.

Grasshopper Sparrow

Grasshopper sparrows are regularly seen in California during the summer breeding season. Little is known of their winter range, but some birds are known to overwinter in the state. Grasshopper sparrows frequent dense, dry grasslands and utilize scattered shrubs for singing perches. The annual grassland on the site provides suitable nesting and foraging habitat, although there are no records for this species in the CNDDB within five miles of the project site (CDFW 2013). Therefore, the potential for this species to occur on the site is low.

Song Sparrow

Song sparrows are year-round residents of California most commonly found in freshwater marsh and early stage riparian habitat. Moderately dense vegetation, such as cattails, willow thickets, or blackberry, near a source of water is required for nesting. Song sparrows forage primarily on the ground (Shuford and Gardali, 2008). The riparian forest provides suitable nesting and foraging habitat. There are no records for this species in the CNDDB within five miles of the project site (CDFW 2013). Therefore, the potential for this species to occur on the site is low.

Swainson's Hawk

Swainson's hawk is a long-distance migrant with nesting grounds in western North America. The Swainson's hawk population that nests in the Central Valley winters primarily in Mexico, while the population that nests in the interior portions of North America winters in South America (Bradbury et. al. in prep.). Swainson's hawks arrive in the Central Valley between March and early April to establish breeding territories. Breeding occurs from late March to late August, peaking in late May through July (Zeiner et. al. 1990). In the Central Valley, Swainson's hawks nest in isolated trees, small groves, or large woodlands next to open grasslands or agricultural fields. This species typically nests near riparian areas; however, it has been known to nest in urban areas as well. Nest locations are usually in close proximity to suitable foraging habitats, which include fallow fields, annual grasslands, irrigated pastures, alfalfa and other hay crops, and low-growing row crops. Swainson's hawks leave their breeding grounds to return to their wintering grounds in late August or early September (Bloom and De Water, 1994). Although there are no records in the CNDDB of this species within five miles of the site, there are three records within 10 miles of the site (CDFW 2013) and the larger cottonwoods and oaks in the riparian woodland present potential nesting habitat. The species was not observed on the site during the biological assessment. For these reasons, Swainson's hawk has a *low* potential to occur within the site.

Western Burrowing Owl

Western burrowing owl is a small ground-dwelling owl that occurs in western North America from Canada to Mexico, and east to Texas, and Louisiana. Although in certain areas of its range western burrowing owls are migratory, these owls are predominantly non-migratory in California (Zeiner *et al.*, 1990). The breeding season for western burrowing owls occurs from February to August, peaking in April and May (Zeiner *et al.*, 1990). Western burrowing owls nest in burrows in the ground, often in old ground squirrel burrows. This owl is also known to use artificial burrows including pipes, culverts, and nest boxes. There are no CNDDB records for this species within five miles of the site (CDFW 2013) and no western burrowing owls were observed during the biological assessment. However, the grassland habitats on the site provide potential habitat for this species. Suitable burrows for this species were not observed during the biological assessment. This lowers the potential for this species to occur. Therefore, the potential for burrowing owls to occur on the site is low.

Pallid Bat and Other Special-Status Bat Species

Several special-status bat species, which are State Species of Concern, have the potential to roost on the project site. Pallid bats roost in rock crevices and caves and occasionally hollow trees and buildings. Long-eared myotis (*Myotis evotis*) live in thinly forested areas and occasionally caves. Hoary bats (*Lasiurus cinereus*) live in wooded areas and hang in trees. Western red bat (*Lasiurus blossevillii*) roosts primarily in trees, usually at edges of streams, fields, or urban areas.

There are no CNDDB records for any of these special-status bat species within five miles of the project site (CDFW 2013) and no bat species were observed onsite during the biological assessment. However, the oak woodlands provide potential roosting habitat; therefore, the potential is *low* for special-status bat species to occur on the site.

5.5 Sensitive Habitats

Sensitive habitats include those that are of special concern to resource agencies or those that are protected under CEQA, Section 1600 of the California Fish and Game Code, or Section 404 of the Clean Water Act. Additionally, sensitive habitats are protected under the specific policies outlined in the Placer County General Plan. Sensitive habitats known to occur on the site, which include wetlands/waters of the U.S., are depressional seasonal wetlands, riverine seasonal wetlands, mixed riparian forest, and oak woodlands (**Figure 4**).

5.5.1 Potential Jurisdictional Waters of the U.S.

Potential jurisdictional waters of the U.S. located on the site total approximately 1.13 acres. Of this acreage, approximately 0.53 acre of riverine seasonal wetland, 0.15 acre of depressional seasonal wetland, 0.44 acre of perennial drainage, 0.01 acre of intermittent drainage, and 0.01 acre of pond. Potential wetland areas on the site have been formally delineated. However, the Corps has not verified these acreages as of the date of this biological resource assessment.

Jurisdictional waters of the U.S. include jurisdictional wetlands as well as all other waters of the U.S. such as creeks, ponds, and intermittent drainages. Wetlands are defined as "those areas that are inundated or saturated by surface or ground water at a frequency and

duration sufficient to support and under normal circumstances do support, a prevalence of vegetation typically adapted for life in saturated soil conditions" (Corps 1987). The majority of jurisdictional wetlands in the United States meet the following three wetland assessment criteria: hydrophilic vegetation, hydric soils, and wetland hydrology. Jurisdictional waters of the U.S. can also be defined by exhibiting a defined bed and bank and OHWM. As discussed in **Regulatory Framework**, jurisdictional waters of the U.S. are subject to Section 404 of the CWA and are regulated by the Corps.

5.5.2 Protected Trees

Approximately 3,000 protected trees were surveyed on the project site, consisting of interior live oaks (*Quercus wislizeni*), valley oaks (*Quercus lobata*), blue oaks (*Quercus douglasii*), and oracle oaks (*Quercus x morehus*). Detailed data on protected and dead trees located on the project site are contained under separate cover in the project *Arborist Report*.

6.0 DISCUSSION AND RECOMMENDATIONS

As discussed, the project site consists of land that supports primarily annual grassland and riparian oak woodland habitats. Known or potential biological constraints on the site include the following:

- Potential habitat for special-status plant species (including big-scale balsamroot, Brandegee's clarkia, dubious pea, and Sanford's arrowhead);
- Potential habitat for valley elderberry longhorn beetle;
- Potential special-status fish habitat;
- Potential habitat for western pond turtle;
- Potential habitat for spadefoot;
- Potential nesting habitat and foraging habitat for raptors (including Cooper's hawk, osprey, white-tailed kite, and Swainson's hawk) and other species protected by the MBTA (including purple martin, song sparrow, and grasshopper sparrow);
- Potential western burrowing owl habitat;
- Potential special-status bat habitat;
- Sensitive habitats (wetlands including seasonal wetlands, mixed riparian forest, perennial drainage, and oak woodland); and
- Protected trees

6.1 Special-Status Plants

As discussed, the site contains potential habitat for four special-status plant species. Based on this, focused special-status plant surveys are recommended to determine presence or absence of the potentially occurring plant species identified in **Table 1**. The survey should be conducted by a qualified biologist during the blooming period for all species that could potentially occur on the site as listed in **Table 1** of this biological resource assessment. If special-status plant species are found, then a mitigation plan should be prepared in consultation with the appropriate agencies. The plan should detail the various mitigation approaches to ensure no net loss of rare plants. Examples of mitigation include avoidance of the resource, salvage of plant materials where possible, acquisition of credits at an approved mitigation bank, or acquisition and preservation of property that supports these species.

6.2 Valley Elderberry Longhorn Beetle

Although no Valley Elderberry Longhorn Beetle (VELB) were observed on the site, there is a high potential for VELB to be present on the site due to the large number of elderberry shrubs present on the site (**Figure 4**) and evidence of past presence as shown by VELB exit holes (**Appendix A**). Although VELB has been proposed for delisting, final action has not been taken by the USFWS. If VELB is still federally listed during

development of the project, then coordination with the USFWS will be required through either the Section 7 (in conjunction with a CWA Section 404 permit from the Corps) or the Section 10 (if no other Federal permits are required) process to determine appropriate avoidance and mitigation measures.

Currently, the USFWS suggests mitigation for impacts to any elderberry shrub with stems greater than 1 inch in diameter at ground level. USFWS calls for a 100-foot buffer to be maintained around any existing elderberry shrub to prevent potential VELB habitat from being impacted. If direct impacts to the shrubs cannot be avoided, mitigation may be required. Mitigation for impacts to elderberry shrubs typically involves the transplantation of the shrubs to be impacted, along with the planting of additional elderberry shrubs and associated riparian plant species within a designated mitigation area. The number of additional elderberry shrubs and associated vegetation varies depending on the number and diameter of elderberry stems suitable for use by VELB that are impacted by the project. The USFWS requires transplantation to occur between the beginning of November and the first two weeks of February when elderberries are typically dormant and the chance of transplantation success is higher.

The diameter and number of live stems of each elderberry shrub were inventoried in 2007 (**Appendix A**). Since mitigation requirements are based on the size of impacted elderberry stems, presence or absence of VELB exit holes, and location in riparian habitat, it is recommended that all elderberries on the site be resurveyed during the spring or summer months to determine their current condition.

6.3 Special-Status Fish Species

Secret Ravine is not expected to be directly impacted by the proposed project. Therefore, no direct impacts to potential habitat for these species are expected and no further mitigation for these species is expected to be necessary. Care should be taken to avoid impacts to water quality from sediment or pollutant runoff into Secret Ravine. This will be addressed during construction by the preparation and implementation of a storm water pollution prevention plan (SWPPP). The project design should integrate design features that will minimize creek impacts, such as maintaining vegetated setbacks and treating runoff on site. If the project requires a streambed alteration agreement for impacts to Secret Ravine or its associated riparian habitat, CDFW will likely require mitigation measures to preserve existing salmonid habitat on the site.

6.4 Western Pond Turtle

Secret Ravine may be utilized by western pond turtle and the surrounding uplands provide potential nesting and overwintering habitat. Therefore, it is recommended that a pre-construction survey for western pond turtle be conducted prior to any construction activity that would directly impact aquatic habitat or occur within 300 feet of the perennial drainage. If western pond turtles are found during the pre-construction survey, CDFW and USFWS should be contacted regarding additional mitigation measures that may be required. Additional mitigation measures would only be considered in the event that western pond turtles were located during the pre-construction survey.

6.5 Western Spadefoot

Any impacts to seasonal wetlands on the site could potentially impact western spadefoot. Wetland conservation and mitigation measures implemented as part of the 404 permit process discussed in **Section 6.9** are expected to compensate for any potential impacts to this species. Therefore, specific mitigation measures are not recommended.

6.6 Raptors and Other Avian Species

As discussed earlier, several species of raptors and other protected birds forage and may nest on the site including Cooper's hawk, osprey, white-tailed kite, Swainson's hawk, purple martin, song sparrow, and grasshopper sparrow. Active raptor nests are protected by the California Fish and Game code Section 3503.5 and the MBTA. For this reason, if construction is expected to occur during the typical raptor nesting season (February-August), a pre-construction raptor survey is recommended to determine if active raptor nests are present on the project site. The survey should be conducted by a qualified biologist no more than 30 days prior to the onset of construction activities.

If active raptor nests are found on or within 500 feet of the project impact area, construction activities should not occur within 500 feet of the nests, or up to ¼-mile of the nest if it is an active Swainson's hawk nest, until the young have fledged or until the biologist has determined that the nest is no longer active. Extensive buffers are not necessary for nesting avian species protected solely by the MBTA. However, depending on the species, site conditions, and the proposed construction activities near the active nest, a small buffer, typically, a 50-100 feet wide, may be prescribed, as determined by the biologist. If active nests are found, the CDFW should be consulted for mitigation measures that may be required. If construction activities are proposed to begin during non-breeding season (September-January), a survey is not required and no further studies are necessary.

6.7 Western Burrowing Owl

Although burrowing owls were not observed during the biological assessment, the site contains annual grassland habitat that is suitable foraging and nesting habitat for burrowing owl. Although no suitable burrows were observed during the biological assessment, the grassland habitat is still considered potential habitat for this species. For this reason, it is recommended that a burrowing owl survey of the project impact area be conducted no more than 30 days prior to the onset of construction. Burrowing owls can be present during all times of the year in California, so this survey is recommended regardless of the time construction activities occur. If active owl burrows are located during the pre-construction survey, it is recommended that a 250-foot buffer zone be established around each burrow with an active nest until the young have fledged and are able to exit the burrow. If occupied burrows are found with no nesting occurring, if active burrows are found after the young have fledged, or if development commences after the breeding season (typically February-August), passive relocation of the birds should be performed. Passive relocation involves installing a one-way door at the burrow entrance, which encourages the owls to move from the occupied burrow. CDFW should be consulted for current guidelines and methods for passive relocation of any owls found

on the site. Mitigation for project impacts that result in relocation of burrowing owls and loss of burrows and/or foraging habitat may be required for CEQA projects (CDFW recommends 6.5 acres of foraging habitat be preserved for each active burrow that would be impacted by project activities). The lead agency under CEQA, in coordination with CDFW, is responsible for prescribing appropriate mitigation for any project-related impacts to burrowing owls. These mitigation measures would only apply in the event that burrowing owls were encountered during the pre-construction survey.

6.8 Special-Status Bat Species

The existing large trees could provide potential roosting habitat for various bat species that occur in the vicinity of the study area. Prior to the initiation of construction activities, it is recommended that a pre-construction survey be performed by a qualified biologist to determine if special-status bat species are roosting in tree crevices in the oak woodlands within the project impact area. If special-status bat species are present and roosting on the project site, then CDFW should be consulted regarding potential additional mitigation measures. Adoption of mitigation measures for roosting bat species would be considered only if special-status bat species are found to be roosting within the project impact area.

6.9 Sensitive Habitats

Potential jurisdictional waters of the U.S. located on the site total approximately 1.13 acres. Of the total, there is an estimated 0.53 acre of riverine seasonal wetland, 0.15 acre of depressional seasonal wetland, 0.44 acre of perennial drainage, 0.01 acre of intermittent drainage, and 0.01 acre of pond. These areas are regulated by the Corps. Additionally, these areas are protected under the Town of Loomis General Plan. Consequently, it is recommended that the jurisdictional assessment for the project site should be submitted to the Corps and the appropriate Section 404 permit should be acquired for any project-related impacts to jurisdictional features. Any waters of the U.S. that would be lost or disturbed should be replaced or rehabilitated on a "no-net-loss" basis in accordance with the Corps' mitigation guidelines. Habitat restoration, rehabilitation, and/or replacement should be at a location and by methods agreeable to the Corps. Impacts to jurisdictional features would also require a 401 water quality certification from the Regional Water Quality Control Board.

It is also recommended that a Streambed Alteration Agreement be obtained from CDFW, pursuant to Section 1600 of the CDFG Code, for each stream crossing and any other activities affecting the bed, bank or associated riparian vegetation of the perennial drainage (Secret Ravine). If required, the project applicant should coordinate with CDFW in developing appropriate mitigation, and should abide by the conditions of any executed permits.

As discussed in Section 3.8, the Loomis General Plan typically requires setbacks of 100 feet from the outermost edge of riparian vegetation along perennial creeks and 50 foot setbacks from ephemeral or intermittent drainages. Lesser setbacks may be approved based on site-specific studies. On the northern half of the site, the riparian woodland on

the site is extensive, ranging from approximately 40 to 180 feet in width, and is confined to a lower terrace along Secret Ravine (**Figure 4**). This terrace is approximately 8 to 10 feet below the majority of the site. As shown in **Figure 5**, the proposed development will be constructed primarily on the upper terrace of the site. With implementation of standard erosion control and stormwater management measures during design and construction, the proposed development is not expected to have significant impacts on the aquatic resources of Secret Ravine due to the existing grade difference and width of the riparian vegetation.

6.10 Protected Trees

A tree permit will be required prior to the removal of any protected tree. Once development plans are finalized, impacts to protected trees should be assessed and the Town of Loomis consulted to determine the appropriate mitigation measures. Detailed information on tree impacts and mitigation requirements is included in the project Arborist Report.

6.11 Summary of Recommended Conservation Measures


- Obtain necessary permits for work done within Secret Ravine or other jurisdictional wetlands (Section 404 Clean Water Act permit, Section 401 Water Quality Certification, and 1600 Streambed Alteration Agreement).
- Obtain Tree Permit from Town of Loomis.
- Conduct special-status plant surveys during bloom season (March October).
- Re-inventory elderberry shrubs to document stem diameter, presence or absence of VELB exit holes, and surrounding habitat characteristics.
- Coordinate with USFWS to determine avoidance or mitigation measures for VELB habitat, if required.
- Conduct pre-construction Worker Environmental Awareness Training regarding identification of and protection for special-status species and sensitive habitats on the project site.
- Conduct pre-construction survey for western pond turtle if construction will occur in or within 300 feet of Secret Ravine.
- Conduct pre-construction survey for active bird nests, bat roosts, and burrowing owls in project impact area.
- Prepare project SWPPP and implement BMPs to prevent sediment and runoff from entering Dry Creek.


7.0 REFERENCES


- Baldwin, B.G., D.H. Goldman, D.J. Keil, R. Patterson, T.J. Rosatti, and D.H. Wilken, editors. 2012. *The Jepson manual: vascular plants of California, second edition*. University of California, Berkeley.
- Barr, C.B. 1991. The distribution, habitat, and status of the valley elderberry longhorn beetle *Desmocerus californicus dimorphus*. U.S. Fish and Wildlife Service: Sacramento, CA.
- Bloom, P. and D. Van De Water. 1994. *Swainson's Hawk* in Life on the Edge: A Guide *to California's Endangered Natural Resources: Wildlife*. BioSystems Books, Santa Cruz, CA.
- California Department of Fish and Game (CDFG). 1988. A Guide to Wildlife Habitats of California. Sacramento, CA.
- CDFG. 1994. Staff Report regarding Mitigation for Impacts to Swainson's Hawks (Buteo swainsoni) in the Central Valley of California.
- California Department of Fish and Wildlife (CDFW). 2013. *California Natural Diversity Data Base*. Sacramento, CA.
- California Native Plant Society (CNPS). 2010. Online Inventory of Rare and Endangered Plants of California (eighth edition). Sacramento, CA.
- Collinge, S.K., M. Holyoak, C.B. Barr, and J.T. Marty. 2001. Riparian habitat fragmentation and population persistence of the threatened valley elderberry longhorn beetle in Central California. *Biological Conservation* 100:103–113.
- Natural Resource Conservation Service (NRCS). April 2012. *National Hydric Soils List*. U.S. Department of Agriculture.
- Sawyer, John O. and Todd Keeler-Wolf. 1995. *A Manual of California Vegetation*. California Native Plant Society (CNPS), Sacramento, CA.
- Shuford, W. D., and Gardali, T., editors. 2008. *California Bird Species of Special Concern: A ranked assessment of species, subspecies, and distinct populations of birds of immediate conservation concern in California*. Studies of Western Birds 1. Western Field Ornithologists, Camarillo, California, and California Department of Fish and Game, Sacramento.
- Stebbins, Robert C. 2003. Western Reptiles and Amphibians (third edition). Houghton Mifflin Company, Boston, MA.


36

- U.S. Department of the Interior, Fish and Wildlife Service. 1980. Listing the valley elderberry longhorn beetle as a threatened species with critical habitat. Federal Register 45:52803–52807.
- U.S. Department of the Interior, Fish and Wildlife Service. 1984. Recovery plan for the valley elderberry longhorn beetle. U.S. Fish and Wildlife Service, Endangered Species Program: Portland, Oregon.
- U.S. Department of the Interior, Fish and Wildlife Service. 1999. Conservation Guidelines for the Valley Elderberry Longhorn Beetle: Sacramento, California.
- U.S. Fish and Wildlife Service. 2013. "Federal Endangered and Threatened Species that may be affected by Projects in the Rocklin, Auburn, Gold Hill, Lincoln, Roseville, Pilot Hill, Clarksville, Folsom, and Citrus Heights 7.5 minute series quadrangles." Sacramento, CA.
- U.S. Geological Survey. 1967. Photorevised 1981. "Rocklin Quadrangle California 7.5-minute series topographic quadrangle." United States Department of Interior.
- Zeiner, D.C., W.R. Laudenslayer Jr., K.E. Mayer, and M. White, eds. 1990. *California's Wildlife Volume II: Birds*, State of California: The Resource Agency, Department of Fish and Wildlife, Sacramento, CA.











6201 Horseshoe Bar Road

Conceptual Development Plan.pub © 2014

Appendix A — 2007 Elderberry Shrub Data

Shrub #	Number of	Number of	Number of	Number of	Stem	Exit
Shrub#	Stems <1 "	Stems 1-3 "	Stems 3-5"	Stems >5"	Total	Holes?
1		1			1	N
2	7	1			8	N
3*	1				1	N
4*	1				1	N
5*	1				1	N
6		1		2	3	Y
7		2	2	3	7	Y
8	1	10		1	12	N
9		9		3	12	Y
10		9	1		10	Y
11		1			1	N
12		2	1		3	N
13			1		1	N
14		4		1	5	N
15			2		2	Y
16		1	2		3	N
17			2		2	N
18				2	2	Y
19		1	1	1	3	N
20		2			2	N
21	2	4	1		7	Y
22*	1		1		2	N
23	3	4			7	Y
24	1	1			2	Y
25	4	4			8	Y
26	2*				2	N
27		3			3	Y
28			1		1	Y
29		5			5	N
30	2	2			4	N
31		1	1		2	Y
32		2			2	N
Total Stem Counts	26	70	16	13		

^{*-} Stems under 1" are not considered VELB habitat

Delineation of Waters of the United States

6201 Horseshoe Bar Road ±63-Acre Site Placer County, California

Prepared for: U.S. Army Corps of Engineers

Contracted By: Tulip Asset LLC

March 27, 2014



Table of Contents

1.0	EXECUTIVE SUMMARY	1
2.0	Introduction	2
3.0	Regulatory Background	3
	.1 Waters of the United States	
	.2 The SWANCC Decision	
	Methodology	
	1 Site-Specific References	
	2 Research and Field Methodology	
	Results	
5	.1 Study Area Description, Land Use	
	5.1.1 Study Area Location	
	5.1.2 Land Use	
5	5.1.3 Site History and Description	
3	5.2.1 Soils	
	5.2.2 Topography	
	5.2.3 Regional Hydrology	
	5.2.4 Site-Specific Hydrology	
5	3 Vegetation	
	5.3.1 Annual Grassland	
	5.3.2 Oak Woodland	
	5.3.3 Great Valley Mixed Riparian Forest	
5	.4 Classification of Waters of the United States	
	5.4.1 Depressional Seasonal Wetland	
	5.4.2 Riverine Seasonal Wetland	
	5.4.3 Intermittent Drainage	
	5.4.4 Perennial Drainage	
	5.4.5 Pond	
6.0	Conclusions	14
7.0	References	15
T :.	et of Tables	
		1.4
rat	ble 1 — Waters of the U.S.: Acreage According to Feature Classification	14
т •	A of Figures	
	st of Figures	1.7
	gure 1 — Site and Vicinity	
Fig	gure 2 — Soils	18
Fig	gure 3 — Delineated Waters of the U.S.	19

List of Appendices

Appendix A — Contact Information

Appendix B — Routine Wetland Determination Data Forms
Appendix C — Preliminary Jurisdictional Determination Form

1.0 EXECUTIVE SUMMARY

This report presents the results of a delineation of the waters of the United States on the 6201 Horseshoe Bar Road site that may be subject to Federal jurisdiction and regulation under Section 404 of the Clean Water Act. A total of 1.13 acres of waters of the U.S., comprised of 0.15-acre of depressional seasonal wetlands, 0.53 acre of depressional seasonal wetland, 0.01 acre of intermittent drainage, 0.44 acre of perennial drainage, and 0.01 acre of pond were delineated on the site.

1

2.0 INTRODUCTION

The purpose of this document is to present the results of a formal delineation of jurisdictional waters of the United States, including wetlands, on the ± 63 -acre 6201 Horseshoe Bar Road site. The site is located within the Town of Loomis, California in Placer County (**Figure 1**).

This report presents the results of Foothill Associates' review of available literature, aerial photographs, soil surveys (**Figure 2**), and fieldwork on the site. These results are summarized to depict jurisdictional waters of the United States following the technical guidelines provided in the 1987 *U.S. Army Corps of Engineers Wetlands Delineation Manual* and the *Arid West Regional Supplement* for identifying wetlands and distinguishing them from aquatic habitats and other nonwetlands. The jurisdictional boundaries for other waters of the United States were identified based on the presence of an ordinary high-water mark (OHWM) as defined in 33 CFR 328.3(e).

The delineation methodology is described in this report, followed by the results of the delineation. Details regarding soils, topography, hydrology, and vegetation are summarized and routine wetland determination data forms are provided in **Appendix B**. A detailed delineation map illustrates waters of the U.S. on the site (**Figure 3**).

3.0 REGULATORY BACKGROUND

The U.S. Army Corps of Engineers (Corps) regulates discharge of dredged or fill material into waters of the United States under Section 404 of the Clean Water Act (CWA). "Discharges of fill material" is defined as the addition of fill material into waters of the U.S., including, but not limited to the following: placement of fill that is necessary for the construction of any structure, or impoundment requiring rock, sand, dirt, or other material for its construction; site-development fills for recreational, industrial, commercial, residential, and other uses; causeways or road fills; fill for intake and outfall pipes and subaqueous utility lines [33 C.F.R. §328.2(f)].

Section 401 of the CWA (33 U.S.C. 1341) requires any applicant for a federal license or permit to conduct any activity that may result in a discharge of a pollutant into waters of the United States to obtain a certification that the discharge will comply with the applicable effluent limitations and water quality standards.

Section 404 of the Clean Water Act requires approval prior to discharging dredged or fill material into the waters of the United States. Typical activities requiring Section 404 permits are:

- Depositing of fill or dredged material in waters of the U.S. or adjacent wetlands;
- Site development fill for residential, commercial, or recreational developments;
- Construction of revetments, groins, breakwaters, levees, dams, dikes, and weirs; and
- Placement of rip-rap and road fills.

Section 10 of the Rivers and Harbors Act of 1899 requires approval prior to the accomplishment of any work in or over navigable waters of the United States, or which affects the course, location, condition or capacity of such waters. Typical activities requiring Section 10 permits are:

- Construction of piers, wharves, bulkheads, dolphins, marinas, ramps, floats, intake structures, and cable or pipeline crossings; and
- Dredging and excavation.

Any person, firm, or agency (including federal, state, and local government agencies) planning to work in navigable waters of the United States, or dump or place dredged or fill material in waters of the United States, must first obtain a permit from the Corps. Permits, licenses, variances, or similar authorization may also be required by other federal, state and local statutes.

3.1 Waters of the United States

33 C.F.R. Section 328.3 provides that "waters of the United States" include all waters that are currently used, or were used in the past or are susceptible to use in interstate commerce, all interstate waters and wetlands, and all intrastate lakes, rivers or streams which could affect interstate commerce. In addition, this regulation provides jurisdiction over waters that are tributary to these waters, and "wetlands" adjacent to them. Section 10 and/or Section 404 permits are required for construction activities in these waters. Boundaries between jurisdictional waters and uplands are determined in a variety of ways depending on which type of water is present. Methods for delineating wetlands and non-tidal waters are described below.

Wetlands are defined as "those areas that are inundated or saturated by surface or groundwater at a frequency and duration sufficient to support and under normal circumstances do support, a prevalence of vegetation typically adapted for life in saturated soil conditions" [33 C.F.R. §328.3(b)]. Presently, to be a wetland, a site must exhibit positive indicators of three wetland criteria: hydrophytic vegetation, hydric soils, and wetland hydrology existing under the "normal circumstances" for the site.

The lateral regulatory extent of non-tidal waters is determined by delineating the ordinary high water mark (OHWM) [33 C.F.R. §328.4(c)(1)]. The OHWM is defined by the Corps as "that line on shore established by the fluctuations of water and indicated by physical character of the soil, destruction of terrestrial vegetation, the presence of litter and debris, or other appropriate means that consider the characteristics of the surrounding areas" [33 C.F.R. §328.3(e)].

3.2 The SWANCC Decision

The Solid Waste Agency of Northern Cook County v. the U.S. Army Corps of Engineers, 531 U.S. 159 (2001), is more commonly referred to as the SWANCC decision. SWANCC involved a challenge to CWA jurisdiction over certain isolated, intrastate, non-navigable ponds in Illinois that formerly had been gravel mine pits, but which, over time, provided habitat for migratory birds. Although these ponds served as migratory bird habitat, they were non-navigable and isolated from the tributary system of other waters regulated under the CWA. In SWANCC, the Supreme Court held that the Army Corps of Engineers had exceeded its authority in asserting CWA jurisdiction pursuant to § 404(a) over the waters at issue based on their use as habitat for migratory birds, pursuant to preamble language, commonly referred to as the Migratory Bird Rule [51 Fed. Reg. 41217 (1986)].

SWANCC squarely eliminates CWA jurisdiction over isolated waters that are intrastate and non-navigable, where the sole basis for asserting CWA jurisdiction is the actual or potential use of the waters as habitat for migratory birds that cross state lines in their migrations. CWA jurisdiction extends to waters, including wetlands, which are adjacent to navigable waters pursuant to the Supreme Court holding in Riverside Bayview Homes, which was endorsed in SWANCC as controlling law. Corps and EPA regulations currently define the term adjacent as "bordering, contiguous, or neighboring" [33 C.F.R.

§ 328.3(b)]. The case law on the precise scope of federal CWA jurisdiction since SWANCC is still developing.							

5

4.1 Site-Specific References

Available information pertaining to the natural resources of the region was reviewed. All references reviewed for this delineation are listed in **Section 7.0**. Pertinent site-specific reports and general references utilized concurrent with the delineation include the following:

- Baldwin, B.G., D.H. Goldman, D.J. Keil, R. Patterson, T.J. Rosatti, and D.H. Wilken, editors. 2012. *The Jepson manual: vascular plants of California*, second edition. University of California, Berkeley;
- Environmental Laboratory. 1987. Corps of Engineers Wetlands Delineation Manual. U.S. Army Corps of Engineers Waterways Experiment Station. Vicksburg, MS;
- Federal Emergency Management Agency (FEMA). 1998. National Flood Insurance Program Q3 Flood Data, Disc 1: California;
- GretagMacbeth. 2000. Munsell Soil Color Charts. New Windsor, NY;
- Lichvar, R.W. 2013. The National Wetland Plant List: 2013 wetland ratings. Phytoneuron 2013-49: 1-241;
- Natural Resource Conservation Service (NRCS). 1980. Soil Survey of Placer County, Western Part, California. U.S. Department of Agriculture;
- NRCS. 2010. Field Indicators of Hydric Soils in the United States, Version 7. G.W. Hurt, P.M. Whited, and R.F. Pringle (Eds). USDA, NRCS in cooperation with the National Committee for Hydric Soils. Fort Worth, TX;
- NRCS. April 2012. *Hydric Soils List for Placer County, California*. U.S. Department of Agriculture;
- U.S. Geological Survey (USGS). 1967. Photorevised 1981. *Rocklin, California* 7.5-minute series topographic quadrangle. United States Department of the Interior; and
- USGS. May 2002. *Sacramento Urban 0.3-meter DOQQ Imagery*. U.S. Department of the Interior.

4.2 Research and Field Methodology

This delineation utilized the Corps' 1987 three-parameter (vegetation, hydrology, and soils) methodology to delineate jurisdictional waters of the U.S., focusing specifically on jurisdictional wetlands. This methodology requires the collection of data on soils, vegetation, and hydrology at several locations to establish the jurisdictional boundary of wetlands. Additional methods to identify and delineate other waters of the U.S. (e.g.,

streams, drainages, lakes) were used as applicable. The method typically used for delineation of non-wetland waters of the U.S. is the delineation of the OHWM.

A review of current aerial photographs, topographic maps, and soils survey data was conducted before a field review of the delineation site. The initial delineation was conducted on August 2, 7, 8, 29 and September 20 of 2006. The 2006 delineation was updated with additional field surveys on November 19 and 20, 2013. Biologists visually inspected the entire site and collected representative data at points within potential wetland areas and corresponding uplands. The location of each data point is depicted in **Figure 3** and corresponding routine wetland determination data forms are provided in **Appendix B**.

4.3 GPS Data Integration

Boundaries of aquatic features within the site were surveyed and mapped with a Trimble GeoXT Global Positioning System (GPS) hand-held unit. This is a mapping-grade GPS unit capable of real-time differential correction and sub-meter accuracy. The GPS data were downloaded from the unit and differentially corrected utilizing Trimble Pathfinder Office software and appropriate base station data, and then converted to ESRI [®] shape file format. Data are typically exported to the Geographic Information System (GIS) software in the State Plane coordinate system (NAD 83) with units as "survey feet." Within the GIS, data are edited and linear features are built into polygons using recorded width information. All wetland shape files are merged to create a single wetland file with calculated acreages. These results are presented in **Figure 3**.

7

5.1 Study Area Description, Land Use

5.1.1 Study Area Location

The ±63-acre site is located in the Town of Loomis, California, immediately south and east of Interstate 80 and is bisected by Horseshoe Bar Road. The site is bounded by Interstate 80 on the north, Secret Ravine and Brace Road on the south, and Betty Road to the west. The site is also bound on the west by rural residences and agricultural lands and on the east by rural residences, agricultural lands, and oak woodland. The site is located within Section 10 of Township 11 North, Range 7 East on the *Rocklin*, *California* USGS 7.5-minute quadrangle map (**Figure 1**).

5.1.2 *Land Use*

The site primarily consists of agricultural land, portions of which are used for horse and cattle grazing. There are a few structures associated with keeping livestock on a portion of the site immediately north of Horseshoe Bar Road. Local land uses surrounding the site consist of agriculture (including grazing), rural residential development, and commercial development along Brace Road and on the north side of Interstate.

5.1.3 Site History and Description

A review of an archaeological report indicates the site has been utilized for livestock grazing, a rural residence, and limited agricultural activities (Jensen, 2006). Portions of the southern half of the site west of Horseshoe Bar Road have been disced and are currently used as grazed annual grassland. A few sporadic fruit trees occur within the oak woodland west of Horseshoe Bar Road.

5.2 Physical Features

5.2.1 Soils

The Natural Resources Conservation Service (NRCS) has mapped three soil units on the site (Figure 2). The soil units that occur on the site include the following: Andregg coarse sandy loam, 2 to 9 percent slopes; Xerorthents, cut and fill; and Xerorthents, Placer areas. General characteristics associated with these soils types are described below.

• Andregg coarse sandy loam, 2 to 9 percent slopes: This moderately deep and well-drained soil is found on low hills in the Loomis Basin between 200 and 1,000 feet above mean sea level (MSL). Andregg soils formed in material weathered from coarse grained acid igneous rocks, mainly granodiorite. Permeability in this soil is moderately rapid and available water capacity is low.

8

Natural vegetation includes annual grasses, herbaceous species, blue oak (*Quercus douglasii*), live oak (*Quercus wislizenii*), and scattered pines (*Pinus* spp.). This soil is used mainly for rangeland, while very limited areas are used for pasture or orchards. The hydric soils list for Placer County identifies one unnamed hydric inclusion located within drainageways of this soil type.

- Xerorthents, cut and fill: This soil unit consists of mixed soil material that no longer contains discernable horizons. Cut and fill areas are typically well-drained and surface runoff is very rapid. Permeability and available water capacity are variable. These areas are typically used for highways and urban development. The hydric soils list for Placer County does not identify hydric components or inclusions occurring within this soil type.
- **Xerorthents, Placer areas**: This soil unit consists of stony, cobbly, and gravelly materials adjacent to streams that have been placer mined. The soil material is derived from a mixture of rocks. Permeability, surface runoff, drainage, and available water capacity are variable. Natural vegetation typically includes annual grasses, oaks (*Quercus* spp.), willows (*Salix* spp.), alders (*Alnus* spp.), and cottonwoods (*Populus* spp.). These soils have some value for grazing and watering livestock. The hydric soils list for Placer County identifies one unnamed hydric inclusion located within drainageways of this soil type.

5.2.2 Topography

Mildly undulating topography and moderate inclines typify the site and the surrounding area. The topography of the western portions of the site is dominated by a series of more or less rolling hills and intervening low lying areas between them. Generally, the hills and drainageways are oriented in a northeast to southwest alignment. Slopes throughout the site range from approximately two to 50 percent. Elevation ranges from approximately 340 and 370 feet above MSL.

5.2.3 Regional Hydrology

The site is located within the Loomis Basin east of Interstate 80 and spans Horseshoe Bar Road. The Loomis Basin is located at the base of the Sierra-Nevada Mountains and lies between "intermediate" and "semi-Mediterranean" climate zones. The Loomis area typically has a wet season, which occurs from late fall through early spring, and a dry season, which occurs from late spring through early fall (PPGN 2006). Historically, several drainages in this area have been dredged in placer mining operations, which have resulted in the alteration of many waterways.

5.2.4 Site-Specific Hydrology

Portions of the site are within the historic 100-year floodplain of Secret Ravine (FEMA 1998). Annual average precipitation in the Loomis area is approximately 39 inches (PPGN 2006). Hydrologic features identified and mapped within the site include depressional seasonal wetlands, riverine seasonal wetlands, and perennial drainages

(**Figure 3**). Diagnostic characteristics of the features mapped on the site are defined and discussed in **Section 5.4**.

The majority of the seasonal wetlands occur within the southern portion of the oak woodland south of Horseshoe Bar Road. The depressional and riverine seasonal wetlands on the southern half of the site within the oak woodland are predominantly charged by the natural sheeting effect of surface water conducted by the surrounding upland topography, as well as direct rainfall. The riverine seasonal wetland identified as feature #6 is supplied water from an offsite ditch via a culvert. Once the depressional and riverine seasonal wetlands within the oak woodland area reach maximum inundation capacity, water flow likely continues toward Secret Ravine via overland sheet flow.

A perennial drainage flows across the northeastern portion of the site into Secret Ravine offsite. The eastern branch of the perennial drainage connects to a pond, of which a portion is onsite. Secret Ravine enters the western half of the site then continues to flow southeast along the southern property boundary as it meanders across the property boundary until exiting the site.

5.3 Vegetation

Three dominant vegetation assemblages occur on the site including: annual grassland, oak woodland, and Great Valley mixed riparian forest. A detailed description of each of vegetation type is described below.

5.3.1 Annual Grassland

Annual grassland is characterized primarily by an assemblage of non-native grasses and forbs. This vegetation community is found in the western half of the property adjacent to Interstate 80. Much of the vegetation in this community is common to the Central Valley. Dominant grass species within this community consist of soft chess (*Bromus hordeaceous*), ripgut brome (*Bromus diandrus*), wild oat (*Avena fatua*), Italian rye grass (*Festuca perennis*), medusahead (*Elymus caput-medusae*), and little quaking grass (*Briza minor*). Other herbaceous vegetation present were California poppy (*Eschscholzia californica*), clustered dock (*Rumex conglomerates*), rose clover (*Trifolium hirtum*), tarweed (*Centromadia pungens*), star thistle (*Centaurea solstitialis*), Italian thistle (*Carduus pycnocephalus*), vetch (*Astragalus* spp.), bindweed (*Convolvulus arvensis*), elegant broadiaea (*Brodiaea elegans*), and short-podded mustard (*Hirschfeldia incana*).

5.3.2 Oak Woodland

This community covers primarily the southern portion of the site adjacent to Secret Ravine. The overstory of this community is dominated by interior live oaks with scattered valley oaks (*Quercus lobata*), blue oaks, and foothill pines (*Pinus sabiniana*). The understory contains scattered toyon (*Adenostoma fasiculata*), California buckeye (*Aesculus californica*), coyotebrush (*Baccharis pilularis*), California blackberry (*Rubus ursinus*), whitethorn ceanothus (*Ceanothus cordulatus*), and poison oak (*Toxicodendron diversilobum*). Several blue elderberry shrubs (*Sambucus mexicana*) were found within

the oak woodland as well. Naturalized orchard trees within the oak woodland habitat included apple (*Malus* spp.), pear (*Pyrus* spp.), and common fig (*Ficus carica*).

5.3.3 Great Valley Mixed Riparian Forest

This community is associated primarily with the margins of Secret Ravine on the southern and eastern portions of the site. The overstory of this community contains willows, Fremont's cottonwood (*Populus fremontii*), and white alders (*Alnus rhombifolia*). The shrub layer contains blue elderberry, Himalayan blackberry (*Rubus armeniacus*), and poison oak.

5.4 Classification of Waters of the United States

Jurisdictional waters of the U.S. are classified into multiple types based on topography, edaphics (soils), vegetation, and hydrologic regime. Primarily, the Corps establishes two distinctions: wetland and nonwetland waters of the U.S. Nonwetland waters are commonly referred to as other waters of the U.S.

Potential jurisdictional wetland types mapped within the site include the following: depressional seasonal wetland and riverine seasonal wetland. Potential other waters of the U.S. mapped within the site include: intermittent drainage, pond, and perennial drainages. The characteristics of these mapped features are described below.

5.4.1 Depressional Seasonal Wetland

A total of **0.15**-acre of depressional seasonal wetland has been delineated within the site. Depressional seasonal wetlands exhibit a hydrologic regime dominated by saturation, rather than inundation. Plant species in depressional seasonal wetlands are adapted to withstand short periods of saturation or saturated soils conditions but will not withstand prolonged periods of inundation, as is common in vernal pools. Several hydrophytic and water tolerant plant species were found within the depressional seasonal wetland on the site including tall flatsedge (*Cyperus eragrostis*), curly dock (*Rumex crispus*), rabbitsfoot grass (*Polypogon monspeliensis*), Italian rye grass, Himalayan blackberry, and California blackberry. The majority of depressional seasonal wetlands are located in the southern portion of the western half of the site near Secret Ravine. In addition, one depressional season wetland is located next to Interstate 80 at the northwestern corner of the western half of the site, and another is located in the northwest portion of the eastern half of the site (**Figure 3**).

5.4.2 Riverine Seasonal Wetland

A total of **0.53**-acre of riverine seasonal wetland has been delineated within the site. Riverine seasonal wetlands are defined by a hydrologic regime dominated by unidirectional flow of water. Riverine seasonal wetlands typically occur in topographic folds or swales and represent natural drainages that convey sufficient water to support wetland vegetation. They typically convey water during and shortly after storm events. Riverine seasonal wetlands usually have a moderately defined bed and bank. As in

depressional seasonal wetlands, plant species found within riverine seasonal wetlands are typically adapted to a hydrologic regime dominated by saturation rather than inundation. Plant species observed within these features on the site include cocklebur (*Xanthium strumarium*), spearmint (*Mentha spicata*), rabbitsfoot grass, common spikerush (*Eleocharis macrostaycha*), bog yellow cress (*Rorippa palustris*), willows, valley oaks, and tall flatsedge. Riverine seasonal wetlands are located in the southern portion of the site (**Figure 3**).

5.4.3 Intermittent Drainage

A total of **0.01**-acre of intermittent drainage has been delineated within the site (**Figure 3**). Intermittent drainages, as in ephemeral drainages, are features that do not meet the three-parameter criteria for vegetation, hydrology and soils, but do convey water and exhibit an ordinary high water mark. Water flows within intermittent drainages are fed primarily by a seasonally perched groundwater table and supplemented by precipitation and stormwater runoff. After the initial onset of rains, these features have persistent flows throughout and past the end of the rainy season. Typically, these features exhibit a defined bed and bank and show signs of scouring as a result of rapid flow events. The bed of intermittent drainages consists of cobble often interrupted with bedrock. Hydrophytic vegetation may occur in association with intermittent drainages. The intermittent drainage on the site flows from the riverine seasonal wetland in the southwest corner of the project towards Secret Ravine.

5.4.4 Perennial Drainage

A total of **0.44-**acre of perennial drainage has been delineated within the site. Perennial drainages are features that may not meet the three-parameter criteria for vegetation, hydrology, and soils but do convey water and exhibit an ordinary high water mark. Perennial drainages generally convey unidirectional water flows throughout the entire year. Perennial drainages typically consist of a channel, bed, and bank and are mostly devoid of vegetation due to the scouring effect of flowing water. Perennial drainages are often bordered by wetland vegetation communities of various composition and cover depending on flow rates, duration of flows and soil types. Plants observed growing on the banks of the perennial drainage include cottonwood, white alder, valley oak, willow, California and Himalayan blackberry, and in certain sections, cattails (*Typha* sp.). Portions of the perennial drainages that occur on the site are located along the southern boundary of the western half of the site and crossing the eastern portion of the site (**Figure 3**).

5.4.5 Pond

A total of **0.01**-acre of pond has been delineated in the northeast corner of the site (**Figure 3**). The pond on the site is charged by the perennial drainage that traverses the central portion of the northern half of the site and flow east towards the west side of the pond. Ponds are often a result of the placement of a dam within jurisdictional waters, as is the suspected origin of the feature onsite. According to the supply of water from a perennial drainage that is likely jurisdictional, the close proximity of the pond to Secret

Ravine, and likelihood that pond flows into Secret Ravine; this feature would likely be subject to Corps jurisdiction.							

6.0 CONCLUSIONS

Application of routine wetland delineation techniques revealed the presence of features that appear to conform to the definition of waters of the U.S pursuant to Section 404 of the Federal Clean Water Act. Potential jurisdictional wetland types mapped within the site include depressional seasonal wetland and riverine seasonal wetland. Other waters of the U.S. delineated within the site include perennial drainage, intermittent drainage, and a pond. In addition, portions of the site nearest the perennial drainage are located within the 100-year floodplain.

The final determination of the extent of Corps' jurisdiction on the property pursuant to Section 404 of the Federal Clean Water Act will depend on the results of field verification by the Corps. Areas deemed jurisdictional will then be subject to the regulatory requirements of the federal Clean Water Act including permitting and mitigation, as required.


Table 1 below provides acreage per class and summarizes the total acreage of wetlands and waters on the site.


Table 1 — Waters of the U.S.: Acreage According to Feature Classification


Classification	Total Acreage
Depressional Seasonal Wetland	0.15
Riverine Seasonal Wetland	0.53
Intermittent Drainage	0.01
Perennial Drainage	0.44
Pond	0.01
TOTAL	1.13


- Baldwin, B.G., D.H. Goldman, D.J. Keil, R. Patterson, T.J. Rosatti, and D.H. Wilken, editors. 2012. *The Jepson manual: vascular plants of California*, second edition. University of California, Berkeley
- Environmental Laboratories. 1987. *Corps of Engineers Wetlands Delineation Manual*. U.S. Army Corps of Engineers Waterways Experiment Station. Vicksburg, MS.
- Federal Emergency Management Agency (FEMA). 1998. National Flood Insurance Program Q3 Flood Data, Disc 1: California.
- GretagMacbeth. 2000. Munsell Soil Color Charts. New Windsor, NY.
- Hitchcock, A.S. 1935. Revised 1971. *Manual of the Grasses of the United States*. U.S. Department of Agriculture, Dover Publications, NY.
- Hitchcock, L.C. and A. Cronquist. 1996. *Flora of the Pacific Northwest*. University of Washington Press, Seattle, WA.
- Jensen, S. 2006. Archaeological Inventory Survey: Turtle Island Development Project, c.60 acres at Loomis, Placer County California.
- Mason, H.L. 1957. *A Flora of the Marshes of California*. University of California Press, Berkeley, CA.
- Munz, P.A. 1968. *A California Flora and Supplement*. University of California Press, Berkeley, CA.
- Natural Resource Conservation Service (NRCS). 1980. *Soil Survey of Placer County, California*. U.S. Department of Agriculture.
- NRCS. March 1992. *Hydric Soils List for Placer County, California*. U.S. Department of Agriculture.
- NRCS. 2003. Field Indicators of Hydric Soils in the United States, Version 5.01. G.W. Hurt, P.M. Whited, and R.F. Pringle (eds). USDA, NRCS in cooperation with the National Committee for Hydric Soils. Fort Worth, TX.
- NRCS. 2010. *Field Indicators of Hydric Soils in the United States*, Version 7. G.W. Hurt, P.M. Whited, and R.F. Pringle (Eds). USDA, NRCS in cooperation with the National Committee for Hydric Soils. Fort Worth, TX
- Park Place Gardens Nursery (PPGN). *The Climate of Loomis*. Located at: http://www.ppgn.com/lolwprofile.html.

- Reed, P.B., Jr. 1988. *National List of Plant Species That Occur in Wetlands: California (Region O)*; U.S. Fish & Wildlife Service.
- Sawyer, J.O. and T. Keeler-Wolf. 1995. *A Manual of California Vegetation*. California Native Plant Society (CNPS), Sacramento, CA.
- U.S. Geological Survey (USGS). 1967 (Photorevised 1981). *Rocklin, California* 7.5-minute series topographic quadrangle. U.S. Department of the Interior.
- USGS. May 2002. Sacramento Urban 0.3-meter DOQQ Imagery. U.S. Department of the Interior.









Appendix A — Contact Information

Client Contact Information: Steve McCullagh

Oakmont Senior Living LLC 220 Concourse Boulevard Santa Rosa, CA 95403

Delineation Conducted by: Meredith Branstad, Biologist

Kirk Vail, Biologist Foothill Associates

590 Menlo Drive, Suite 5 Rocklin, CA 95765

Appendix B — Routine Wetland Determination Data Forms

Project/Site: Loomis Market Applicant/Owner: KOBRA Investigator: Elaine Flock Eric Christense	Date: 08/02/2006 County: Placer State: California						
Do Normal Circumstances exist on the site? Is the site significantly disturbed (Atypical Situation)? Is the area a potential Problem Area? (If needed, explain on reverse.) O Yes O No Community ID: UPL Transect ID: 1 Plot ID:							
VEGETATION			_				
Dominant Plant Species 1. Bromus hordeaceus (30%) 2. Torilis arvensis (30%) 3. Rubus discolor (40%) 4. Quercus douglassi (10%) 5. Quercus lobata (10%) 6. Baccharis salicifolia (10%) 7 8 Percent of Dominant Species that are (excluding FAC-). Remarks: Insufficient hydrophyte	HERB HERB SHRUB TREE TREE SHRUB OBL, FACW or	FAC	9	Stratum Indicator			
Recorded Data (Describe in Rem Stream, Lake, or Tide Gauge Aerial Photographs Vother No Recorded Data Available Field Observations: Depth of Surface Water: Depth to Free Water in Pit: Depth to Saturated Soil:		A (in.)	Wetland Hydrology Indicators: Inundated Saturated in Upp Water Marks Drift Lines Sediment Depos Drainage Pattern Secondary Indicators (2 Oxidized Root Cl Water-Stained Le Local Soil Survey FAC-Neutral Test Other (Explain in	er 12 Inches its s in Wetlands 2 or more required): hannels in Upper 12 Inches saves y Data			
Remarks: Insufficient hydrolog	y indicators.	Other: topo	graphic map.				

(Series an	Map Unit Name (Series and Phase): Andregg coarse sandy loam, 2-9% slopes Taxonomy (Subgroup): Ultic Haploxerolls Drainage Class: Well Drained Field Observations Confirm Mapped Type? O Yes No							
Profile Des Depth (inches)	cription: Horizon	Matrix Color (Munsell Moist)	Mottle Colors (Munsell Moist)	Mottle Abundance/ Size/Contrast	Texture, Concretions, Structure, etc.			
0-6	<u>A</u>	10YR 3/2	N/A	N/A	gravelly clay loam			
		() () () () () () () () () ()						
Remarks: 1	Hydric Soil Indicators: Histosol							
Hydrophyti Wetland H	Hydrophytic Vegetation Present? Wetland Hydrology Present? Hydro Soils Present? O Yes O No Hydric Soils Present? O Yes O No Is this Sampling Point Within a Wetland? O Yes O No							
Remarks: Does not meet all three wetland parameters; upland.								

Project/Site: Loomis Marketplace Applicant/Owner: KOBRA Properties Investigator: Elaine Flock Eric Christensen Do Normal Circumstances exist on the site? Is the site significantly disturbed (Atypical Situation)? Is the area a potential Problem Area? (If needed, explain on reverse.)					
HERB FACW SHRUB FACW* e OBL, FACW or FAC phytic vegetation.	9. Bromus hordeaceus 10. Lolium perenne (tr) 11. Polypogon monspeli 12. Cirsium sp. (15%) 13. Torilis arvensis (10%) 14. Rumex crispus (5%) 15.	HERB FAC* iensis (10%) HERB FACW+ HERB W) HERB UPL			
marks): ge	Wetland Hydrology Indicate Primary Indicators: Inundated Saturated in Uppe Water Marks Drift Lines Sediment Depos Drainage Pattern: Secondary Indicators (C	er 12 Inches sits is in Wetlands 2 or more required):			
N/A(in.)N/A(in.)	 ✓ Oxidized Root Channels in Upper 12 Inches ✓ Water-Stained Leaves ✓ Local Soil Survey Data ✓ FAC-Neutral Test ✓ Other (Explain in Remarks) 				
	exist on the site? urbed (Atypical Situation blem Area? erse.) Stratum Indicator HERB FACW SHRUB FACW* OBL, FACW or FAC phytic vegetation.	exist on the site? urbed (Atypical Situation)? Yes No olem Area? erse.) Stratum Indicator HERB FACW SHRUB FACW* 10. Lolium perenne (tr) 11. Polypogon monspeli 12. Cirsium sp. (15%) 13. Torilis arvensis (10%) 14. Rumex crispus (5%) 15. 16. e OBL, FACW or FAC 100 % phytic vegetation. Wetland Hydrology Indicators: Inundated Saturated in Upp Water Marks Drift Lines Secondary Indicators: Sediment Depos Drainage Pattern Secondary Indicators: Oxidized Root C			

38	d Phase): And	dregg coarse sa Ultic Haploxero	Fie	Drainage Class: Well Drained Field Observations Confirm Mapped Type? Yes O No			
Profile Des Depth (inches)	Horizon	Matrix Color (Munsell Moist)	Mottle Colors (Munsell Moist)	Mottle Abundance/ Size/Contrast	Texture, Concretion		
0-10	<u>A</u>	10YR 3/2	2.5YR 3/6	few/fine/prom	sandy clay loa	am	
□ H □ Si □ Ai □ R ☑ G	istosol stic Epipedon ulfidic Odor quic Moisture R educing Condit leyed or Low-C Sufficient hyc Soil at data po	tions Chroma Colors dric soil indicator	☐ Organic ☐ Listed o ☐ Listed o ☐ Other (rganic Content in Surface L c Streaking in Sandy Soils on Local Hydric Soils List on National Hydric Soils List explain in Remarks) with mottles. Unable to		ue to dry, 1	rocky soils.
VETLAN	D DETERM	MINATION			W-4000-01		
Wetland H	ic Vegetation P ydrology Prese ils Present?	ent? O	Yes O No Yes O No Yes O No	ls this Sampling F	Point Within a Wetland	? O Yes	O No
Remarks:	Meets all thre	ee wetland param	eters; depressional s	easonal wetland.			

Project/Site: Loomis Market Applicant/Owner: KOBRA Investigator: Elaine Flock Eric Christens	Date: 08/02/2006 County: Placer State: California		
Do Normal Circumstances Is the site significantly distu Is the area a potential Prob (If needed, explain on reve	urbed (Atypical Situatio blem Area?	● Yes ○ No n)? ○ Yes ● No ○ Yes ● No	Community ID: UPL Transect ID: 2 Plot ID: b
VEGETATION			
Dominant Plant Species 1. Bromus diandrus (40%) 2. Torilis arvensis (30%) 3. Rubus discolor (40%) 4. Quercus wislizenii (70%) 5	OBL, FACW or FAC	11	
Recorded Data (Describe in Rei Stream, Lake, or Tide Gaug Aerial Photographs Other No Recorded Data Available Field Observations: Depth of Surface Water: Depth to Free Water in Pit: Depth to Saturated Soil:	Marks): e N/A(in.)N/A(in.)N/A(in.)	Wetland Hydrology Indicate Primary Indicators: Inundated Saturated in Upp Water Marks Drift Lines Sediment Depos Drainage Pattern Secondary Indicators (2 Oxidized Root Cl Water-Stained Le Local Soil Survey FAC-Neutral Test	ner 12 Inches sits as in Wetlands 2 or more required): hannels in Upper 12 Inches eaves y Data t
Remarks: Insufficient hydrolog	gy indicators. Other: topo	ographic map.	

(Series an	Map Unit Name (Series and Phase): Andregg coarse sandy loam, 2-9% slopes Taxonomy (Subgroup): Ultic Haploxerolls Drainage Class: Well Drained Field Observations Confirm Mapped Type? • Yes							
Profile Des Depth (inches)	Horizon	Matrix Color (Munsell Moist)	Mottle Colors (Munsell Moist)	Mottle Abundance/ Size/Contrast	Texture, Concretions, Structure, etc.			
0-8	<u>A</u>	10YR 3/3	7.5YR 4/6	few/fine/prom	sandy clay loam	_		
Hydric Soil								
□ H □ Si □ Ai □ Ri	stosol stic Epipedon ulfidic Odor quic Moisture educing Cond leyed or Low-	Regime	☐ Organi ☐ Listed ☐ Listed	stions Irganic Content in Surface L ic Streaking in Sandy Soils on Local Hydric Soils List on National Hydric Soils List (Explain in Remarks)				
Remarks:]	nsufficient l	hydric soil indicat	ors. Unable to dig p	ast 8 inches due to dry, re	ocky soils.			
VETLAN	D DETER	MINATION						
Wetland H	c Vegetation ydrology Pres ls Present?	sent? C	Yes O No Yes O No Yes O No	ls this Sampling P	Point Within a Wetland? O Yes	⊙ No		
Remarks: Does not meet all three wetland parameters; upland.								
				64.		9		

Project/Site: Loomis Marketplace Applicant/Owner: KOBRA Properties Investigator: Elaine Flock Eric Christensen				
st on the site? ed (Atypical Situation n Area? .)	● Yes ○ No on)? ○ Yes ● No ○ Yes ● No	Comm Transe Plot ID	Paragraph and Angel	
HERB FAC* SHRUB FACW* TREE TREE FAC SHRUB UPL	9. Bromus hordeaceus 10. Cyperus eragrostis (1 11. Cirsium sp. (10%) 12. Quercus wislizenii (1 13.	5%)		
N/A (in.) N/A (in.) N/A (in.)	Primary Indicators: Inundated Saturated in Upp Water Marks Drift Lines Sediment Depos Drainage Pattern Secondary Indicators (3 Oxidized Root Cl Water-Stained Le Local Soil Survey FAC-Neutral Test Other (Explain in	er 12 Inche sits Is in Wetlan 2 or more re hannels in le eaves y Data t Remarks)	ds equired): Upper 12 Inches	
	Stratum Indicator HERB FAC* SHRUB FACW* TREE TREE FAC SHRUB UPL , FACW or FAC ic vegetation. Assumes.	Stratum Indicator HERB FAC* SHRUB FACW* TREE TAC SHRUB UPL SHRUB UPL SHRUB SHRUB SHRUB SPECIES SHRUB UPL SH	Stratum Indicator Associate Plant Species Plot ID Stratum Indicator HERB FAC* 9. Bromus hordeaceus (tr) TREE TREE 11. Cirsium sp. (10%) TREE FAC 12. Quercus wislizenii (5%) SHRUB UPL 13. 14. 15. 16. TREC FACW or FAC 80 9/0 Sheward of the site? Yes No No Transe Plot ID Wetland Hydrology indicators: Primary Indicators: Primary Indicators: Inundated Saturated in Upper 12 Inche Water Marks Drift Lines Drainage Patterns in Wetlan Secondary Indicators (2 or more reconded in the secondary Indicators (2 or more reconded in	

(Series an	Map Unit Name (Series and Phase): Andregg coarse sandy loam, 2-9% slopes Taxonomy (Subgroup): Ultic Haploxerolls Drainage Class: Well Drained Field Observations Confirm Mapped Type? O Yes No								_ ⊙ №
Profile Des Depth (inches) 0-6 6-10	Horizon A A	Matrix Color (Munsell Moist) 10YR 2/1 10YR 4/1	M)	ottle Colors unsell Moist) N/A 7.5YR 5/6	Mottle Abundance/ Size/Contrast N/A comm/med/pror		sandy clay l	loam	
H H H S S S S S S S S S S S S S S S S S	Hydric Soil Indicators: Histosol								
WETLAN	D DETER	MINATION							
Wetland H	Hydrophytic Vegetation Present? Wetland Hydrology Present? Hydric Soils Present? O Yes O No Hydric Soils Present? O Yes O No Is this Sampling Point Within a Wetland? O Yes O No								
Remarks:	Remarks: Meets all three wetland parameters; riverine seasonal wetland.								

Project/Site: Loomis Marketp Applicant/Owner: KOBRA F Investigator: Elaine Flock Eric Christense Do Normal Circumstances et Is the site significantly distur Is the area a potential Proble (If needed, explain on revers	Date:08/02/2006 County: Placer State:California Community ID:UPL Transect ID:3 Plot ID:b		
VEGETATION			
Dominant Plant Species 1. Cirsium sp. (50%) 2. Torilis arvensis (20%) 3. Rubus discolor (20%) 4. Quercus wislizenii (10%) 5. Salix sp. (10%) 6. Toxocodendron divers. (10%) 7	DBL, FACW or FAC	9	Stratum Indicator
Recorded Data (Describe in Remal Stream, Lake, or Tide Gauge Aerial Photographs Other No Recorded Data Available Field Observations: Depth of Surface Water: Depth to Free Water in Pit: Depth to Saturated Soil: Remarks: Insufficient hydrology	N/A(in.)N/A(in.)	☐ Water-Stained L ☐ Local Soil Surve ☐ FAC-Neutral Tes ☐ Other (Explain in	per 12 Inches sits ns in Wetlands (2 or more required): Channels in Upper 12 Inches eaves by Data st n Remarks)

13	d Phase): <u>An</u>	dregg coarse san Ultic Haploxerol	dy loam, 2-9% s ls	Fie	ainage Class: Well Drained eld Observations onfirm Mapped Type? O Yes No	
Profile Des Depth (inches)	Horizon A	Matrix Color (Munsell Moist) 10YR 2/1	Mottle Colors (Munsell Moist) N/A	Mottle Abundance/ Size/Contrast N/A	Texture, Concretions, Structure, etc. sandy clay loam	
Hydric Soil Indicators: Histosol						
VETLAN Hydrophyti	D DETERNIC Vegetation P	IIINATION	act match of mapp	ed soils.		
Wetland Hydrology Present? O Yes O No Hydric Soils Present? O Yes O No Is this Sampling Point Within a Wetland? O Yes O No Remarks: Does not meet all three wetland parameters; upland.						

Project/Site: Loomis Marke Applicant/Owner: KOBRA Investigator: Elaine Flock Eric Christens	Date: 08/02/2006 County: Placer State: California					
Do Normal Circumstances exist on the site? Is the site significantly disturbed (Atypical Situation)? Is the area a potential Problem Area? (If needed, explain on reverse.) O Yes O No O Yes O No						
VEGETATION						
Dominant Plant Species 1. Lolium perenne (80%) 2. Rubus discolor (10%) 3. Quercus lobata (15%) 4. Quercus wislizenii (10%) 5	OBL, FACW or FAC	12 13 14 15				
Recorded Data (Describe in Rer Stream, Lake, or Tide Gaug Aerial Photographs Other No Recorded Data Available Field Observations: Depth of Surface Water: Depth to Free Water in Pit: Depth to Saturated Soil:		Wetland Hydrology Indicators: Primary Indicators: Inundated Saturated in Uppe Water Marks Drift Lines Sediment Deposi Drainage Patterns Secondary Indicators (2 Oxidized Root Cr Water-Stained Le Local Soil Survey FAC-Neutral Test Other (Explain in	er 12 Inches its s in Wetlands or more required): nannels in Upper 12 Inches aves Data			
Remarks: Sufficient hydrology indicate water pools attached riverine sea	within feature. Feature is	C-neutral test. Other: tops depressional in shape. V	ographic map. Cracks in soil Water appears to flow into			

(Series and	Map Unit Name (Series and Phase): Andregg coarse sandy loam, 2-9% slopes Taxonomy (Subgroup): Ultic Haploxerolls Drainage Class: Well Drained Field Observations Confirm Mapped Type? O Yes										
Taxonomy	(Subgroup): _	Onic Haploxelo	Co	nfirm Mapped Type? Yes	⊙ No						
Profile Des Depth (inches)	cription: Horizon	Matrix Color (Munsell Moist)	Mottle Colors (Munsell Moist)	Mottle Abundance/ Size/Contrast	Texture, Concretions, Structure, etc.						
0-10	<u>A</u>	10YR 3/1	7.5YR 4/6	comm/med/prom	sandy clay loam	_					
			-5								
□ Hi □ Hi □ St □ Ad	Hydric Soil Indicators: Histosol										
Remarks: g	Sufficient hyd o dig past 10	dric soil indicators inches due to dry	- low chroma soil wi , rocky soils. Soil at o	th mottles. Also obser data point similar, but i	rved soft manganese concretions not an exact match of mapped so	. Unable pils.					
VETLANI	D DETERN	/INATION									
Wetland Hy	Hydrophytic Vegetation Present?										
Remarks:	Meets all thr	ee wetland param	eters; depressional sea	sonal wetland.							

Project/Site: Loomis Marke Applicant/Owner: KOBRA Investigator: Elaine Flock Eric Christens	Date: 08/02/2006 County: Placer State: California		
Do Normal Circumstances Is the site significantly distu Is the area a potential Prot (If needed, explain on reve	urbed (Atypical Situation blem Area?	● Yes ○ No ○ Yes ● No ○ Yes ● No	Community ID: UPL Transect ID: 4 Plot ID: b
VEGETATION			
Dominant Plant Species 1. Torilis arvensis (40%) 2. Rubus discolor (20%) 3. Quercus wislizenii (30%) 4. Bromus diandrus (20%) 5. Cirsium sp. (20%) 6	OBL, FACW or FAC	1213141516	HERB FACW-TREE FAC
Recorded Data (Describe in Recorded Data (Describe in Recorded Data (Describe in Recorded Data Photographs of Other No Recorded Data Available Field Observations: Depth of Surface Water: Depth to Free Water in Pit: Depth to Saturated Soil:		Wetland Hydrology Indicate Primary Indicators: Inundated Saturated in Upp Water Marks Drift Lines Sediment Depos Drainage Pattern Secondary Indicators (2 Oxidized Root Cl Water-Stained Le Local Soil Survey FAC-Neutral Test Other (Explain in	er 12 Inches its s in Wetlands 2 or more required): hannels in Upper 12 Inches saves y Data
Remarks: Insufficient hydrolog	gy indicators. Does not pa	ass FAC-neutral test. Oth	her: topographic map.

	d Phase): An	dregg coarse Ultic Haploxe		oam, 2-9% s	slopes		Field (ge Class: We Observations m Mapped Type?	Il Drained O Yes	O No
Profile Des Depth (inches)	Horizon A	Matrix Color (Munsell Moist) 10YR 3/2) (Mu	ttlle Colors insell Moist) 5YR 5/8		lottle Abundance/ ize/Contrast comm/med/pro	om	Texture, Concret Structure, etc. sandy clay l	0.000.000	
H H H S S G R G R G R G R G R G R G R G R G R	Hydric Soil Indicators: Histosol									
VETLAN	D DETERN	MINATION								
Wetland H	ic Vegetation P ydrology Prese ils Present?	ent?	O Yes O Yes O Yes	O No O No O No		ls this Samplin	ng Poin	t Within a Wetlar	id? O Yes	⊙ No
Remarks: Does not meet all three wetland parameters; upland.										

Project/Site: Loomis Marketpl Applicant/Owner: KOBRA Pr Investigator: Elaine Flock Eric Christensen Do Normal Circumstances ex Is the site significantly disturb Is the area a potential Proble (If needed, explain on reverse	Date: 08/02/2006 County: Placer State: California Community ID: RSW Transect ID: 5 Plot ID:		
	SHRUB FACW* HERB OBL	9. Unknown grass (10 10	
Recorded Data (Describe in Rema Stream, Lake, or Tide Gauge Aerial Photographs Other No Recorded Data Available Field Observations: Depth of Surface Water: Depth to Free Water in Pit: Depth to Saturated Soil: Remarks: Sufficient hydrology in indicate water pools with the stream of the surface water pools with the surfa	N/A (in.) N/A (in.) N/A (in.)	Water-Stained I Local Soil Surve FAC-Neutral Tee Other (Explain i	per 12 Inches sits ns in Wetlands (2 or more required): Channels in Upper 12 Inches Leaves ey Data st in Remarks)

	nd Phase): <u>An</u>	dregg coarse sar Ultic Haploxero	rainage Class: Well ided Observations onfirm Mapped Type?	Drained O Yes	_ ⊙ №		
Profile Des Depth (inches)	scription;	Matrix Color (Munsell Moist)	Mottle Colors (Munsell Moist)	Mottle Abundance/ Size/Contrast	Texture, Concretic	ons,	
0-10	<u>A</u>	10YR 3/1	7.5YR 4/6	comm/med/prom	sandy clay lo	am	
□ A □ R ☑ G	Sufficient hy	itions Chroma Colors dric soil indicators	☐ Orgai ☐ Listec ☐ Listec ☐ Other	Organic Content in Surface I nic Streaking in Sandy Soils d on Local Hydric Soils List d on National Hydric Soils List c (Explain in Remarks) I with mottles. Also obse at data point similar, but	erved soft manganese	concretion of mapped	s. Unable soils.
	D DETERM	MINATION Present? 0	Yes O No	Т			
	lydrology Prese ils Present?		Yes O No Yes O No	Is this Sampling	Point Within a Wetland	? • Yes	O No
Remarks:	Meets all thr	ee wetland param	eters; riverine seaso	onal wetland.			

Project/Site: Loomis Market Applicant/Owner: KOBRA Investigator: David Bise Eric Christense	Date: 08/07/2006 County: Placer State: California		
Do Normal Circumstances of Is the site significantly disturn Is the area a potential Probatily (If needed, explain on rever	on)? ○ Yes ○ No ○ Yes ○ No ○ Yes ○ No	Community ID: DSW Transect ID: 6 Plot ID: a	
VEGETATION			
Dominant Plant Species 1. Cynodon dactylon (65%) 2. Querçus wislizenii (20%) 3. Rubus discolor (5%) 4 5 6 7 8 Percent of Dominant Species that are (excluding FAC-). Remarks: Sufficient hydrophytic	OBL, FACW or FAC	14 15	HERB FACW-
Recorded Data (Describe in Ren Stream, Lake, or Tide Gauge Aerial Photographs Other No Recorded Data Available Field Observations: Depth of Surface Water: Depth to Free Water in Pit: Depth to Saturated Soil:	N/A (in.) N/A (in.) N/A (in.)	✓ Water-Stained Le Local Soil Survey ✓ FAC-Neutral Test Other (Explain in	er 12 Inches its s in Wetlands 2 or more required): hannels in Upper 12 Inches eaves y Data t Remarks)
Remarks: Sufficient hydrology leaves. Other: topogr		vithin a topographic depres	ssion containing water-stained

	nd Phase): X_0	erorthents, cut a	Fie	ainage Class: Variable eld Observations onfirm Mapped Type? Yes	No					
Profile De Depth (inches)	escription: Horizon	Matrix Color (Munsell Moist)	Mottle Colors (Munsell Moist)	Mottle Abundance/ Size/Contrast	Texture, Concretions, Structure, etc.	2.8				
0-6	A	7.5YR 4/2	5YR 5/6	many/med/prom	sandy loam					
	Hydric Soil Indicators: Histosol									
ETLAN	D DETER	MINATION			_					
Wetland F	Hydrophytic Vegetation Present? O Yes O No Wetland Hydrology Present? O Yes O No Hydric Soils Present? O Yes O No Is this Sampling Point Within a Wetland? O Yes O No									
Remarks:	Meets all the	ree wetland parar	neters; depressional	seasonal wetland.						

Project/Site: Loomis Marketplace Applicant/Owner: KOBRA Properties Investigator: David Bise Eric Christensen Do Normal Circumstances exist on the site? Is the site significantly disturbed (Atypical Situation) Is the area a potential Problem Area? (If needed, explain on reverse.)	Date:08/07/2006 County: Placer State:California Community ID:UPL Transect ID:6 Plot ID:b	
VEGETATION		
Dominant Plant Species 1. Centaurea solstitialis (50%) 2. Centromadia pungens (30%) 3. HERB FAC 3.	12 13 14 15	
HYDROLOGY Recorded Data (Describe in Remarks): Stream, Lake, or Tide Gauge Aerial Photographs Other No Recorded Data Available Field Observations: Depth of Surface Water: Depth to Free Water in Pit: N/A (in.) Depth to Saturated Soil: Remarks: Insufficient hydrology indicators. Other: topog		er 12 Inches its s in Wetlands ? or more required): nannels in Upper 12 Inches naves

(Series and	Map Unit Name (Series and Phase): Andregg coarse sandy loam, 2-9% slopes Taxonomy (Subgroup): Ultic Haploxerolls Drainage Class: Field Observations Confirm Mapped Type? Yes • No										
Profile Description: Depth Matrix Color Mottle Colors Mottle Abundance/ Texture, Concretions, (inches) Horizon (Munsell Moist) (Munsell Moist) Size/Contrast Structure, etc.											
0-8	<u>A</u>	10YR 3/3		N/A	N/A		sandy loam				
						_					
Remarks: I	Hydric Soil Indicators: Histosol										
Hydrophytic Wetland Hy	Hydrophytic Vegetation Present? Wetland Hydrology Present? O Yes No Hydric Soils Present? O Yes No Is this Sampling Point Within a Wetland? O Yes No										
Remarks:	Remarks: Does not meet all three wetland parameters; upland.										

Project/Site: Loomis Market Applicant/Owner: KOBRA Investigator: Eric Christense	Date: 09/20/2006 County: Placer State: California		
Do Normal Circumstances of Is the site significantly disturbed in the area a potential Prob (If needed, explain on rever	rbed (Atypical Situation lem Area?	● Yes ○ No ∩ Yes ● No ○ Yes ● No	Community ID: UPL Transect ID: 7 Plot ID:
EGETATION			
Dominant Plant Species	Stratum Indicator	Associate Plant Species	Stratum Indicator
1. Torilis arvensis (30%)	HERB UPL	9. Toxicodendron dive	
2. Cynosurus echinatus (40%)			
3. Bromus diandrus (25%)	HERB NI	11	
4. Quercus wislizenii (80%)	TREE UPL	1,171,1-0.	
5		1.075/201	
6			
7		11.55.4	
8		16	
Remarks: Insufficient hydrophy	tic vegetation.		
YDROLOGY			
Recorded Data (Describe in Ren Stream, Lake, or Tide Gauge Aerial Photographs Other No Recorded Data Available		Wetland Hydrology Indica Primary Indicators: Inundated Saturated in Upp Water Marks Drift Lines	per 12 Inches
Field Observations:		Sediment Depos Drainage Pattern Secondary Indicators (ns in Wetlands
Depth of Surface Water:	N/A(in.)	☐ Oxidized Root C	Channels in Upper 12 Inches
Depth to Free Water in Pit:	N/A(in.)	Water-Stained L Local Soil Surve FAC-Neutral Tes	ey Data St
Depth to Saturated Soil:	N/A(in.)	Other (Explain in	n Remarks)
Remarks: Insufficient hydrolog	y indicators. Other: topo	ographic map.	

	nd Phase): <u>Ar</u>	ndregg coarse sar Ultic Haploxero	Fi	rainage Class: Well Drained lield Observations O Yes	 ⊙ №					
Profile De Depth (inches)	scription: Horizon	Matrix Color (Munsell Moist)	Mottle Colors (Munsell Moist)	Mottle Abundance/ Size/Contrast	Texture, Concretions, Structure, etc.					
0-18	A	7.5YR 3/3	N/A	N/A	sandy loam					
-										
□ H □ H □ S □ R □ G	Hydric Soil Indicators: Histosol									
Hydrophyt Wetland H	Hydrophytic Vegetation Present? O Yes O No Wetland Hydrology Present? O Yes O No Hydric Soils Present? O Yes O No Is this Sampling Point Within a Wetland? O Yes O No									
Remarks: Does not meet all three wetland parameters; upland.										

Project/Site: Loomis Marketp Applicant/Owner: KOBRA P Investigator: Eric Christenser	County:	09/20/2006 Placer California						
Do Normal Circumstances ex Is the site significantly disturb Is the area a potential Proble (If needed, explain on revers	Commu Transec Plot ID:	nity ID: Rip Wet t ID: 8 a						
VEGETATION								
Dominant Plant Species Stratum Indicator 1. Xanthium strumarium (25%) HERB FAC+ 1. Xanthium strumar								
Recorded Data (Describe in Remarks): Stream, Lake, or Tide Gauge Inundated Saturated in Upper 12 Inches Water Marks Drift Lines Sediment Deposits Drainage Patterns in Wetlands Secondary Indicators (2 or more required): Oxidized Root Channels in Upper 12 Inches Water-Stained Leaves Drift Lines Coxidized Root Channels in Upper 12 Inches Water-Stained Leaves Drift Lines Coxidized Root Channels in Upper 12 Inches Rocket Root Channels in Upper 12 Inches Water-Stained Leaves Drift Lines Coxidized Root Channels in Upper 12 Inches Water-Stained Leaves Drift Lines Coxidized Root Channels in Upper 12 Inches Coxidized Root Channels								
Remarks: Sufficient hydrology i	ndicators.	Satisfies FAC	C-neutral test. Other: top	ographic	map.			

Depth (inches)	Scription: Horizon	Matrix Color (Munsell Moist)	Mottle Colors (Munsell Moist)	Mottle Abundance/ Size/Contrast	Texture, Concretions, Structure, etc.	_
0-3	<u>A</u>	10YR 4/1	5YR 5/8	many/coarse/prom.	sandy clay loam	
4-8	A	10YR 4/2	2.5YR 3/4	many/coarse/prom.	sandy clay	
		_	-		6. 9 	
		_	-X A		K 3 <u></u>	
		-			20 A	
lydric Soil	Indicators:					
	istosol istic Epipedo	n	☑ Concre	etions rganic Content in Surface Laye	ar in Sandy Soile	
□s	ulfidic Odor quic Moisture		Organi	c Streaking in Sandy Soils on Local Hydric Soils List	ar iii Sandy Soiis	
□R	educing Con		☐ Listed	on National Hydric Soils List (Explain in Remarks)		
	icycu or Low	-Cirona Colors	U Other (Explain in Remarks)		
					black concretions believed to	

WETLAND DETERMINATION

Hydrophytic Vegetation Present? Wetland Hydrology Present? Hydric Soils Present?	• Yes • Yes • Yes	O No O No O No	Is this Sampling Point Within a Wetland?
Remarks: Meets all three wetland	parameters	; riparian wetla	nd.
			9

Project/Site: Loomis Market Applicant/Owner: KOBRA Investigator: Eric Christens	Date: 09/20/2006 County: Placer State: California				
Do Normal Circumstances of Is the site significantly disturble the area a potential Prob (If needed, explain on rever	rbed (Atypical Situation lem Area?	● Yes ○ No n)? ○ Yes ● No ○ Yes ● No	Commul Transect Plot ID:	t ID:	UPL B
Dominant Plant Species 1. Torilis arvensis (20%) 2. Cynosurus echinatus (20%) 3. Quercus wislizenii (20%) 4. Rubus discolor (5%) 5. Salix sp. (10%) 6. 7. 8. Percent of Dominant Species that are (excluding FAC-). Remarks: Insufficient hydrophy	OBL, FACW or FAC	Associate Plant Species 9. Mentha spicata (1%) 10. Bromus diandrus (15 11. Polypogon monspelie 12. Hordeum murinum (13. Lolium perenne (10% 14 15 16 40 % g Salix species is FAC or	%) ensis (1%) 15%) 6)	HERB HERB	-
PROLOGY Recorded Data (Describe in Render Stream, Lake, or Tide Gauge Aerial Photographs Other No Recorded Data Available Field Observations: Depth of Surface Water: Depth to Free Water in Pit: Depth to Saturated Soil:		Wetland Hydrology Indicator Primary Indicators: Inundated Saturated in Uppo Water Marks Drift Lines Sediment Deposi Drainage Patterns Secondary Indicators (2 Oxidized Root Cl Water-Stained Le Local Soil Survey FAC-Neutral Test Other (Explain in	er 12 Inches its s in Wetlands or more req nannels in Up naves Data	uired):	nes
Remarks: Insufficient hydrolog	y indicators. Other: topo	ographic map.			

SOILS Map Unit Name (Series and Phase): Xerorthents, Placer Areas Drainage Class: D Field Observations Confirm Mapped Type? Taxonomy (Subgroup): Xerorthents Yes O No Profile Description: Depth (inches) Horizon Matrix Color (Munsell Moist) Mottle Colors Mottle Abundance/ Texture, Concretions, Horizon (Munsell Moist) Size/Contrast Structure, etc. 0 - 4A 10YR 3/2 7.5YR 4/4 comm/fine/prom loamy sand 5-12 10YR 3/2 7.5YR 2.5/3 comm/med/prom sandy clay loam Hydric Soil Indicators: ☐ Histosol □ Concretions □ High Organic Content in Surface Layer in Sandy Soils □ Organic Streaking in Sandy Soils Concretions ☐ Histic Epipedon ☐ Sulfidic Odor ☐ Aquic Moisture Regime ☐ Reducing Conditions ☑ Gleyed or Low-Chroma Colors ☐ Listed on Local Hydric Soils List ☐ Listed on National Hydric Soils List☐ Other (Explain in Remarks) Remarks: Sufficient hydric soil indicators - low chroma soil with mottles.

WETLAND DETERMINATION

Hydrophytic Vegetation Present? Wetland Hydrology Present? Hydric Soils Present?	O Yes O Yes O Yes	O No O No O No	ls this Sampling Point Within a Wetland?	O Yes	⊙ No
Remarks: Does not meet all three	wetland par	ameters; upland	1.	N	
9					

WETLAND DETERMINATION DATA FORM – Arid West Region

Project/Site: 6201 Horseshoe Bar Road		City/County:	Loomis/F	Placer Sam	pling Date: 11/19/2013	
Applicant/Owner: Tulip Asset LLC						
Investigator(s): Kirk Vail Section, Township, Range: 510, T11N, R7E Rocklin, California USGS 7.5-minute quadrangle						
Landform (hillslope, terrace, etc.): Terrace						
Subregion (LRR): C						
Soil Map Unit Name: Xerorthents, placer areas						
Are climatic / hydrologic conditions on the site typical for this						
Are Vegetation, Soil, or Hydrologysi			Are "	Normal Circumstances" preser	nt? Yes ✓ No	
Are Vegetation, Soil, or Hydrology no				eded, explain any answers in f		
SUMMARY OF FINDINGS – Attach site map s			\$2000 C			
Hydrophytic Vegetation Present? Hydric Soil Present? Wetland Hydrology Present? Remarks: Wetland is a four foot strip along both ban		withi		nd? Yes✓_	No	
VEGETATION – Use scientific names of plant	ts.					
	Absolute	Dominant Species 2		Dominance Test workshee		
Tree Stratum (Plot size:) 1. n/a		Species?		Number of Dominant Specie That Are OBL, FACW, or FA		
2.						
3.				Total Number of Dominant Species Across All Strata:	1 (B)	
4.				Percent of Dominant Specie	ie.	
		= Total Co	ver	That Are OBL, FACW, or FA	AC: <u>100</u> (A/B)	
Sapling/Shrub Stratum (Plot size:)				Prevalence Index workshe	et:	
1. <u>n/a</u>				Total % Cover of:		
2				OBL species 50		
3				FACW species 7		
5				FAC species 0		
J.		= Total Co		FACU species 0		
Herb Stratum (Plot size:)	70			UPL species 0	_ x 5 =0	
1. Persicaria punctata	10	N	OBL_	Column Totals:57	_ (A) <u>64</u>	
2. <u>Leersia orycoides</u>			OBL	Prevalence Index = B	/Δ = 1.1	
3. Juncus balticus			FACW	Hydrophytic Vegetation In		
4. Cyperus eragrostis			FACW FACW	✓ Dominance Test is >50°		
5. Verbena bonariensis			(A	✓ Prevalence Index is ≤3.		
6				Morphological Adaptation	ons ¹ (Provide supporting	
8.				data in Remarks or o	on a separate sheet)	
0		= Total Co	ver	Problematic Hydrophytic	c Vegetation' (Explain)	
Woody Vine Stratum (Plot size:)		- 2008000000		1		
1			-	¹ Indicators of hydric soil and be present, unless disturbed	d or problematic.	
2			·		**************************************	
		_ = Total Co		Hydrophytic Vegetation	9	
% Bare Ground in Herb Stratum % Cove	r of Biotic C	rust		Present? Yes	<u>√No</u>	
Remarks:						

Profile Des	crintion: (Describe to	the depth needed to doc	umant tha ladiantas			Sampling Point: 9a		
Depth	Matrix			or contin	m the absence	of indicators.)		
(inches)	Color (moist)	% Color (moist)	dox Features%Type ¹	Loc ²	Texture	Remarks		
0-12	10YR 4/1	00 10YR 4/6		PL		Tierrang		
		2011. 1/0			Sandy Class			
	4. 				. (4			
	(i)				• ×	6		
					 			
	** 							
	88 8			W <u> </u>	-			
	u.							
				/ii				
¹ Type: C=C	concentration, D=Depleti	on, RM=Reduced Matrix, (CS=Covered or Coate	ed Sand G	Grains. ² Loca	ation: PL=Pore Lining, M=Matrix.		
		e to all LRRs, unless oth	erwise noted.)		Indicators 1	for Problematic Hydric Soils ³ :		
Histoso	8 6	Sandy Re			1 cm Muck (A9) (LRR C)			
	pipedon (A2)	Stripped N	N. 17 (18 18 18 18 18 18 18 18 18 18 18 18 18 1			uck (A10) (LRR B)		
	listic (A3)		ucky Mineral (F1)		Reduced Vertic (F18)			
	en Sulfide (A4)		eyed Matrix (F2)			rent Material (TF2)		
	d Layers (A5) (LRR C)	<u> ✓</u> Depleted			Other (E	Explain in Remarks)		
	uck (A9) (LRR D)		rk Surface (F6)					
	d Below Dark Surface (A ark Surface (A12)		Dark Surface (F7)		3			
	Mucky Mineral (S1)		pressions (F8)	9		of hydrophytic vegetation and		
	Gleyed Matrix (S4)	Vernal Po	ols (F9)			ydrology must be present,		
	Layer (if present):				unless dis	sturbed or problematic.		
	anyor (ii proceing.							
0.0000000000000000000000000000000000000					1			
	ches):				Hydric Soil F	Present? Yes <u>√</u> No		
Remarks:					-97			
YDROLO	GY							
	drology Indicators:							
		equired; check all that app	ah A		0	1 3 30 1		
	Water (A1)		Nijiti, eta			lary Indicators (2 or more required)		
- Comment Sent and		Salt Crus	The state of the s			ater Marks (B1) (Riverine)		
	ater Table (A2)	Biotic Cru				diment Deposits (B2) (Riverine)		
Saturation			nvertebrates (B13)			ft Deposits (B3) (Riverine)		
	larks (B1) (Nonriverine)		Sulfide Odor (C1)			ainage Patterns (B10)		
	nt Deposits (B2) (Nonriv		Rhizospheres along I	9.75	ots (C3) Dry	y-Season Water Table (C2)		
Drift Der	oosits (B3) (Nonriverine	Presence	of Reduced Iron (C4)	Cre	ayfish Burrows (C8)		
	Soil Cracks (B6)			,	018	aynon burrows (OO)		

Surface Soil Cracks (B Inundation Visible on A Water-Stained Leaves	6) Aerial Imagery (B7)	Recent Iron Reduction in Tilled Thin Muck Surface (C7) Other (Explain in Remarks)	Soils (C6) Saturation Visible on Aerial Imagery (C9) Shallow Aquitard (D3) FAC-Neutral Test (D5)
Field Observations: Surface Water Present?	Yes No	o✓_ Depth (inches):	
Water Table Present?	Yes No	o Depth (inches):	
Saturation Present? (includes capillary fringe)	Yes No	o Depth (inches):	Wetland Hydrology Present? Yes _ ✓ No
Describe Recorded Data (s	tream gauge, monit	itoring well, aerial photos, previous insp	ections), if available:
Remarks:			
Adjacent to perenni	al stream prov	vides frequent source of wate	er.

WETLAND DETERMINATION DATA FORM – Arid West Region

Project/Site: 6201 Horseshoe Bar Road	(City/County	: Loomis/F	Placer Sampling Date: <u>11/19/201</u> :
				State: CA Sampling Point: 9b
Investigator(s): Kirk Vail				
Landform (hillslope, terrace, etc.): Terrace				
				Long: -121.18547 Datum: NAD 83
Soil Map Unit Name: Xerorthents, placer areas				
Are climatic / hydrologic conditions on the site typical for th				
Are Vegetation, Soil, or Hydrology				"Normal Circumstances" present? Yes No
Are Vegetation, Soil, or Hydrology				eeded, explain any answers in Remarks.)
SUMMARY OF FINDINGS – Attach site map			270,000,000	
	10			
Hydrophytic Vegetation Present? Hydric Soil Present? Yes N			e Sampled	
Hydric Soil Present? Yes Wetland Hydrology Present? Yes ✓ N		2000000		nd? Yes No/
Remarks:				
This area considered riparian wetland in 20	007. Valle	v oak an	d Himala	ivan blackberry indicator status changed to
FACU. Therefore, dominant vegetation is n	o longer h	nydroph	vtic.	,,,
generalistics and secretaristic personal and described an experience of the contract of the co				
VEGETATION – Use scientific names of plan		Deminent	Indicator	Dominance Test worksheet:
Tree Stratum (Plot size:)	Absolute % Cover		Indicator Status	Number of Dominant Species
		Υ		That Are OBL, FACW, or FAC:1 (A)
2. Quercus lobata	10	Y	FACU	Total Number of Dominant
3. Quercus wislizeni		N	UPL	Species Across All Strata:6 (B)
4				Percent of Dominant Species
Sapling/Shrub Stratum (Plot size:)	52	= Total Co	over	That Are OBL, FACW, or FAC:16 (A/B)
1. Rubus armenicus	60	Υ	FACU	Prevalence Index worksheet:
2. Phytolacca americana	MAY			Total % Cover of: Multiply by:
3		1 20		OBL species x 1 =
4				FACW species <u>40</u> x 2 = <u>80</u>
5		0.		FAC species 2 x 3 = 6
Harb Stratum (Diet size:	62	= Total Co	over	FACU species 80 x 4 = 320 UPL species 12 x 5 = 60
Herb Stratum (Plot size:) 1. Bromus diandrus	3	Υ	UPL	UPL species 12
Torilis arvensis			UPL	Column Totals. 134 (A) 400 (B)
3. Toxicodendron diversiloba	5	Y		Prevalence Index = B/A =3.47
4				Hydrophytic Vegetation Indicators:
5				Dominance Test is >50%
6		-		Prevalence Index is ≤3.0¹
7		-		Morphological Adaptations ¹ (Provide supporting data in Remarks or on a separate sheet)
8				Problematic Hydrophytic Vegetation ¹ (Explain)
Woody Vine Stratum (Plot size:)	60	_ = Total C	over	
1				¹Indicators of hydric soil and wetland hydrology must
2				be present, unless disturbed or problematic.
	-	_ = Total C	over	Hydrophytic Vegetation
% Bare Ground in Herb Stratum % Cov	er of Biotic C	rust		Present? Yes No/_
Remarks:		115		

Profile Des	cription: (Describe	to the dep	th needed to docu	ment the	indicator	or confin	m the absence o	f indicators.)
Depth	Matrix			ox Feature				
(inches)	Color (moist)	%	Color (moist)	%	Type ¹	_Loc ²	Texture	Remarks
0-12	10YR 4/1	95	10YR 4/6	5	RM	_PL	sandy clan	
						-		
Hydric Soil	oncentration, D=Dep	oletion, RM=	Reduced Matrix, C	S=Covere	ed or Coate	d Sand G		ion: PL=Pore Lining, M=Matrix. or Problematic Hydric Soils ³ :
Black H Hydrog Stratifie	pipedon (A2) istic (A3) en Sulfide (A4) d Layers (A5) (LRR (C)	Sandy Red Stripped M Loamy Mu Loamy Gle Depleted M	atrix (S6) cky Miner yed Matrix fatrix (F3)	al (F1) x (F2)		2 cm Mu Reduced Red Pare	ck (A9) (LRR C) ck (A10) (LRR B) Vertic (F18) ent Material (TF2) kplain in Remarks)
Deplete Thick D Sandy I Sandy 0	uck (A9) (LRR D) d Below Dark Surfac ark Surface (A12) Mucky Mineral (S1) Gleyed Matrix (S4)	e (A11)	Redox Dar Depleted D Redox Dep Vernal Poo	ark Surfa ressions	ce (F7)		wetland hy	hydrophytic vegetation and drology must be present, urbed or problematic.
Туре:	Layer (if present):							
Remarks:					*		Hydric Soil Pi	resent? Yes <u>√</u> No
YDROLO	GV							
	drology Indicators:							
Primary Indi	cators (minimum of o			Mariana -				ary Indicators (2 or more required)
High Wa Saturati Water N Sedimer Drift De Surface Inundati Water-S	larks (B1) (Nonriver int Deposits (B2) (Non posits (B3) (Nonriver Soil Cracks (B6) on Visible on Aerial I tained Leaves (B9)	nriverine) rine)	Salt Crust Biotic Crust Aquatic In Hydrogen Oxidized F Presence Recent Iro Thin Muck Other (Exp	st (B12) vertebrate Sulfide O Rhizosphe of Reduct in Reducti	dor (C1) eres along I ed Iron (C4 ion in Tilled (C7))	Sed	er Marks (B1) (Riverine) iment Deposits (B2) (Riverine) Deposits (B3) (Riverine) nage Patterns (B10) Season Water Table (C2) rfish Burrows (C8) aration Visible on Aerial Imagery (C9) llow Aquitard (D3) -Neutral Test (D5)
Field Obser Surface Wat Water Table Saturation Princledes car	er Present? Yeresent? Yeresent? Yeresent?	es N	No ✓ Depth (in Depth (in ✓ Depth (in	ches):		 Wetl:	and Hydrology P	resent? Yes ✓ No

(includes capillary fringe)

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:

WETLAND DETERMINATION DATA FORM – Arid West Region

Project/Site: 6201 Horseshoe Bar Road		city/County:	Loomis/F	Placer Sampling Date: 11/19/2013
				State: CA Sampling Point: 10
Investigator(s): Kirk Vail				
Landform (hillslope, terrace, etc.): Terrace				
				Long: <u>-121.18668</u> Datum: <u>NAD 83</u>
				NWI classification: Upland
Are climatic / hydrologic conditions on the site typical for this				
Are Vegetation, Soil, or Hydrologysi				"Normal Circumstances" present? Yes✓ No
Are Vegetation, Soil, or Hydrology no			i .	eded, explain any answers in Remarks.)
SUMMARY OF FINDINGS – Attach site map			42 3 00000	
		1		
Hydrophytic Vegetation Present? Yes No		Is the	e Sampled	2
		with	in a Wetlan	nd? Yes No ✓
Remarks:				
This area considered riparian wetland in 200	17 Valley	oak and	d Himala	van blackberry indicator status changed to
FACU, therefore dominant vegetation is no				, a J
DAVID PARK RESPECTED A 229 CO AND CONTRACTOR OF THE ACCOUNT OF	223			
VEGETATION – Use scientific names of plant		Dominant	Indicator	Dominance Test worksheet:
Tree Stratum (Plot size:)	Absolute % Cover			Number of Dominant Species
1. Salix laevigata	15	<u>Y</u>	FACW	That Are OBL, FACW, or FAC:1 (A)
2. Quercus lobata	30	Y	_FACU_	Total Number of Dominant
Quercus wislizeni	5	N	UPL	Species Across All Strata:6 (B)
4				Percent of Dominant Species
Sapling/Shrub Stratum (Plot size:)	50	= Total Co	ver	That Are OBL, FACW, or FAC:16 (A/B)
1. Rubus armenicus	30	Y	_FACU_	Prevalence Index worksheet:
2. Phytolacca americana		N		Total % Cover of: Multiply by:
3				OBL species x 1 =
4				FACW species 15 x 2 = 30
5				FAC species 3 x 3 = 9
Herb Stratum (Plot size:)	33	= Total Co	ver	FACU species 60 x 4 = 240 UPL species 17 x 5 = 60
1. Bromus diandrus	2	Υ	UPL	Column Totals: 95 (A) 466 (B)
2. Torilis arvensis	5	Υ	UPL	100
3. Toxicodendron diversiloba	5	Y	UPL	Prevalence Index = B/A = 3.56
4			-	Hydrophytic Vegetation Indicators:
5				Dominance Test is >50% Prevalence Index is ≤3.0¹
6				Morphological Adaptations ¹ (Provide supporting
7				data in Remarks or on a separate sheet)
8		= Total Co		Problematic Hydrophytic Vegetation¹ (Explain)
Woody Vine Stratum (Plot size:)		_ rotar oc	,,,,,	
1		v 		¹ Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.
2				
	-	_ = Total Co	over	Hydrophytic Vegetation
% Bare Ground in Herb Stratum % Cover	r of Biotic C	rust		Present? Yes No/
Remarks:				

_	-		
•	(1	п	

Depth	100217900	70			dicator	or confirn	the absence of	findicators.)
(inches)	Color (moist)	%		x Features %	Type ¹	_Loc²	Texture	Demode
0-12	10YR 4/1	200000	LOYR 4/4	Wite Sale	RM	PL	silty	Remarks
Hydric Soil Ir Histosol (Histic Epi Black His Hydrogen Stratified 1 cm Muc Depleted Thick Dar Sandy Mu	pedon (A2)	cable to all L	Reduced Matrix, CS RRs, unless other Sandy Redo Stripped Ma Loamy Muc Loamy Gley Depleted M Redox Dark Depleted Dark Vernal Pool	rwise noted ox (S5) atrix (S6) ky Mineral (red Matrix (F atrix (F3) a Surface (F6 ark Surface ressions (F8	f.) F1) F2) 6) (F7)	d Sand Gi	Indicators fo 1 cm Muc 2 cm Muc Reduced Red Pare Other (Ex) Indicators of wetland hy	ion: PL=Pore Lining, M=Matrix. or Problematic Hydric Soils ³ : ck (A9) (LRR C) ck (A10) (LRR B) Vertic (F18) ent Material (TF2) kplain in Remarks) hydrophytic vegetation and drology must be present, urbed or problematic.
Type: har								
Depth (inch	175						Hydric Soil Pr	resent? Yes ✓ No
Remarks:							Tryanc don Pr	resent? Yes / No
Vana.								
Wetland Hydromery Indica Surface W High Wate Saturation Water Ma	rology Indicators: stors (minimum of o Vater (A1) er Table (A2) n (A3) rks (B1) (Nonriver	ne required;	Salt Crust Biotic Crus Aquatic Inv Hydrogen	(B11) it (B12) vertebrates (Sulfide Odo	r (C1)		Wate Sedi Drift _/ Drai	ery Indicators (2 or more required) er Marks (B1) (Riverine) iment Deposits (B2) (Riverine) Deposits (B3) (Riverine) nage Patterns (B10)
Wetland Hydrometric Primary Indica Surface Water High Water Mater Mater Ma	rology Indicators: stors (minimum of o Vater (A1) er Table (A2) n (A3) rks (B1) (Nonriver Deposits (B2) (No	ne required; ine) nriverine)	Salt Crust Biotic Crust Aquatic Inv Hydrogen	(B11) It (B12) vertebrates (Sulfide Odor thizospheres	r (C1) s along l		Wat Sed Drift Drai ts (C3) Dry-	er Marks (B1) (Riverine) iment Deposits (B2) (Riverine) Deposits (B3) (Riverine) nage Patterns (B10) Season Water Table (C2)
Wetland Hydromary Indica Surface World High Water Saturation Water Marged Sediment Drift Depo	rology Indicators: ators (minimum of o Vater (A1) er Table (A2) n (A3) rks (B1) (Nonriver Deposits (B2) (Noriver oil Cracks (B6) n Visible on Aerial I	ine required; ine) nriverine) rine)	Salt Crust Biotic Crust Aquatic Inv Hydrogen 3 ✓ Oxidized R Presence co Recent Iron Thin Muck	(B11) It (B12) Vertebrates (Sulfide Odor Chizospheres Of Reduced In Reduction Surface (C7	r (C1) s along l Iron (C4) in Tilled)	Wate Sedi Drift Draits (C3) Dry Cray) Satu Shal	er Marks (B1) (Riverine) iment Deposits (B2) (Riverine) Deposits (B3) (Riverine) nage Patterns (B10) Season Water Table (C2) rfish Burrows (C8) aration Visible on Aerial Imagery (C9) flow Aquitard (D3)
Wetland Hydrometric Primary Indica Surface Wellingh Water Saturation Water Ma Sediment Drift Depo Surface S Inundation Water-Sta	rology Indicators: ators (minimum of or Vater (A1) er Table (A2) fr (A3) frks (B1) (Nonriver Deposits (B2) (Nonriver oil Cracks (B6) fr Visible on Aerial I	ine required; ine) nriverine) rine)	Salt Crust Biotic Crust Aquatic Inv Hydrogen V Oxidized R Presence o	(B11) It (B12) Vertebrates (Sulfide Odor Chizospheres Of Reduced In Reduction Surface (C7	r (C1) s along l Iron (C4) in Tilled)	Wate Sedi Drift Draits (C3) Dry Cray) Satu Shal	er Marks (B1) (Riverine) iment Deposits (B2) (Riverine) Deposits (B3) (Riverine) nage Patterns (B10) Season Water Table (C2) rfish Burrows (C8) iration Visible on Aerial Imagery (C9)
Wetland Hydromary Indica Surface Wellingh Water Saturation Water Ma Sediment Drift Depo Surface S Inundation Water-Sta	rology Indicators: stors (minimum of or Vater (A1) er Table (A2) n (A3) rks (B1) (Nonriver Deposits (B2) (Nonriver soil Cracks (B6) n Visible on Aerial I sined Leaves (B9) attions:	ine) nriverine) rine) magery (B7)	Salt Crust Biotic Crus Aquatic Inv Hydrogen s Oxidized R Presence c Recent Iron Thin Muck Other (Exp	(B11) It (B12) Ivertebrates (Sulfide Odor Ithizospheres of Reduced In Reduction Surface (C7 Idain in Rema	r (C1) s along I Iron (C4 in Tilled 7) arks)	Soils (C6	Wate Sedi Drift Draits (C3) Dry Cray) Satu Shal	er Marks (B1) (Riverine) iment Deposits (B2) (Riverine) Deposits (B3) (Riverine) nage Patterns (B10) Season Water Table (C2) rfish Burrows (C8) aration Visible on Aerial Imagery (C9) flow Aquitard (D3)
Wetland Hydromary Indica Surface Water Ma Sediment Drift Depo Surface S Inundatior Water-Sta Field Observa	rology Indicators: stors (minimum of or Vater (A1) er Table (A2) n (A3) rks (B1) (Nonriver Deposits (B2) (Non sits (B3) (Nonriver oil Cracks (B6) n Visible on Aerial I sined Leaves (B9) ations:	ine) nriverine) rine) magery (B7)	Salt Crust Biotic Crust Aquatic Inv Hydrogen 3 Oxidized R Presence c Recent Iron Thin Muck Other (Exp	(B11) It (B12) Vertebrates (Sulfide Odor Chizospheres Of Reduced In Reduction Surface (C7 Ilain in Remainshes):	r (C1) s along I Iron (C4 in Tilled 7) arks)	Soils (C6	Wate Sedi Drift Draits (C3) Dry Cray) Satu Shal	er Marks (B1) (Riverine) iment Deposits (B2) (Riverine) Deposits (B3) (Riverine) nage Patterns (B10) Season Water Table (C2) rfish Burrows (C8) aration Visible on Aerial Imagery (C9) flow Aquitard (D3)
Wetland Hydromany Indica Surface Water Ma Sediment Drift Depo Surface S Inundation Water-Sta Field Observa Surface Water Water Table P Saturation Pre	rology Indicators: ators (minimum of or Vater (A1) er Table (A2) n (A3) rks (B1) (Nonriver Deposits (B2) (Non river oil Cracks (B6) n Visible on Aerial I nined Leaves (B9) ations: Present? yesent? yesent?	ine) nriverine) magery (B7) es No	Salt Crust Biotic Crus Aquatic Inv Hydrogen s Oxidized R Presence c Recent Iron Thin Muck Other (Exp	(B11) It (B12) Vertebrates (Sulfide Odor Chizospheres Of Reduced In Reduction Surface (C7 Ilain in Remainshers): Suches):	r (C1) s along I Iron (C4 in Tilled 7) arks)	Soils (C6	Wate Sedi Drift Draits (C3) Dry Cray) Satu Shat FAC	er Marks (B1) (Riverine) iment Deposits (B2) (Riverine) Deposits (B3) (Riverine) nage Patterns (B10) Season Water Table (C2) rfish Burrows (C8) aration Visible on Aerial Imagery (C9) flow Aquitard (D3)
Wetland Hydromany Indica Surface Water Mare Sediment Drift Deporation Water-Star Inundation Water-Star Field Observa Surface Water Table P Saturation Pre Signification Pre Si	rology Indicators: ators (minimum of or Vater (A1) er Table (A2) n (A3) rks (B1) (Nonriver Deposits (B2) (Non river oil Cracks (B6) n Visible on Aerial I nined Leaves (B9) ations: Present? yesent? yesent?	ine) nriverine) rine) magery (B7) es No es No	Salt Crust Biotic Crust Aquatic Inv Hydrogen 3 Oxidized R Presence c Recent Iron Thin Muck Other (Exp Depth (inc	(B11) It (B12) Vertebrates (Sulfide Odor Chizospheres Of Reduced In Reduction Surface (C7 Ilain in Remainshes): Ches): Ches):	r (C1) s along I lron (C4 in Tilled 7) arks)	Soils (C6	Wate Sedi Drift Draits (C3) Dry Cray Satu Shal FAC	er Marks (B1) (Riverine) iment Deposits (B2) (Riverine) Deposits (B3) (Riverine) nage Patterns (B10) Season Water Table (C2) rfish Burrows (C8) aration Visible on Aerial Imagery (C9) llow Aquitard (D3) -Neutral Test (D5)
Primary Indica Surface W High Water Saturation Water Ma Sediment Drift Depo Surface S Inundation Water-Sta Field Observa Surface Water Water Table P Saturation Pre (includes capill Describe Reco	rology Indicators: ators (minimum of or Vater (A1) er Table (A2) n (A3) rks (B1) (Nonriver Deposits (B2) (Nonriver oil Cracks (B6) n Visible on Aerial I hined Leaves (B9) ations: Present? yeresent? yeresent?	ine) nriverine) rine) magery (B7) es No es No	Salt Crust Biotic Crust Aquatic Inv Hydrogen 3 Oxidized R Presence c Recent Iron Thin Muck Other (Exp Depth (inc	(B11) It (B12) Vertebrates (Sulfide Odor Chizospheres Of Reduced In Reduction Surface (C7 Ilain in Remainshes): Ches): Ches):	r (C1) s along I lron (C4 in Tilled 7) arks)	Soils (C6	Wate Sedi Drift Draits (C3) Dry Cray Satu Shal FAC	er Marks (B1) (Riverine) iment Deposits (B2) (Riverine) Deposits (B3) (Riverine) nage Patterns (B10) Season Water Table (C2) rfish Burrows (C8) aration Visible on Aerial Imagery (C9) llow Aquitard (D3) -Neutral Test (D5)
Wetland Hydromany Indica Surface Worker Marker Marker Marker Marker Marker Marker Marker Marker Surface Surface Surface Water Mater Table Posaturation Presincludes capill Describe Records	rology Indicators: ators (minimum of or Vater (A1) er Table (A2) n (A3) rks (B1) (Nonriver Deposits (B2) (Nonriver oil Cracks (B6) n Visible on Aerial I hined Leaves (B9) ations: Present? yeresent? yeresent?	ine) nriverine) rine) magery (B7) es No es No	Salt Crust Biotic Crust Aquatic Inv Hydrogen 3 Oxidized R Presence c Recent Iron Thin Muck Other (Exp Depth (inc	(B11) It (B12) Vertebrates (Sulfide Odor Chizospheres Of Reduced In Reduction Surface (C7 Ilain in Remainshes): Ches): Ches):	r (C1) s along I lron (C4 in Tilled 7) arks)	Soils (C6	Wate Sedi Drift Draits (C3) Dry Cray Satu Shal FAC	er Marks (B1) (Riverine) iment Deposits (B2) (Riverine) Deposits (B3) (Riverine) nage Patterns (B10) Season Water Table (C2) rfish Burrows (C8) irration Visible on Aerial Imagery (C9) llow Aquitard (D3) -Neutral Test (D5)

WETLAND DETERMINATION DATA FORM - Arid West Region

Project/Site: 6201 Horseshoe Bar Road	(City/County	Loomis/I	Placer	Sampling Date:11/19/2013
Applicant/Owner: Tulip Asset LLC		550 550		State: CA	Sampling Point:11a
Investigator(s): Kirk Vail					
Landform (hillslope, terrace, etc.): Terrace					
Subregion (LRR): C					
Soil Map Unit Name: Andregg coase sandy loam, 2 to					
Are climatic / hydrologic conditions on the site typical for t					
Are Vegetation, Soil, or Hydrology					oresent? Yes ✓ No
Are Vegetation, Soil, or Hydrology			4	eded, explain any answe	
SUMMARY OF FINDINGS – Attach site ma			g point l	ocations, transects	, important features, etc.
Hydrophytic Vegetation Present? Yes✓	No				
Hydric Soil Present? Yes ✓			e Sampled	nd? Yes✓	, No
Wetland Hydrology Present? Yes <u>√</u>	No	With	III a vvetiai	103	_ "
Remarks:					
Northwest corner of site.					
VEGETATION – Use scientific names of pla	ints.				
	Absolute	Dominant	Indicator	Dominance Test work	(sheet:
Tree Stratum (Plot size:)	% Cover			Number of Dominant S	
1. Salix laevigata		<u> </u>		That Are OBL, FACW,	or FAC:4 (A)
2. Populus fremontii				Total Number of Domir	270223
3				Species Across All Stra	ata:5 (B)
4		= Total Co	wor	Percent of Dominant S	pecies
Sapling/Shrub Stratum (Plot size:)	45	_	ivei	That Are OBL, FACVV,	or FAC: <u>80</u> (A/B)
1. Rubus armenicus	70	Y	_FACU_	Prevalence Index wor	ksheet:
2. Rosa sp.	3	N	Unk.	Total % Cover of:	
3					x1 =
4					x 2 =
5					x3=
Herb Stratum (Plot size:)	73	= Total Co	over	The state of the s	x 4 = x 5 =
Festuca perennis	5	Υ	FAC	The second secon	(A) (B)
2. Cyperus eragrostis		N	FACW	Column Totals.	(A) (D)
3. Festuca bromoides			FAC	Prevalence Index	c = B/A =
4.				Hydrophytic Vegetati	on Indicators:
5				✓ Dominance Test is	
6				Prevalence Index	
7					aptations ¹ (Provide supporting as or on a separate sheet)
8					ophytic Vegetation ¹ (Explain)
Woody Vine Stratum (Plot size:)	8	= Total Co	over		
1					oil and wetland hydrology must
2.				be present, unless dist	urbed or problematic.
-		= Total Co		Hydrophytic	
% Bare Ground in Herb Stratum % Co	ver of Biotic C	rust		Vegetation Present? Yes	es No
Remarks:	VCI OI DIOLIO O	1401		110001111	
Remarks.					

Profile Des	cription: (Describe	to the de	pth needed to docu	ment the	indicator	or confir	m the absence of i	ndicators.)
Depth Matrix			Redox Features					
(inches)	Color (moist)	%	Color (moist)	%		_Loc ²	Texture	Remarks
0-12	10YR 3/1	90	10YR 4/6	10	<u>C</u>	PL	silty loam	
Hydric Soil Histoso Histic E Black F Hydrog Stratifie	Concentration, D=Dep Indicators: (Application) I (A1) Epipedon (A2) Histic (A3) en Sulfide (A4) ed Layers (A5) (LRR 0)	able to al	M=Reduced Matrix, Colling I LRRs, unless other Sandy Record Matrix, Colling I Loamy Mu Loamy Gle Depleted Matrix, Colling I Loamy Gle Redox Dan	erwise not dox (S5) latrix (S6) cky Minera eyed Matrix Matrix (F3)	al (F1)	ed Sand G	Indicators for 1 cm Muck 2 cm Muck Reduced \ Red Paren	(A10) (LRR B)
Thick D Sandy I	ed Below Dark Surfac Park Surface (A12) Mucky Mineral (S1) Gleyed Matrix (S4)	e (A11)	Depleted E Redox Dep Vernal Poo	oressions (wetland hydr	ydrophytic vegetation and rology must be present, rbed or problematic.
Restrictive Type: <u>h</u> a	Layer (if present): ard layer nches): 12							7854C 5000 504 545
Remarks:	iones). <u>IL</u>						Hydric Soil Pre	sent? Yes No
YDROLC								
	drology Indicators: cators (minimum of o		ed: check all that ann	lv)			Secondar	y Indicators (2 or more required
	Water (A1)	no require	Salt Crus					y <u>Indicators (2 or more required</u> r Marks (B1) (Riverine)
	ater Table (A2)		Biotic Cru					nent Deposits (B2) (Riverine)
	V		5.5 510	0. (0.12)			Sedin	ion populio (DZ) (MVerille)

Wetland Hydrology Indicators:		
Primary Indicators (minimum of one required; c	heck all that apply)	Secondary Indicators (2 or more required)
 Surface Water (A1) High Water Table (A2) Saturation (A3) Water Marks (B1) (Nonriverine) Sediment Deposits (B2) (Nonriverine) Drift Deposits (B3) (Nonriverine) Surface Soil Cracks (B6) Inundation Visible on Aerial Imagery (B7) Water-Stained Leaves (B9) 	Salt Crust (B11) Biotic Crust (B12) Aquatic Invertebrates (B13) Hydrogen Sulfide Odor (C1) Oxidized Rhizospheres along Living Roots (C3 Presence of Reduced Iron (C4) Recent Iron Reduction in Tilled Soils (C6) Thin Muck Surface (C7) Other (Explain in Remarks)	 Water Marks (B1) (Riverine) Sediment Deposits (B2) (Riverine) Drift Deposits (B3) (Riverine) ✓ Drainage Patterns (B10) Dry-Season Water Table (C2) Crayfish Burrows (C8) Saturation Visible on Aerial Imagery (C9) Shallow Aquitard (D3) FAC-Neutral Test (D5)
Water Table Present? Yes No Saturation Present? Yes No (includes capillary fringe)	✓ Depth (inches): ✓ The proof of the proo	lydrology Present? Yes✓_ No ilable:

WETLAND DETERMINATION DATA FORM - Arid West Region

Project/Site: 6201 Horseshoe Bar Road	Ci	ity/County: Lo	omis/Pl	acer	_ Sampling Date: _	11/19/2013
Applicant/Owner: Tulip Asset LLC				State:CA	_ Sampling Point: _	11b
Investigator(s): Kirk Vail	S	ection, Townsl	hip, Rang	ge: 510, T11N, R7E Rocklin, Ca	alifornia USGS 7.5-minute o	quadrangle
Landform (hillslope, terrace, etc.): Terrace	L	ocal relief (cor	ncave, co	nvex, none): none	Slop	e (%):0
Subregion (LRR): C	Lat: 38.83	1404		Long: <u>-121.19121</u>	Datur	
Soil Map Unit Name: Xerorthents, placer areas				NWI classifi	cation: Upland	
Are climatic / hydrologic conditions on the site typical fo	r this time of year	? Yes	_ No	(If no, explain in I	Remarks.)	
Are Vegetation, Soil, or Hydrology	significantly di	isturbed?	Are "N	ormal Circumstances"	present? Yes✓	No
Are Vegetation, Soil, or Hydrology	naturally prob	lematic?	(If nee	ded, explain any answ	ers in Remarks.)	
SUMMARY OF FINDINGS – Attach site m			oint lo	cations, transect	s, important fe	atures, etc.
Hydric Soil Present? Yes	No <u>√</u> No <u>√</u> No <u>√</u>	Is the Sa within a		Area 1? Yes	No✓	
Remarks:						
VEGETATION – Use scientific names of p	44.00		r	D	desh sets	
Tree Stratum (Plot size:) 1.	% Cover	Dominant Ind Species? St	tatus_	Number of Dominant S That Are OBL, FACW	Species	(A)
2				Total Number of Domi	inant	
3				Species Across All St		(B)
4				Percent of Dominant S	Species	00000000
Sapling/Shrub Stratum (Plot size:)		= Total Cover		That Are OBL, FACW	, or FAC:0	(A/B)
1. Rubus armenicus	20	Y	ACU	Prevalence Index wo	orksheet:	
2				Total % Cover of:		
3				OBL species		
4				FACW species		7.7
5		The same of the sa		FAC species		
Herb Stratum (Plot size:)	20:	= Total Cover		FACU species		
1. Trifolium hirtum	20	Υ	UPL	UPL species		330 (B)
2. Centaurea solstitialis		100		Column Totals:	70 (A)	330 (B)
3					ex = B/A =4.	71
4				Hydrophytic Vegetat		
5				Dominance Test		
6				Prevalence Index		
7				Morphological Ad	laptations ¹ (Provide ks or on a separate	supporting sheet)
8				Problematic Hydr	생기가 살아가는 아름이 하지만 아이를 하는데 되었다.	
Woody Vine Stratum (Plot size:)	50	= Total Cover				
1				¹ Indicators of hydric s		
2.				be present, unless dis	sturbed or problema	tic.
3	<u></u>	= Total Cover		Hydrophytic Vegetation Present?	/es No	,
% Bare Ground in Herb Stratum % C	JOVEL OF BIOLIC CIT	uət		riosonti i	NO_	
Remarks:						

	cription. (Describ	e to the dep	th needed to docur	nent the indi	cator or confir	m the abse	nce of indicators.)
Depth	Matrix		Redo	x Features		. 9	
(inches)	Color (moist)	%	Color (moist)	<u> % T</u>	ype ¹ Loc ²	Texture	e Remarks
)-12	10YR 4/3	100				silty	
Type: C=C	concentration, D=De	pletion, RM:	=Reduced Matrix, CS	S=Covered or	Coated Sand G	Grains	² Location: PL=Pore Lining, M=Matrix.
lydric Soil	Indicators: (Appli	cable to all	LRRs, unless other	wise noted.)	osaioa oana o		tors for Problematic Hydric Soils ³ :
Histosol			Sandy Redo				cm Muck (A9) (LRR C)
_ Histic E	pipedon (A2)		Stripped Ma	253-75779 3-30-755			cm Muck (A10) (LRR B)
	istic (A3)			ky Mineral (F1	1)		educed Vertic (F18)
	en Sulfide (A4)			ed Matrix (F2))	Re	ed Parent Material (TF2)
	d Layers (A5) (LRR	(C)	Depleted M	[10] [10] 이 기원 전기 (Parties Print) : 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		Ot	her (Explain in Remarks)
	uck (A9) (LRR D)	78.441	11	Surface (F6)) Lux		
	d Below Dark Surfa ark Surface (A12)	ce (A11)		ark Surface (F	7)	3, ,,	• ************************************
	Mucky Mineral (S1)		(i)	essions (F8)			tors of hydrophytic vegetation and
	Gleyed Matrix (S4)		Vernal Pool	s (F9)			and hydrology must be present, ss disturbed or problematic.
	Layer (if present):					unic.	ss disturbed of problematic.
testrictive						1	
Type:						Undrie	Soil Branant? Von No. /
Туре:	ches):					Hydric	Soil Present? Yes No _✓
Type: Depth (in Remarks:	ches):					Hydric :	Soil Present? Yes No _✓
Type: Depth (in Remarks:	ches):					Hydric :	Soil Present? Yes No _✓
Type: Depth (in Remarks:	ches):	:		A			
Type: Depth (in lemarks: /DROLO /etland Hydrimary Indications	ches): GY drology Indicators cators (minimum of	:	l; check all that apply	Newsys.			econdary Indicators (2 or more required)
Type: Depth (in emarks: /DROLO /etland Hy- rimary India _ Surface	ches): GY drology Indicators cators (minimum of Water (A1)	:	l; check all that apply Salt Crust	(B11)			econdary Indicators (2 or more required) _ Water Marks (B1) (Riverine)
Type: Depth (in emarks: /DROLO /etland Hy- rimary India _ Surface _ High Wa	ches):	:	l; check all that apply Salt Crust Biotic Crus	(B11) t (B12)	40)		econdary Indicators (2 or more required) Water Marks (B1) (Riverine) Sediment Deposits (B2) (Riverine)
Type: Depth (in emarks: /DROLO /etland Hyerimary India Surface High Wa Saturatio	ches): GY drology Indicators cators (minimum of Water (A1) ater Table (A2) on (A3)	: one required	l; check all that apply Salt Crust Biotic Crus Aquatic Inv	(B11) t (B12) vertebrates (B		<u>S</u> e	econdary Indicators (2 or more required) Water Marks (B1) (Riverine) Sediment Deposits (B2) (Riverine) Drift Deposits (B3) (Riverine)
Type: Depth (in Temarks: /DROLO /etland Hy rimary India Surface High Wa Saturatia Water M	drology Indicators cators (minimum of Water (A1) ater Table (A2) on (A3) larks (B1) (Nonrive	: one required	l; check all that apply Salt Crust Biotic Crus Aquatic Inv	(B11) t (B12) rertebrates (B Sulfide Odor (C1)	<u>S</u> e	econdary Indicators (2 or more required) Water Marks (B1) (Riverine) Sediment Deposits (B2) (Riverine) Drift Deposits (B3) (Riverine) Drainage Patterns (B10)
Type: Depth (in Temarks: TOROLO Tetland Hyr rimary India Surface High Wa Saturatia Water M Sedimer	drology Indicators cators (minimum of Water (A1) ater Table (A2) on (A3) larks (B1) (Nonrive nt Deposits (B2) (No	: one required rine) onriverine)	l; check all that apply Salt Crust Biotic Crus Aquatic Inv Hydrogen 3	(B11) t (B12) rertebrates (B Sulfide Odor (hizospheres a	C1) along Living Ro	<u>Se</u>	econdary Indicators (2 or more required) Water Marks (B1) (Riverine) Sediment Deposits (B2) (Riverine) Drift Deposits (B3) (Riverine) Drainage Patterns (B10) Dry-Season Water Table (C2)
Type: Depth (in: Remarks: TOROLO Vetland Hydrimary India Surface High Water M Sedimer Drift Dep	drology Indicators cators (minimum of Water (A1) ater Table (A2) on (A3) larks (B1) (Nonrive nt Deposits (B2) (No	: one required rine) onriverine)	l; check all that apply Salt Crust Biotic Crus Aquatic Inv Hydrogen S Oxidized R Presence c	(B11) t (B12) vertebrates (B' Sulfide Odor (i hizospheres a of Reduced Iro	C1) along Living Ro on (C4)	<u>Se</u> 	econdary Indicators (2 or more required) Water Marks (B1) (Riverine) Sediment Deposits (B2) (Riverine) Drift Deposits (B3) (Riverine) Drainage Patterns (B10) Dry-Season Water Table (C2) Crayfish Burrows (C8)
Type: Depth (in: Remarks: TOROLO Vetland Hy Trimary India Surface High Wa Saturatia Water M Sedimer Drift Dep Surface	drology Indicators cators (minimum of Water (A1) ater Table (A2) on (A3) darks (B1) (Nonrive nt Deposits (B2) (No cosits (B3) (Nonrive Soil Cracks (B6)	: one required rine) onriverine)	l; check all that apply Salt Crust Biotic Crus Aquatic Inv Hydrogen S Oxidized R Recent Iroi	(B11) t (B12) rertebrates (Biscolling Color) Sulfide Odor (inhizospheres and Reduced Iron Reduction in	C1) along Living Ro on (C4)	Se	econdary Indicators (2 or more required) Water Marks (B1) (Riverine) Sediment Deposits (B2) (Riverine) Drift Deposits (B3) (Riverine) Torainage Patterns (B10) Dry-Season Water Table (C2) Crayfish Burrows (C8) Saturation Visible on Aerial Imagery (C9)
Type: Depth (in emarks: /DROLO /etland Hydrimary India Surface High Wa Saturatia Water Maccommoder Maccommod	drology Indicators cators (minimum of Water (A1) ater Table (A2) on (A3) larks (B1) (Nonrive nt Deposits (B2) (No cosits (B3) (Nonrive Soil Cracks (B6) on Visible on Aerial	: one required rine) onriverine)	l; check all that apply Salt Crust Biotic Crust Aquatic Inv Hydrogen 3 Oxidized R Presence co Recent Iron	(B11) t (B12) rertebrates (Bright (B15)) Sulfide Odor (Indicate (B15)) hizospheres a soft Reduced Iron Reduction in Surface (C7)	C1) along Living Roon (C4) Tilled Soils (C6)	ots (C3)	econdary Indicators (2 or more required) Water Marks (B1) (Riverine) Sediment Deposits (B2) (Riverine) Drift Deposits (B3) (Riverine) Drainage Patterns (B10) Dry-Season Water Table (C2) Crayfish Burrows (C8) Saturation Visible on Aerial Imagery (C9) Shallow Aquitard (D3)
Type: Depth (in Temarks: TDROLO Vetland Hyerimary India Surface High Wa Saturatia Water Male Sedimer Drift Depter Surface Inundatia Water-S	drology Indicators cators (minimum of Water (A1) ater Table (A2) on (A3) larks (B1) (Nonrive nt Deposits (B2) (No cosits (B3) (Nonrive Soil Cracks (B6) on Visible on Aerial tained Leaves (B9)	: one required rine) onriverine)	l; check all that apply Salt Crust Biotic Crus Aquatic Inv Hydrogen S Oxidized R Recent Iroi	(B11) t (B12) rertebrates (Bright (B15)) Sulfide Odor (Indicate (B15)) hizospheres a soft Reduced Iron Reduction in Surface (C7)	C1) along Living Roon (C4) Tilled Soils (C6)	ots (C3)	econdary Indicators (2 or more required) Water Marks (B1) (Riverine) Sediment Deposits (B2) (Riverine) Drift Deposits (B3) (Riverine) Torainage Patterns (B10) Dry-Season Water Table (C2) Crayfish Burrows (C8) Saturation Visible on Aerial Imagery (C9)
Type: Depth (in Temarks: /DROLO /etland Hyr rimary India _ Surface _ High Wa _ Saturatia _ Water M _ Sedimer _ Drift Dep _ Surface _ Inundatia _ Water-S ield Observire	drology Indicators cators (minimum of Water (A1) ater Table (A2) on (A3) larks (B1) (Nonrive nt Deposits (B2) (No cosits (B3) (Nonrive Soil Cracks (B6) on Visible on Aerial tained Leaves (B9) vations:	: one required rine) onriverine) erine)	l; check all that apply Salt Crust Biotic Crus Aquatic Inv Hydrogen 3 Oxidized R Presence 0 Recent Iroi Thin Muck ✓ Other (Exp	(B11) t (B12) rertebrates (B' Sulfide Odor (i hizospheres a of Reduced Iro n Reduction in Surface (C7) lain in Remark	C1) along Living Roon (C4) a Tilled Soils (Co	ots (C3)	econdary Indicators (2 or more required) Water Marks (B1) (Riverine) Sediment Deposits (B2) (Riverine) Drift Deposits (B3) (Riverine) Drainage Patterns (B10) Dry-Season Water Table (C2) Crayfish Burrows (C8) Saturation Visible on Aerial Imagery (C9) Shallow Aquitard (D3)
Type: Depth (in: Remarks: YDROLO Vetland Hyverimary India Surface High Water M Sedimer Drift Depth Surface Inundation Water-S ield Observariace Water Water-S	drology Indicators cators (minimum of Water (A1) ater Table (A2) on (A3) darks (B1) (Nonrive nt Deposits (B2) (No cosits (B3) (Nonrive Soil Cracks (B6) on Visible on Aerial tained Leaves (B9) vations: er Present?	: one required rine) onriverine) erine) Imagery (B7	I; check all that apply Salt Crust Biotic Crust Aquatic Inv Hydrogen S Oxidized R Presence C Recent Irol Thin Muck Other (Exp	(B11) t (B12) rertebrates (B Sulfide Odor (i hizospheres a of Reduced Iro n Reduction in Surface (C7) lain in Remark	C1) along Living Roon (C4) a Tilled Soils (Coks)	ots (C3)	econdary Indicators (2 or more required) Water Marks (B1) (Riverine) Sediment Deposits (B2) (Riverine) Drift Deposits (B3) (Riverine) Drainage Patterns (B10) Dry-Season Water Table (C2) Crayfish Burrows (C8) Saturation Visible on Aerial Imagery (C9) Shallow Aquitard (D3)
Type: Depth (in: Remarks: YDROLO Vetland Hydrimary India Surface High Water M Sedimer Drift Dep Surface Inundatio Water-Sield Observarface Water Table that uration Procludes cap	drology Indicators cators (minimum of Water (A1) ater Table (A2) on (A3) larks (B1) (Nonrive nt Deposits (B2) (No cosits (B3) (Nonrive Soil Cracks (B6) on Visible on Aerial tained Leaves (B9) vations: er Present? Present? resent?	: one required rine) onriverine) erine) Imagery (B7 //es //es //es	I; check all that apply Salt Crust Biotic Crust Aquatic Inv Hydrogen S Oxidized R Presence C Recent Irol Thin Muck ✓ Other (Exp	(B11) t (B12) rertebrates (B') Sulfide Odor (in hizospheres and Reduced Iron Reduction in Surface (C7) Itain in Remark Sches): Sches):	C1) along Living Roon (C4) n Tilled Soils (Coks) Wet	ots (C3)	econdary Indicators (2 or more required) Water Marks (B1) (Riverine) Sediment Deposits (B2) (Riverine) Drift Deposits (B3) (Riverine) Drainage Patterns (B10) Dry-Season Water Table (C2) Crayfish Burrows (C8) Saturation Visible on Aerial Imagery (C9) Shallow Aquitard (D3) FAC-Neutral Test (D5)
Type: Depth (in: Remarks: YDROLO Vetland Hydrimary India Surface High Water M Sedimer Drift Dep Surface Inundatio Water-Sield Observarface Water Table that uration Procludes cap	drology Indicators cators (minimum of Water (A1) ater Table (A2) on (A3) larks (B1) (Nonrive nt Deposits (B2) (No cosits (B3) (Nonrive Soil Cracks (B6) on Visible on Aerial tained Leaves (B9) vations: er Present? Present? resent?	: one required rine) onriverine) erine) Imagery (B7 //es //es //es	Salt Crust Salt Crust Salt Crust Salt Crust Aquatic Inv Hydrogen S Oxidized R Presence C Recent Irol Thin Muck Other (Exp	(B11) t (B12) rertebrates (B Sulfide Odor (r hizospheres a of Reduced Iro n Reduction in Surface (C7) lain in Remark thes):	C1) along Living Roon (C4) n Tilled Soils (Coks) Wet	ots (C3)	econdary Indicators (2 or more required) Water Marks (B1) (Riverine) Sediment Deposits (B2) (Riverine) Drift Deposits (B3) (Riverine) Drainage Patterns (B10) Dry-Season Water Table (C2) Crayfish Burrows (C8) Saturation Visible on Aerial Imagery (C9 Shallow Aquitard (D3) FAC-Neutral Test (D5)
Type: Depth (in: Remarks: YDROLO Vetland Hydrimary India Surface High Water M Sedimer Drift Dep Surface Inundation Water-S ield Observation Procludes cap	drology Indicators cators (minimum of Water (A1) ater Table (A2) on (A3) larks (B1) (Nonrive nt Deposits (B2) (No cosits (B3) (Nonrive Soil Cracks (B6) on Visible on Aerial tained Leaves (B9) vations: er Present? Present? resent?	: one required rine) onriverine) erine) Imagery (B7 //es //es //es	I; check all that apply Salt Crust Biotic Crust Aquatic Inv Hydrogen S Oxidized R Presence C Recent Irol Thin Muck ✓ Other (Exp	(B11) t (B12) rertebrates (B Sulfide Odor (r hizospheres a of Reduced Iro n Reduction in Surface (C7) lain in Remark thes):	C1) along Living Roon (C4) n Tilled Soils (Coks) Wet	ots (C3)	econdary Indicators (2 or more required) Water Marks (B1) (Riverine) Sediment Deposits (B2) (Riverine) Drift Deposits (B3) (Riverine) Drainage Patterns (B10) Dry-Season Water Table (C2) Crayfish Burrows (C8) Saturation Visible on Aerial Imagery (C9) Shallow Aquitard (D3) FAC-Neutral Test (D5)

WETLAND DETERMINATION DATA FORM – Arid West Region

Project/Site: 6201 Horseshoe Bar Road		City/County: Loomis/	Placer	Sampling Date:11/19/	2013
Applicant/Owner: Tulip Asset LLC			State:CA	Sampling Point:12a	a
Investigator(s): Kirk Vail		Section, Township, Ra	nge: S10, T11N, R7E Rocklin, Ca	lifornia USGS 7.5-minute quadrangle	
Landform (hillslope, terrace, etc.): Terrace					
Subregion (LRR): C					
Soil Map Unit Name: Andregg coarse sandy					
Are climatic / hydrologic conditions on the site t					
Are Vegetation, Soil, or Hydrold				present? Yes ✓ No	
Are Vegetation, Soil, or Hydrold			eeded, explain any answe		
SUMMARY OF FINDINGS - Attach			ocations, transects	s, important features,	, etc.
Hydrophytic Vegetation Present? Yes	No	Is the Complete	I Avon		
	No	Is the Sampled within a Wetlan		No <u></u>	
Wetland Hydrology Present? Yes	No	Within a Wotlan			
Remarks:					
Graded strips of vegetation for fir					
VEGETATION – Use scientific name		Dominant Indicator	Dominance Test work	ksheet:	
Tree Stratum (Plot size:) 1.	% Cover	Species? Status	Number of Dominant S		(A)
2			Total Number of Domin	nant	
3			Species Across All Stra		(B)
4			Percent of Dominant S	Species	
Continue/Observe Ottookuma /Diet sings		= Total Cover	That Are OBL, FACW,	or FAC:0	(A/B)
Sapling/Shrub Stratum (Plot size:1			Prevalence Index wo	rksheet:	
2.				Multiply by:	_
3.				x 1 =	
4.			FACW species	x 2 =	- 0
5			FAC species	x 3 =	. e
		= Total Cover	FACU species	x 4 =	-
Herb Stratum (Plot size:)	20	V 1101	I MARK DAKE HARROCKS TRATE	x 5 =	
1. Bromus diandrus		Y UPL Y FACU	Column Totals:	(A)	_ (B)
2. Bromus hordeaceus		N UPL	Prevalence Inde	x = B/A =	2
			Hydrophytic Vegetat		
4 5.			Dominance Test i	s >50%	
6.			✓ Prevalence Index		
7.			Morphological Ad	aptations1 (Provide supporti	ing
8.				ks or on a separate sheet) ophytic Vegetation¹ (Explain	n)
		= Total Cover	Problematic Hydro	opnytic vegetation (Explain	ij
Woody Vine Stratum (Plot size:)		1 Indicators of bydric se	oil and wetland hydrology m	nuet
1			be present, unless dis		luot
2		= Total Cover	Hydrophytic Vegetation	20	
% Bare Ground in Herb Stratum	_ % Cover of Biotic C	rust	Present? Y	es No	
Remarks:					
1					

Profile Des	cription: (Describe	to the death n	noded to decur	mont the indicator	or confir	m the cheenes of	Sampling Point:1
Depth	Matrix	to the depth in			or confin	n the absence of	indicators.)
(inches)	Color (moist)			Redox Features Color (moist) % Type ¹ Lo		Texture	Remarks
0-12	10YR 4/4						Remarks
7 12	101114/4					silty	
ype: C=C	Concentration, D=Dep	oletion, RM=Red	luced Matrix, CS	S=Covered or Coate	ed Sand G		on: PL=Pore Lining, M=Matri r Problematic Hydric Soils ³ :
_ Histoso			Sandy Redo				k (A9) (LRR C)
_ Histic E	pipedon (A2)	9,	Stripped Ma				k (A10) (LRR B)
_ Black H	istic (A3)		Loamy Muc	ky Mineral (F1)		Reduced	
_ Hydroge	en Sulfide (A4)		Loamy Gley	red Matrix (F2)			nt Material (TF2)
_ Stratifie	d Layers (A5) (LRR (C) _	Depleted Ma	atrix (F3)		Other (Ex	plain in Remarks)
_ 1 cm M	uck (A9) (LRR D)		Redox Dark	Surface (F6)			
	d Below Dark Surfac	e (A11)	Depleted Da	ark Surface (F7)			
	ark Surface (A12)		Redox Depr	essions (F8)		3Indicators of h	hydrophytic vegetation and
	Mucky Mineral (S1)	4	Vernal Pool	s (F9)		wetland hyd	Irology must be present,
	Gleyed Matrix (S4)			C9 98		unless distu	irbed or problematic.
estrictive	Layer (if present):						1997
Type:							
Depth (in	ches):					Hydric Soil Pre	esent? Yes No _
emarks:							
DROLO	GY						
etland Hy	drology Indicators:						
imary India	cators (minimum of o	ne required; che	eck all that apply	()		Secondar	ry Indicators (2 or more requir
	Water (A1)		Salt Crust	West reports			er Marks (B1) (Riverine)
	ater Table (A2)		Biotic Crus				ment Deposits (B2) (Riverine)
_ Saturation				rertebrates (B13)			Deposits (B3) (Riverine)
	larks (B1) (Nonrive ri	ine)		Sulfide Odor (C1)			
v valci iv	mino (DI) (MOIIIIAGLI	110)	riyurogen s	Juniue Odor (C1)		Drain	nage Patterns (B10)

___ Oxidized Rhizospheres along Living Roots (C3) ___ Dry-Season Water Table (C2) Sediment Deposits (B2) (Nonriverine) Drift Deposits (B3) (Nonriverine) Presence of Reduced Iron (C4) __ Crayfish Burrows (C8) Surface Soil Cracks (B6) __ Recent Iron Reduction in Tilled Soils (C6) ___ Saturation Visible on Aerial Imagery (C9) Inundation Visible on Aerial Imagery (B7) __ Shallow Aquitard (D3) __ Thin Muck Surface (C7) __ Water-Stained Leaves (B9) Other (Explain in Remarks) FAC-Neutral Test (D5) Field Observations: Yes ____ No _ ✓ Depth (inches): _ Surface Water Present?

(includes capillary fringe)

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Yes ____ No _ ✓ Depth (inches): ___

Yes ____ No _ ✓ Depth (inches): _

Remarks:

Water Table Present?

Saturation Present?

Wetland Hydrology Present? Yes ___

WETLAND DETERMINATION DATA FORM - Arid West Region

Project/Site: 6201 Horseshoe Bar Road	City/C	ounty: Loomis/I	Placer	Sampling Date:11/19/2013
				Sampling Point:12b
Investigator(s): Kirk Vail				
Landform (hillslope, terrace, etc.): Terrace				
Subregion (LRR): C				
Soil Map Unit Name: Andregg coarse sandy loam, 2 t				
Are climatic / hydrologic conditions on the site typical for the				
Are Vegetation, Soil, or Hydrology				present? Yes No
Are Vegetation, Soil, or Hydrology			eded, explain any answe	
SUMMARY OF FINDINGS – Attach site map			37 ANO ES 20	
Hydrophytic Vegetation Present? Yes✓	No			
Hydrophytic Vegetation Present? Yes Hydric Soil Present? Yes ✓ Yes		Is the Sampled		/ N-
Wetland Hydrology Present? Yes ✓		within a Wetlar	nd? Yes <u>v</u>	No
Remarks:				
Southwestern corner.				
South Western Connect				
VEGETATION – Use scientific names of pla	nte			
VEGETATION – Ose scientific flames of pla		ninant Indicator	Dominance Test wor	ksheet:
Tree Stratum (Plot size:)	% Cover Spe	cies? Status	Number of Dominant S	Species
1. Populus fremontii	33	Y FACW	That Are OBL, FACW,	
2. Quercus lobata			Total Number of Domi	nant
3. Quercus wislizeni	5	N UPL	Species Across All Str	
4			Percent of Dominant S	Species
Condition (Clear to Chrothum (Plot size)	48 = To	otal Cover	That Are OBL, FACW,	or FAC:50 (A/B)
Sapling/Shrub Stratum (Plot size:) 1. Rubus armenicus	30	V FACII	Prevalence Index wo	rksheet:
Salix lasiolepis			Total % Cover of:	
3				x 1 =
4.			FACW species 103	x 2 =206
5				x3=
	100 = To	otal Cover		x 4 = <u>160</u>
Herb Stratum (Plot size:)			UPL species 5	x 5 = <u>25</u>
1			Column Totals:1	<u>48</u> (A) <u>391</u> (B)
2			Prevalence Inde	x = B/A =2.64
3			Hydrophytic Vegetat	
4			Dominance Test i	
5			✓ Prevalence Index	
6			Morphological Ad	aptations ¹ (Provide supporting
7 8.				ks or on a separate sheet)
0	= To	otal Cover	Problematic Hydro	ophytic Vegetation ¹ (Explain)
Woody Vine Stratum (Plot size:)	1			
1			Indicators of hydric so	oil and wetland hydrology must turbed or problematic.
2				
_	= To	otal Cover	Hydrophytic Vegetation	
% Bare Ground in Herb Stratum % Co	ver of Biotic Crust		Present? Y	es No
Remarks:				

~	-	
9	(1	

Sampling	Point:	12b
Sampling	Politi.	TZU

Profile Description: (Describe to the of Depth Matrix	Red	ox Feature	es			
(inches) Color (moist) %	Color (moist)	%	Type ¹	_Loc ²	Texture	Remarks
<u>0-12</u> <u>10YR 3/2</u> <u>90</u>	10YR 3/4	10	_ <u>C</u>	_PL	silty	
						5
		7/17			-	
	_		. — —			
	-(3)					
¹ Type: C=Concentration, D=Depletion, R	M=Reduced Matrix C	S=Covere	d or Coate	d Sand G	rains ² l postio	n: PL=Pore Lining, M=Matrix.
Hydric Soil Indicators: (Applicable to	all LRRs. unless othe	erwise not	ed.)	u Sanu G		Problematic Hydric Soils ³ :
Histosol (A1)	Sandy Red		,			(A9) (LRR C)
Histic Epipedon (A2)	Stripped M					(A10) (LRR B)
Black Histic (A3)	Loamy Mu	1000	al (F1)		Reduced V	맞면 있는 하면 맛있다면 그러워 그렇게 하다.
Hydrogen Sulfide (A4)	Loamy Gle					t Material (TF2)
Stratified Layers (A5) (LRR C)	Depleted N	Matrix (F3)				lain in Remarks)
1 cm Muck (A9) (LRR D)	✓ Redox Dar					
Depleted Below Dark Surface (A11)	Depleted D		A 60		3.	
Thick Dark Surface (A12)	Redox Dep		F8)			drophytic vegetation and
Sandy Mucky Mineral (S1) Sandy Gleyed Matrix (S4)	Vernal Poo	ois (F9)				ology must be present,
Restrictive Layer (if present):					uniess disturi	bed or problematic.
Type:					1	
					1	
Denth (inches):					Undela Call Dea	
Depth (inches):Remarks:					Hydric Soil Pres	sent? Yes No
	_				Hydric Soil Pres	sent? Yes <u>√</u> No
Remarks:					Hydric Soil Pres	sent? Yes <u>√</u> No
Remarks:					Hydric Soil Pres	sent? Yes <u>√</u> No
Remarks: IYDROLOGY Wetland Hydrology Indicators:	red: check all that ann	lv)				
Remarks: IYDROLOGY Wetland Hydrology Indicators: Primary Indicators (minimum of one requi	contraction of Marie	1 Salasanaray			Secondary	Indicators (2 or more required)
Remarks: IYDROLOGY Wetland Hydrology Indicators: Primary Indicators (minimum of one requi Surface Water (A1)	Salt Crust	t (B11)			Secondary Water	r Indicators (2 or more required) Marks (B1) (Riverine)
Remarks: IYDROLOGY Wetland Hydrology Indicators: Primary Indicators (minimum of one requi Surface Water (A1) High Water Table (A2)	Salt Crust	t (B11) st (B12)	ue (R13)		Secondary — Water — Sedim	Indicators (2 or more required) Marks (B1) (Riverine) ent Deposits (B2) (Riverine)
Remarks: IYDROLOGY Wetland Hydrology Indicators: Primary Indicators (minimum of one requi Surface Water (A1) High Water Table (A2) Saturation (A3)	Salt Crust Biotic Cru Aquatic In	t (B11) st (B12) overtebrate			Secondary Water Sedim Drift D	Marks (B1) (Riverine) ent Deposits (B2) (Riverine) eposits (B3) (Riverine)
Remarks: IYDROLOGY Wetland Hydrology Indicators: Primary Indicators (minimum of one requi Surface Water (A1) High Water Table (A2) Saturation (A3) Water Marks (B1) (Nonriverine)	Salt Crust Biotic Cru Aquatic Ir Hydrogen	t (B11) est (B12) evertebrate Sulfide Od	dor (C1)	iving Ros	Secondary Water Sedim Drift D	Marks (B1) (Riverine) lent Deposits (B2) (Riverine) leposits (B3) (Riverine) leposits (B3) (Riverine)
Remarks: IYDROLOGY Wetland Hydrology Indicators: Primary Indicators (minimum of one requi Surface Water (A1) High Water Table (A2) Saturation (A3) Water Marks (B1) (Nonriverine) Sediment Deposits (B2) (Nonriverine	Salt Crusi Biotic Cru Aquatic Ir Hydrogen Ø Oxidized	t (B11) st (B12) nvertebrate Sulfide Oo Rhizosphe	dor (C1) res along l		Secondary Water Sedim Drift D Draina	Marks (B1) (Riverine) lent Deposits (B2) (Riverine) leposits (B3) (Riverine) leposits (B10) leposits (B10) leposits (B10)
Remarks: IYDROLOGY Wetland Hydrology Indicators: Primary Indicators (minimum of one requi Surface Water (A1) High Water Table (A2) Saturation (A3) Water Marks (B1) (Nonriverine) Sediment Deposits (B2) (Nonriverine)	Salt Crusi Biotic Cru Aquatic Ir Hydrogen d) ✓ Oxidized I Presence	t (B11) st (B12) nvertebrate Sulfide Oc Rhizosphe of Reduce	dor (C1) res along l ed Iron (C4)	Secondary Water Sedim Drift D Draina ots (C3) Crayfis	Marks (B1) (Riverine) ent Deposits (B2) (Riverine) eposits (B3) (Riverine) eposits (B10) eason Water Table (C2) sh Burrows (C8)
Remarks: IYDROLOGY Wetland Hydrology Indicators: Primary Indicators (minimum of one requi Surface Water (A1) High Water Table (A2) Saturation (A3) Water Marks (B1) (Nonriverine) Sediment Deposits (B2) (Nonriverine) Drift Deposits (B3) (Nonriverine) Surface Soil Cracks (B6)	Salt Crust Biotic Cru Aquatic Ir Hydrogen Oxidized Presence Recent Iro	t (B11) st (B12) nvertebrate Sulfide Oo Rhizosphe of Reduce	dor (C1) res along l ed Iron (C4 on in Tilled)	Secondary Water Sedim Drift D Dry-Se Crayfis Solution	r Indicators (2 or more required) Marks (B1) (Riverine) ment Deposits (B2) (Riverine) meposits (B3) (Riverine) meposits (B10) meason Water Table (C2) meason Water Table (C2) meason Water Table (C2) meason Water Table (C2)
Remarks: IYDROLOGY Wetland Hydrology Indicators: Primary Indicators (minimum of one requi Surface Water (A1) High Water Table (A2) Saturation (A3) Water Marks (B1) (Nonriverine) Sediment Deposits (B2) (Nonriverine)	Salt Crusi Biotic Cru Aquatic Ir Hydrogen Oxidized Presence Recent Iro (B7) Salt Crusi	t (B11) st (B12) nvertebrate Sulfide Oc Rhizosphe of Reduce on Reducti k Surface (dor (C1) res along led Iron (C4 on in Tilled)	Secondary Water Sedim Drift D Draina Ots (C3) Dry-Se Crayfie Satura Shallo	Marks (B1) (Riverine) lent Deposits (B2) (Riverine) leposits (B3) (Riverine) leposits (B3) (Riverine) leposits (B10) leason Water Table (C2) lesh Burrows (C8) lition Visible on Aerial Imagery (C9) w Aquitard (D3)
Remarks: HYDROLOGY Wetland Hydrology Indicators: Primary Indicators (minimum of one requi Surface Water (A1) High Water Table (A2) Saturation (A3) Water Marks (B1) (Nonriverine) Sediment Deposits (B2) (Nonriverine) Drift Deposits (B3) (Nonriverine) Surface Soil Cracks (B6) Inundation Visible on Aerial Imagery Water-Stained Leaves (B9)	Salt Crust Biotic Cru Aquatic Ir Hydrogen Oxidized Presence Recent Iro	t (B11) st (B12) nvertebrate Sulfide Oc Rhizosphe of Reduce on Reducti k Surface (dor (C1) res along led Iron (C4 on in Tilled)	Secondary Water Sedim Drift D Draina Ots (C3) Dry-Se Crayfie Satura Shallo	r Indicators (2 or more required) Marks (B1) (Riverine) ment Deposits (B2) (Riverine) meposits (B3) (Riverine) meposits (B10) meason Water Table (C2) meason Water Table (C2) meason Water Table (C2) meason Water Table (C2)
Remarks: HYDROLOGY Wetland Hydrology Indicators: Primary Indicators (minimum of one requi Surface Water (A1) High Water Table (A2) Saturation (A3) Water Marks (B1) (Nonriverine) Sediment Deposits (B2) (Nonriverine) Drift Deposits (B3) (Nonriverine) Surface Soil Cracks (B6) Inundation Visible on Aerial Imagery Water-Stained Leaves (B9) Field Observations:	Salt Crust Biotic Cru Aquatic Ir Hydrogen Oxidized I Presence Recent Irc (B7) Thin Mucl	t (B11) st (B12) evertebrate Sulfide Oc Rhizosphe of Reduce on Reduction k Surface (plain in Re	dor (C1) res along led Iron (C4 on in Tilled (C7) emarks))	Secondary Water Sedim Drift D Draina Ots (C3) Dry-Se Crayfie Satura Shallo	Marks (B1) (Riverine) lent Deposits (B2) (Riverine) leposits (B3) (Riverine) leposits (B3) (Riverine) leposits (B10) leason Water Table (C2) lesh Burrows (C8) lition Visible on Aerial Imagery (C9) w Aquitard (D3)
Remarks: HYDROLOGY Wetland Hydrology Indicators: Primary Indicators (minimum of one requi Surface Water (A1) High Water Table (A2) Saturation (A3) Water Marks (B1) (Nonriverine) Sediment Deposits (B2) (Nonriverine) Drift Deposits (B3) (Nonriverine) Surface Soil Cracks (B6) Inundation Visible on Aerial Imagery Water-Stained Leaves (B9) Field Observations: Surface Water Present? Yes	Salt Crust Biotic Cru Aquatic Ir Hydrogen Oxidized I Presence Recent Ir (B7) Thin Mucl Other (Ex	t (B11) st (B12) evertebrate sulfide Oc Rhizosphe of Reduce on Reduction k Surface (plain in Re	dor (C1) res along l ed Iron (C4 on in Tilled (C7) emarks)) Soils (C6	Secondary Water Sedim Drift D Draina Ots (C3) Dry-Se Crayfie Satura Shallo	Marks (B1) (Riverine) lent Deposits (B2) (Riverine) leposits (B3) (Riverine) leposits (B3) (Riverine) leposits (B10) leason Water Table (C2) lesh Burrows (C8) lition Visible on Aerial Imagery (C9) w Aquitard (D3)
HYDROLOGY Wetland Hydrology Indicators: Primary Indicators (minimum of one requi Surface Water (A1) High Water Table (A2) Saturation (A3) Water Marks (B1) (Nonriverine) Sediment Deposits (B2) (Nonriverine) Drift Deposits (B3) (Nonriverine) Surface Soil Cracks (B6) Inundation Visible on Aerial Imagery Water-Stained Leaves (B9) Field Observations: Surface Water Present? Yes Water Table Present? Yes	Salt Crust Biotic Cru Aquatic Ir Hydrogen Cru Presence Recent Iro (B7) Thin Muct Other (Ex	t (B11) st (B12) evertebrate sulfide Oc Rhizosphe of Reduce on Reductic x Surface (plain in Re enches):	dor (C1) res along l ed Iron (C4 on in Tilled (C7) emarks)) Soils (C6	Secondary Water Sedim Drift D Draina Ots (C3) Crayfi Solution FAC-N	r Indicators (2 or more required) Marks (B1) (Riverine) ment Deposits (B2) (Riverine) meposits (B3) (Riverine) meposits (B10) meason Water Table (C2) meason Water Table (C2) meason Water Table (C2) meason Water Table (C3) meason Water Table (C5)
HYDROLOGY Wetland Hydrology Indicators: Primary Indicators (minimum of one requi Surface Water (A1) High Water Table (A2) Saturation (A3) Water Marks (B1) (Nonriverine) Sediment Deposits (B2) (Nonriverine) Drift Deposits (B3) (Nonriverine) Surface Soil Cracks (B6) Inundation Visible on Aerial Imagery Water-Stained Leaves (B9) Field Observations: Surface Water Present? Water Table Present? Yes Saturation Present? Yes [Includes capillary fringe]	Salt Crust Biotic Cru Aquatic Ir Hydrogen Oxidized I Presence Recent Ir Other (Ex No V Depth (in No V Depth (in	t (B11) ast (B12) avertebrate a Sulfide Oc Rhizosphe of Reduce on Reduction k Surface (plain in Re aches): aches): aches):	dor (C1) res along l ed Iron (C4 on in Tilled (C7) emarks)) Soils (C6	Secondary Water Sedim Drift D Drift D Crayfis Sts (C3) Dry-Sc Crayfis Shallo FAC-N	Marks (B1) (Riverine) lent Deposits (B2) (Riverine) leposits (B3) (Riverine) leposits (B3) (Riverine) leposits (B10) leason Water Table (C2) lesh Burrows (C8) lition Visible on Aerial Imagery (C9) w Aquitard (D3)
HYDROLOGY Wetland Hydrology Indicators: Primary Indicators (minimum of one requi Surface Water (A1) High Water Table (A2) Saturation (A3) Water Marks (B1) (Nonriverine) Sediment Deposits (B2) (Nonriverine) Drift Deposits (B3) (Nonriverine) Surface Soil Cracks (B6) Inundation Visible on Aerial Imagery Water-Stained Leaves (B9) Field Observations: Surface Water Present? Water Table Present? Yes Saturation Present? Yes [includes capillary fringe]	Salt Crust Biotic Cru Aquatic Ir Hydrogen Oxidized I Presence Recent Ir Other (Ex No V Depth (in No V Depth (in	t (B11) ast (B12) avertebrate a Sulfide Oc Rhizosphe of Reduce on Reduction k Surface (plain in Re aches): aches): aches):	dor (C1) res along l ed Iron (C4 on in Tilled (C7) emarks)) Soils (C6	Secondary Water Sedim Drift D Drift D Crayfis Sts (C3) Dry-Sc Crayfis Shallo FAC-N	r Indicators (2 or more required) Marks (B1) (Riverine) ment Deposits (B2) (Riverine) meposits (B3) (Riverine) meposits (B10) meason Water Table (C2) meason Water Table (C2) meason Water Table (C2) meason Water Table (C3) meason Water Table (C5)
HYDROLOGY Wetland Hydrology Indicators: Primary Indicators (minimum of one requi Surface Water (A1) High Water Table (A2) Saturation (A3) Water Marks (B1) (Nonriverine) Sediment Deposits (B2) (Nonriverine) Drift Deposits (B3) (Nonriverine) Surface Soil Cracks (B6) Inundation Visible on Aerial Imagery Water-Stained Leaves (B9) Field Observations: Surface Water Present? Water Table Present? Yes Saturation Present? Yes [Includes capillary fringe]	Salt Crust Biotic Cru Aquatic Ir Hydrogen Oxidized I Presence Recent Ir Other (Ex No V Depth (in No V Depth (in	t (B11) ast (B12) avertebrate a Sulfide Oc Rhizosphe of Reduce on Reduction k Surface (plain in Re aches): aches): aches):	dor (C1) res along l ed Iron (C4 on in Tilled (C7) emarks)) Soils (C6	Secondary Water Sedim Drift D Drift D Crayfis Sts (C3) Dry-Sc Crayfis Shallo FAC-N	r Indicators (2 or more required) Marks (B1) (Riverine) ment Deposits (B2) (Riverine) meposits (B3) (Riverine) meposits (B10) meason Water Table (C2) meason Water Table (C2) meason Water Table (C2) meason Water Table (C3) meason Water Table (C5)
HYDROLOGY Wetland Hydrology Indicators: Primary Indicators (minimum of one requi Surface Water (A1) High Water Table (A2) Saturation (A3) Water Marks (B1) (Nonriverine) Sediment Deposits (B2) (Nonriverine) Drift Deposits (B3) (Nonriverine) Surface Soil Cracks (B6) Inundation Visible on Aerial Imagery Water-Stained Leaves (B9) Field Observations: Surface Water Present? Yes Water Table Present? Yes Saturation Present? Yes [includes capillary fringe) Describe Recorded Data (stream gauge, 1)	Salt Crust Biotic Cru Aquatic Ir Hydrogen Oxidized I Presence Recent Ir Other (Ex No V Depth (in No V Depth (in	t (B11) ast (B12) avertebrate a Sulfide Oc Rhizosphe of Reduce on Reduction k Surface (plain in Re aches): aches): aches):	dor (C1) res along l ed Iron (C4 on in Tilled (C7) emarks)) Soils (C6	Secondary Water Sedim Drift D Drift D Crayfis Sts (C3) Dry-Sc Crayfis Shallo FAC-N	r Indicators (2 or more required) Marks (B1) (Riverine) ment Deposits (B2) (Riverine) meposits (B3) (Riverine) meposits (B10) meason Water Table (C2) meason Water Table (C2) meason Water Table (C2) meason Water Table (C3) meason Water Table (C5)
HYDROLOGY Wetland Hydrology Indicators: Primary Indicators (minimum of one requi Surface Water (A1) High Water Table (A2) Saturation (A3) Water Marks (B1) (Nonriverine) Sediment Deposits (B2) (Nonriverine) Drift Deposits (B3) (Nonriverine) Surface Soil Cracks (B6) Inundation Visible on Aerial Imagery Water-Stained Leaves (B9) Field Observations: Surface Water Present? Yes Water Table Present? Yes Saturation Present? Yes	Salt Crust Biotic Cru Aquatic Ir Hydrogen Oxidized I Presence Recent Ir Other (Ex No V Depth (in No V Depth (in	t (B11) ast (B12) avertebrate a Sulfide Oc Rhizosphe of Reduce on Reduction k Surface (plain in Re aches): aches): aches):	dor (C1) res along l ed Iron (C4 on in Tilled (C7) emarks)) Soils (C6	Secondary Water Sedim Drift D Drift D Crayfis Sts (C3) Dry-Sc Crayfis Shallo FAC-N	r Indicators (2 or more required) Marks (B1) (Riverine) ment Deposits (B2) (Riverine) meposits (B3) (Riverine) meposits (B10) meason Water Table (C2) meason Water Table (C2) meason Water Table (C2) meason Water Table (C3) meason Water Table (C5)
Remarks: HYDROLOGY Wetland Hydrology Indicators: Primary Indicators (minimum of one requi Surface Water (A1) High Water Table (A2) Saturation (A3) Water Marks (B1) (Nonriverine) Sediment Deposits (B2) (Nonriverine) Drift Deposits (B3) (Nonriverine) Surface Soil Cracks (B6) Inundation Visible on Aerial Imagery Water-Stained Leaves (B9) Field Observations: Surface Water Present? Yes Water Table Present? Yes Saturation Present? Yes (includes capillary fringe) Describe Recorded Data (stream gauge, 1)	Salt Crust Biotic Cru Aquatic Ir Hydrogen Oxidized I Presence Recent Ir Other (Ex No V Depth (in No V Depth (in	t (B11) ast (B12) avertebrate a Sulfide Oc Rhizosphe of Reduce on Reduction k Surface (plain in Re aches): aches): aches):	dor (C1) res along l ed Iron (C4 on in Tilled (C7) emarks)) Soils (C6	Secondary Water Sedim Drift D Drift D Crayfis Sts (C3) Dry-Sc Crayfis Shallo FAC-N	r Indicators (2 or more required) Marks (B1) (Riverine) nent Deposits (B2) (Riverine) neposits (B3) (Riverine) neposits (B10) neposits (B10) neason Water Table (C2) neposits (C8) neposits (C9) nepos
Remarks: HYDROLOGY Wetland Hydrology Indicators: Primary Indicators (minimum of one requi Surface Water (A1) High Water Table (A2) Saturation (A3) Water Marks (B1) (Nonriverine) Sediment Deposits (B2) (Nonriverine) Drift Deposits (B3) (Nonriverine) Surface Soil Cracks (B6) Inundation Visible on Aerial Imagery Water-Stained Leaves (B9) Field Observations: Surface Water Present? Yes Water Table Present? Yes Saturation Present? Yes (includes capillary fringe) Describe Recorded Data (stream gauge, 1)	Salt Crust Biotic Cru Aquatic Ir Hydrogen Oxidized I Presence Recent Ir Other (Ex No V Depth (in No V Depth (in	t (B11) ast (B12) avertebrate a Sulfide Oc Rhizosphe of Reduce on Reduction k Surface (plain in Re aches): aches): aches):	dor (C1) res along l ed Iron (C4 on in Tilled (C7) emarks)) Soils (C6	Secondary Water Sedim Drift D Drift D Crayfis Sts (C3) Dry-Sc Crayfis Shallo FAC-N	r Indicators (2 or more required) Marks (B1) (Riverine) ment Deposits (B2) (Riverine) meposits (B3) (Riverine) meposits (B10) meason Water Table (C2) meason Water Table (C2) meason Water Table (C2) meason Water Table (C3) meason Water Table (C5)

Appendix C — **Preliminary Jurisdictional Determination Form**

PRELIMINARY JURISDICTIONAL DETERMINATION FORM

BACKGROUND INFORMATION

A. DE	REPORT COMPLETION DATI TERMINATION (JD): March 27, 2014	_	LIMINARY JURIS	DICTIONAL
Ę	NAME AND ADDRESS OF PE Foothill Associates 590 Menlo Drive, Suite 5 Rocklin, California 95765	ERSON REC	UESTING PRELI	MINARY JD:
C.	DISTRICT OFFICE, FILE NAM	IE, AND NU	MBER: CENAP-C	P-R-
•	PROJECT LOCATION(S) AND SE THE ATTACHED TABLE TO DEFERENT SITES) State: California County: Plate Center coordinates of site (lat/long Lat.38.82 ° N, Long121.7	ocument acer C in degree d	MULTIPLE WAT	
	Universal Transverse Mercator: Name of nearest waterbody: Secret	m East		m Northing (y)
	Identify (estimate) amount of water Non-wetland waters: line Cowardin Class: Stream Flow: Wetlands:1.13 acres. Cowardin Class:	rs in the revi ear feet:	iew area: width (ft) and/d	or acres.
	Name of any water bodies on the s Tidal: Non-Tidal:	site that hav	e been identified a	as Section 10 waters:
Ε.	REVIEW PERFORMED FOR SITE	E EVALUAT	ION (CHECK ALL 1	THAT APPLY):
	☐ Office (Desk) Determination.☐ Field Determination.	Date: Date(s):		

- 1. The Corps of Engineers believes that there may be jurisdictional waters of the United States on the subject site, and the permit applicant or other affected party who requested this preliminary JD is hereby advised of his or her option to request and obtain an approved jurisdictional determination (JD) for that site. Nevertheless, the permit applicant or other person who requested this preliminary JD has declined to exercise the option to obtain an approved JD in this instance and at this time.
- 2. In any circumstance where a permit applicant obtains an individual permit, or a Nationwide General Permit (NWP) or other general permit verification requiring "pre-construction" notification" (PCN), or requests verification for a non-reporting NWP or other general permit, and the permit applicant has not requested an approved JD for the activity, the permit applicant is hereby made aware of the following: (1) the permit applicant has elected to seek a permit authorization based on a preliminary JD, which does not make an official determination of jurisdictional waters; (2) that the applicant has the option to request an approved JD before accepting the terms and conditions of the permit authorization, and that basing a permit authorization on an approved JD could possibly result in less compensatory mitigation being required or different special conditions; (3) that the applicant has the right to request an individual permit rather than accepting the terms and conditions of the NWP or other general permit authorization; (4) that the applicant can accept a permit authorization and thereby agree to comply with all the terms and conditions of that permit, including whatever mitigation requirements the Corps has determined to be necessary; (5) that undertaking any activity in reliance upon the subject permit authorization without requesting an approved JD constitutes the applicant's acceptance of the use of the preliminary JD, but that either form of JD will be processed as soon as is practicable; (6) accepting a permit authorization (e.g., signing a proffered individual permit) or undertaking any activity in reliance on any form of Corps permit authorization based on a preliminary JD constitutes agreement that all wetlands and other water bodies on the site affected in any way by that activity are jurisdictional waters of the United States, and precludes any challenge to such jurisdiction in any administrative or judicial compliance or enforcement action, or in any administrative appeal or in any Federal court; and (7) whether the applicant elects to use either an approved JD or a preliminary JD, that JD will be processed as soon as is practicable. Further, an approved JD, a proffered individual permit (and all terms and conditions contained therein), or individual permit denial can be administratively appealed pursuant to 33 C.F.R. Part 331, and that in any administrative appeal, jurisdictional issues can be raised (see 33 C.F.R. 331.5(a)(2)). If, during that administrative appeal, it becomes necessary to make an official determination whether CWA jurisdiction exists over a site, or to provide an official delineation of jurisdictional waters on the site, the Corps will provide an approved JD to accomplish that result, as soon as is practicable.

This preliminary JD finds that there "may be" waters of the United States on the subject project site, and identifies all aquatic features on the site that could be affected by the proposed activity, based on the following information:

SUPPORTING DATA: Data reviewed for preliminary JD (check all that apply - checked items should be included in case file and, where checked and requested, appropriately reference sources below):
 Maps, plans, plots or plat submitted by or on behalf of the applicant/consultant: Data sheets prepared/submitted by or on behalf of the applicant/consultant. Office concurs with data sheets/delineation report. Office does not concur with data sheets/delineation report.
☐ Data sheets prepared by the Corps:
Corps navigable waters' study:
 U.S. Geological Survey Hydrologic Atlas: USGS NHD data. USGS 8 and 12 digit HUC maps. U.S. Geological Survey map(s). Cite scale & quad name: USDA Natural Resources Conservation Service Soil Survey. Citation:
☐ National wetlands inventory map(s). Cite name:
State/Local wetland inventory map(s):
☐ FEMA/FIRM maps:
☐ 100-year Floodplain Elevation is: (National Geodetic Vertical Datum of 1929) ☐ Photographs: ☐ Aerial (Name & Date): ☐ Other (Name & Date):
☐ Previous determination(s). File no. and date of response letter: ☐ Other information (please specify): See Attached.
IMPORTANT NOTE: The information recorded on this form has not necessarily been verified by the Corps and should not be relied upon for later jurisdictional determinations.
Merculoth Bitum
Signature and date of Signature and date of
Regulatory Project Manager person requesting preliminary JD (REQUIRED) (REQUIRED, unless obtaining the signature is impracticable)

Arborist Report

6201 Horseshoe Bar Road ±63-Acre Site Loomis, California

Prepared for: Tulip Asset LLC

Date: January 27, 2014



Table of Contents


1.0 Introduction	
3.0 Results and Discussion	
List of Figures	
Figure 1 — Site and Vicinity	.2
List of Tables	
Table 1 — Tree Rating System Table 2 — Number of Trees by Health and Structure Ratings	
List of Appendices	
Appendix A — Tree Survey Data Appendix B — Dead Trees Appendix C — Tree Locations Maps	

1.0 INTRODUCTION

This report presents the results of a tree survey conducted for portions of the ± 63 -acre 6201 Horseshoe Bar Road site located in the Town of Loomis, Placer County, California. The site is located just south of Interstate 80 and is bifurcated by Horseshoe Bar Road. The western half of the site is bordered on the south by Brace Road (**Figure 1**). The property is bounded on the east, south, and west by low-density residential development. Secret Ravine flows generally along the southeast boundary of the site and a tributary to it crosses the northeast corner of the site. The purpose of this report is to present information on the species, size, and condition of the trees on the property.

The entire site was previously surveyed in 2007, as documented in the *Arborist Report* dated October 10, 2007 prepared by Foothill Associates. While the 2007 report documented a total of 2,936 trees on the project site, this report focuses only on the potentially impacted areas. All trees within 30 feet of the conceptual plan site improvement boundary were reinventoried.

The Town of Loomis Ordinance for the Preservation of Heritage Trees regulates the removal of protected trees. Heritage trees include all native oak trees with a trunk diameter of at least six inches and other tree species with a trunk diameter of 19 inches at 54 inches above the ground. Eucalyptus (*Eucalyptus* sp.), alder (*Alnus rhombifolia*), cottonwood (*Populus fremontii*), pine (*Pinus* spp.), fruit trees, and willow (*Salix* spp.) trees of any size are exempted from the ordinance.



2.0 METHODS

The property was surveyed by International Society of Arboriculture (ISA) Certified Arborists during the month of December 2013. All living tagged trees were closely examined to determine their species type and diameter. A diameter tape was used to verify each trunk diameter at breast height (DBH) which is 54" above the ground. The measurement from the trunk to the end of the longest lateral limb was used as the dripline radius (DLR), which establishes the tree protection zone (TPZ) of the tree. All tagged trees that met the criteria for protection under the Town of Loomis Heritage Tree Ordinance were inventoried. All surveyed trees are identified with an aluminum tag or plastic flagging which corresponds to the numbering in **Appendix A**. Tree locations were previously surveyed by Burrell Engineering. No data were collected for dead trees, which are identified in **Appendix B**. The approximate locations of new trees tagged during this survey were located based on their position in relation to existing trees (**Appendix C**).

The health and structural condition of each tree was rated according to **Table 1**. The health rating considers factors such as the size, color, and density of the foliage; the amount of deadwood within the canopy; bud viability; evidence of wound closure; and the presence or evidence of stress, disease, nutrient deficiency, and insect infestation. The structural rating reflects the trunk and branch configuration; canopy balance; the presence of included bark and other structural defects such as decay; and the potential for structural failure. In cases where conditions fall between the Good, Fair, and Poor ratings, intermediate ratings Fair-Good and Fair-Poor were used.

Table 1 — Tree Rating System

Rating	Tree Health
Good	There is an average or below-average amount of deadwood/dieback with respect to the tree's size and growing environment; leaf size, color, and density are typical for the species; buds are normal size, viable, abundant, and uniform throughout the canopy; current and past growth increments are generally average or better; any callusing is vigorous. This health rating indicates that there is very little, if any, evidence of stress, disease, nutrient deficiency, and/or insect infestation.
Fair	There is an above-average amount of deadwood/dieback with respect to the tree's size and growing environment; leaf size, color, and density may be below what is typically expected for the species; buds are normal size and viable, but slightly sparse throughout the canopy; current and past growth increments may be below average; tree may be slow to callus around old wounds. This health rating indicates that there is moderate evidence of stress, disease, nutrient deficiency, and/or insect infestation.
Poor	There is an extreme amount of deadwood/dieback with respect to the tree's size and growing environment; leaf size, color, and density are clearly compromised; very few viable buds are present throughout the canopy; current and past growth increments are meager; no evidence of callusing around old wounds. This health rating indicates that there is widespread evidence of stress, disease, nutrient deficiency, and/or insect infestation.
	Tree Structure
Good	No wounds, cavities, decay, or indication of hollowness are evident in the root crown, trunk, or primary and secondary limbs; no anchor roots are exposed; no codominant branching or multiple trunk attachments are present; very little included bark at branch attachments exists; no dead primary or secondary limbs are present in canopy; there have been no major limb failures; limbs are not overburdened; branching structure is appropriate for species; any decay is limited to small dead branches/stubs. This structure rating represents a low potential for failure.
Fair	With respect to the size of the tree, small to moderate wounds, cavities, decay, and indication of hollowness may be evident in the root crown, trunk, and/or primary and secondary limbs; some anchor roots may be exposed; codominant branching or multiple trunk attachments may be present, but included bark does not exist or is not well developed; minor to moderate amounts of included bark at branch attachments may exist; there may be small to moderate amounts of large dead limbs in canopy, but there is no evidence of large limb failures; limbs may be slightly overburdened; branching structure and/or canopy balance may be moderately altered by the tree's growing environment. This structure rating represents a moderate potential for failure.
Poor	With respect to the size of the tree, significant wounds, cavities, decay, and/or indication of hollowness may be evident in the root crown, trunk, and/or primary and secondary limbs; anchor roots may be exposed and/or the tree may have lost anchorage; codominant branching or multiple trunk attachments may be present; significant amounts of included bark may exist in trunk and branch attachments; there may be significant amounts of large dead limbs in the canopy; there may be evidence of trunk or large limb failures; limbs may be severely overburdened; branching structure and/or canopy balance may be drastically altered by the tree's growing environment. This structure rating represents a high potential for failure.

A total of 1,214 trees, comprised of 679 interior live oaks (*Quercus wislizenii*), 526 valley oaks (*Quercus lobata*), and 9 blue oaks (*Quercus douglasii*), were inventoried on the site. Additionally, 52 dead trees were identified.

The inventoried trees are located only within the proposed project footprint and a 30-foot buffer surrounding it. The northwest quadrant has been used for agriculture in the past and is composed primarily of grassland with scattered groupings of trees. The southern section of the eastern half of the site is also open grassland with scattered trees and is currently used as horse pasture. The rest of the site is densely wooded, with a number of small drainages and swales running toward Secret Ravine.

The understory of the open areas is composed of annual grasses and forbs. The oak woodland understory includes poison oak (*Toxicodendron diversilobum*), Himalayan blackberry (*Rubus ameniacus*), toyon (*Heteromeles arbutifolia*), California coffeeberry (*Rhamnus californica*), California buckeye (*Aesculus californica*), and other grasses and forbs.

Table 2 shows the health condition by the structure rating with 1,036 trees (85 percent) rated as Fair or better, with a large proportion of trees (843 trees or 69 percent) in the Fair category. A total of 926 trees (76 percent) have a structure rating of Fair or better. **Appendix A** lists the data collected for each inventoried tree.

Health Good Fair-Good Fair Fair-Poor **Total Trees** Poor 2 173 279 459 Good 5 Structure Fair-Good 0 0 0 3 27 30 Fair 0 14 405 18 437 0 0 0 0 Fair-Poor 8 Poor 0 1 124 133 22 280 2 191 843 156 22 1214 **Total Trees**

Table 2 — Number of Trees by Health and Structure Ratings

Overall, the data show the site trees as in fair or better health and structure. Trees in the open-grown areas tend to have a fuller, more symmetrical crown, and usually show a better health and structure rating than suppressed trees under dense canopy. While trees with a Fair health rating have the potential to improve over time with the implementation of plant health care techniques, changes in environmental elements, etc.; trees with a Fair structure rating typically worsen over time as existing structural defects (e.g., decay and included bark) continue to exacerbate. For this reason, trees with a Fair structure rating may not be good candidates for preservation in proposed high-use areas.

Once improvement plans are finalized, the impacts to all inventoried trees should be assessed by an ISA Certified Arborist so that the appropriate recommendations can be provided.

Appendix A —	Tree S	Survey	Data
--------------	--------	--------	------

		# of		DLR		
Tree #	Species	Trunks	DBH (inches)	(feet)	Health	Structure
2	Valley Oak	2	17,24	40	Fair	Good
4	Valley Oak	1	17	25	Fair	Good
37	Interior Live Oak	3	14,12,6	20	Fair	Fair
65	Valley Oak	1	16	30	Fair-Good	Good
75	Valley Oak	1	19	30	Fair	Good
76	Valley Oak	2	16,8	30	Fair	Good
81	Valley Oak	1	22	50	Fair-Good	Good
84	Valley Oak	1	24	30	Fair	Fair-Good
94	Valley Oak	1	21	30	Fair	Good
99	Valley Oak	1	24	40	Fair	Good
118	Valley Oak	1	19	40	Fair-Good	Good
124	Valley Oak	1	15	30	Good	Good
129	Interior Live Oak	3	22,14,9	30	Fair-Good	Good
138	Valley Oak	1	14	25	Fair	Good
139	Valley Oak	1	12	25	Fair-Good	Good
141	Valley Oak	2	17,10	30	Fair-Good	Good
153	Valley Oak	1	19	30	Fair-Good	Good
157	Valley Oak	2	13,6	20	Fair	Good
166	Valley Oak	1	13	20	Fair	Fair-Good
172	Valley Oak	1	17	25	Fair	Good
176	Interior Live Oak	6	14,14,10,10,6,6	40	Fair-Good	Good
182	Valley Oak	1	10	10	Fair	Poor
190	Valley Oak	1	14	20	Fair	Fair
193	Valley Oak	1	13	20	Fair	Fair
197	Valley Oak	1	14	20	Fair	Fair
201	Interior Live Oak	6	8,6,6,6,6,6	15	Fair	Fair
202	Interior Live Oak	2	11,6	15	Fair	Fair
208	Interior Live Oak	2	9,9	25	Fair-Good	Good
319	Valley Oak	1	7	10	Fair	Fair
343	Valley Oak	2	14,8	30	Fair	Good
344	Valley Oak	2	11,12	40	Fair	Good
345	Interior Live Oak	1	7	10	Fair-Poor	Poor
347	Interior Live Oak	1	13	30	Fair	Fair
352	Interior Live Oak	6	6,5,11,8,7,11	30	Fair	Fair
353	Valley Oak	1	9	15	Fair	Fair
354	Interior Live Oak	1	6	20	Fair-Poor	Poor
355	Valley Oak	1	14	10	Fair	Poor
356	Valley Oak	1	13	10	Fair	Poor
358	Valley Oak	1	8	10	Fair-Poor	Fair
359	Valley Oak	1	20	40	Fair-Good	Good
360	Valley Oak	1	18	30	Fair-Good	Good
361	Valley Oak	1	15	25	Fair	Fair
362	Valley Oak	1	15	30	Fair	Fair

		# of	Tree Survey Da	DLR		
Tree #	Species	Trunks	DBH (inches)	(feet)	Health	Structure
363	Valley Oak	1	12	20	Fair	Fair
364	Valley Oak	1	8	10	Fair	Fair
365	Valley Oak	2	13,12	30	Fair	Fair
366	Valley Oak	1	10	15	Fair	Fair
367	Valley Oak	1	6	10	Fair	Fair
368	Interior Live Oak	1	9	15	Fair	Poor
369	Valley Oak	1	14	20	Fair	Fair
374	Interior Live Oak	1	7	15	Fair	Fair
375	Interior Live Oak	1	10	10	Fair-Poor	Poor
520	Interior Live Oak	4	12,8,10,13	40	Fair-Good	Good
521	Valley Oak	1	12	25	Fair	Good
523	Valley Oak	2	17,16	50	Fair-Good	Good
525	Interior Live Oak	1	18	50	Fair-Good	Good
526	Valley Oak	1	17	40	Fair-Good	Good
531	Interior Live Oak	2	6,4	15	Fair	Poor
539	Interior Live Oak	1	20	20	Fair	Fair
540	Interior Live Oak	4	10,7,7,6	30	Fair	Good
544	Interior Live Oak	1	19	40	Fair-Good	Good
550	Interior Live Oak	2	12,8	30	Fair	Good
713	Interior Live Oak	1	9		Poor	Poor
719	Interior Live Oak	3	10,10,6	30	Fair-Good	Good
746	Interior Live Oak	2	6,3	10	Fair-Poor	Poor
784	Interior Live Oak	1	7	15	Fair	Fair
787	Interior Live Oak	3	9,8,7	30	Fair	Fair
819	Interior Live Oak	1	5	10	Fair-Poor	Poor
830	Interior Live Oak	1	7	15	Fair	Fair
852	Interior Live Oak	2	13,11	30	Fair	Fair
854	Interior Live Oak	1	6	10	Fair-Poor	Poor
869	Interior Live Oak	1	7	5	Fair	Poor
873	Interior Live Oak	1	8	10	Fair-Poor	Poor
915	Valley Oak	1	29,11	50	Fair	Good
917	Valley Oak	1	19	25	Fair-Good	Good
925	Valley Oak	1	13	20	Fair	Fair
976	Valley Oak	1	19	20	Fair	Poor
1038	Valley Oak	1	16	35	Fair	Fair-Good
1045	Interior Live Oak	1	14	30	Fair	Poor
1046	Interior Live Oak	1	6	10	Fair-Poor	Poor
1128	Interior Live Oak	1	8	10	Fair-Poor	Poor
1273	Valley Oak	1	18	20	Fair	Poor
1274	Interior Live Oak	1	10	15	Fair	Fair
1281	Interior Live Oak	1	8	15	Fair	Poor
1296	Interior Live Oak	1	11	25	Fair	Fair
1617	Valley Oak	1	16	40	Fair-Good	Good

Tree #	Species	# of Trunks	DBH (inches)	DLR (feet)	Health	Structure
1620	Interior Live Oak	1	8	15	Fair-Poor	Poor
1624	Valley Oak	1	14	20	Fair	Fair
1875	Interior Live Oak	1	17	30	Fair	Fair
1876	Interior Live Oak	1	11	20	Fair	Fair-Poor
1877	Interior Live Oak	2	12,8	30	Fair	Fair
1878	Interior Live Oak	2	9,5	30	Fair	Fair
1879	Interior Live Oak	1	8	20	Fair	Fair
1880	Interior Live Oak	6	11,12,13,11,7,8	60	Fair-Good	Good
1881	Interior Live Oak	2	13,9	30	Fair-Good	Good
1891	Interior Live Oak	1	10	30	Fair	Good
1892	Interior Live Oak	1	10	25	Fair	Fair
1926	Interior Live Oak	1	12	30	Fair	Fair
1927	Interior Live Oak	3	15,10,8	40	Fair	Good
1945	Interior Live Oak	1	7	10	Fair	Poor
1946	Interior Live Oak	1	8	20	Fair	Poor
1947	Interior Live Oak	1	10	20	Fair	Poor
1948	Interior Live Oak	2	6,5	10	Fair	Poor
1949	Interior Live Oak	2	9,11	30	Fair	Good
1953	Interior Live Oak	1	6	15	Fair	Fair
1954	Valley Oak	1	8	10	Fair	Poor
1955	Interior Live Oak	3	17,11,7	45	Fair-Good	Good
1966	Valley Oak	1	9	15	Fair	Poor
1967	Valley Oak	1	10	10	Poor	Poor
1969	Interior Live Oak	1	8	20	Fair	Fair
1970	Interior Live Oak	1	6	10	Fair	Fair
1971	Interior Live Oak	2	7,6	10	Fair	Fair
1972	Valley Oak	1	7	10	Fair	Poor
1973	Valley Oak	1	9	15	Fair	Poor
1974	Valley Oak	2	17,14	50	Fair	Good
1979	Interior Live Oak	1	14	40	Fair	Good
1981	Valley Oak	1	7	10	Fair-Poor	Poor
1982	Valley Oak	1	9	10	Fair	Fair
1983	Valley Oak	1	6	10	Fair	Poor
1984	Interior Live Oak	1	11	15	Fair-Poor	Poor
1986	Interior Live Oak	1	10	20	Fair-Good	Good
2005	Interior Live Oak	3	26,4,3	50	Fair	Good
2007	Interior Live Oak	2	9,8	30	Fair	Fair-Good
2008	Interior Live Oak	2	6,8	15	Fair	Fair
2009	Interior Live Oak	2	9,6	20	Fair	Fair
2010	Interior Live Oak	1	13	30	Fair	Fair
2028	Interior Live Oak	2	10,5	15	Fair	Poor
2029	Interior Live Oak	1	8	20	Fair	Fair
2031	Interior Live Oak	1	7	15	Fair	Fair

		# of	Tree Survey Da	DLR		
Tree #	Species	Trunks	DBH (inches)	(feet)	Health	Structure
2032	Interior Live Oak	3	10,8,4	30	Fair	Fair
2033	Interior Live Oak	1	8	20	Fair	Fair
2034	Interior Live Oak	1	8	15	Fair	Fair
2040	Interior Live Oak	4	6,6,5,4	20	Fair-Good	Good
2041	Interior Live Oak	3	9,8,6	20	Fair	Poor
2042	Interior Live Oak	2	6,5	10	Fair	Poor
2044	Interior Live Oak	2	9,6	20	Fair-Poor	Poor
2045	Interior Live Oak	1	10	20	Fair	Fair
2046	Interior Live Oak	1	10	20	Fair	Fair
2077	Interior Live Oak	1	6	10	Fair-Poor	Poor
2078	Valley Oak	2	12,6	15	Fair	Fair
2079	Valley Oak	1	30	20	Poor	Poor
2080	Valley Oak	2	12,7	20	Fair	Poor
2082	Interior Live Oak	2	10,9	30	Fair	Fair
2083	Valley Oak	2	9,7	15	Fair	Poor
2084	Interior Live Oak	1	7	10	Fair-Poor	Poor
2085	Interior Live Oak	2	17,6	30	Fair-Good	Good
2086	Interior Live Oak	1	9	30	Fair	Fair
2087	Valley Oak	1	10	15	Fair	Fair-Poor
2119	Valley Oak	1	14	20	Fair	Fair
2120	Valley Oak	1	8	15	Fair	Fair
2209	Interior Live Oak	1	16	40	Fair-Good	Good
2210	Interior Live Oak	1	13	20	Fair	Fair
2215	Valley Oak	1	10	15	Fair	Fair
2216	Valley Oak	1	13	15	Fair-Poor	Poor
2220	Interior Live Oak	1	14	25	Fair	Fair
2226	Interior Live Oak	1	15	10	Fair-Poor	Poor
2228	Valley Oak	1	12	15	Fair	Poor
2231	Interior Live Oak	1	14	10	Fair-Poor	Poor
2232	Valley Oak	1	12	20	Fair	Poor
2238	Interior Live Oak	1	18	15	Fair-Poor	Poor
2239	Interior Live Oak	1	11	20	Fair	Fair
2242	Valley Oak	1	18	40	Fair	Fair
2244	Valley Oak	1	13	10	Fair-Poor	Poor
2250	Valley Oak	1	8	10	Fair-Poor	Poor
2253	Interior Live Oak	5	11,9,10,9,6	40	Fair-Good	Good
2256	Interior Live Oak	1	8	15	Fair-Poor	Poor
2258	Valley Oak	1	18	15	Fair	Fair
2259	Interior Live Oak	1	15	15	Poor	Poor
2260	Interior Live Oak	1	7	15	Fair	Good
2269	Interior Live Oak	1	14	12	Fair	Fair
2274	Valley Oak	1	19	30	Fair-Poor	Poor
2275	Interior Live Oak	1	20	25	Fair-Poor	Good

		# of	Tree Survey Da	DLR		
Tree #	Species	Trunks	DBH (inches)	(feet)	Health	Structure
2278	Valley Oak	1	9	15	Fair	Fair
2279	Valley Oak	1	9	20	Fair	Poor
2280	Valley Oak	1	13	20	Fair-Poor	Poor
2281	Valley Oak	1	9	10	Fair-Poor	Poor
2282	Valley Oak	1	9	15	Fair	Fair
2285	Blue Oak	1	28	40	Fair	Fair
2287	Valley Oak	1	10	10	Fair	Fair
2288	Valley Oak	1	7	10	Fair-Poor	Poor
2289	Valley Oak	1	7	10	Fair	Poor
2290	Valley Oak	1	9	20	Fair	Fair
2292	Valley Oak	1	17	25	Fair	Fair
2293	Valley Oak	1	13	20	Fair-Poor	Poor
2295	Valley Oak	1	12	10	Fair-Poor	Poor
2300	Valley Oak	1	10	15	Fair	Poor
2338	Valley Oak	1	34	30	Fair	Fair
2361	Valley Oak	1	18	30	Fair	Good
2394	Interior Live Oak	2	12, 4	20	Fair	Fair
2395	Interior Live Oak	3	8,4,6	15	Fair	Fair
2397	Interior Live Oak	8	8,6,9,8,11,5,10,6	20	Fair	Fair
2400	Interior Live Oak	1	7	10	Fair-Poor	Poor
2401	Interior Live Oak	2	12,7	25	Fair	Good
2403	Interior Live Oak	2	9,6	25	Fair	Fair
2405	Interior Live Oak	2	10,10	30	Fair	Good
2406	Interior Live Oak	1	6	15	Fair	Fair
2408	Interior Live Oak	1	10	25	Fair	Fair
2408	Interior Live Oak	1	18	20	Fair	Fair
2409	Valley Oak	1	9	15	Fair	Fair
2410	Interior Live Oak	1	10	15	Fair	Fair
2411	Interior Live Oak	1	16	20	Fair	Fair
2412	Valley Oak	1	14	30	Fair	Fair
2413	Valley Oak	1	10	20	Fair	Fair
2414	Valley Oak	1	7	10	Fair	Poor
2415	Interior Live Oak	2	9,8	20	Fair	Fair
2416	Interior Live Oak	3	8,7,3	30	Fair	Fair-Good
2417	Interior Live Oak	6	11,8,7,5,4,4	30	Fair-Good	Good
2418	Valley Oak	2	9,7	30	Fair	Fair
2419	Interior Live Oak	2	8	15	Fair	Fair
2420	Valley Oak	1	11	20	Fair	Fair
2421	Interior Live Oak	2	11,6	20	Fair	Fair
2424	Valley Oak	1	9	15	Fair-Good	Good
2425	Interior Live Oak	4	9,7,7,7	20	Fair	Poor
2426	Interior Live Oak	3	10,6,6	20	Fair	Good
2427	Valley Oak	1	9	15	Fair	Fair

		# of	Tee Survey Da	DLR		
Tree #	Species	Trunks	DBH (inches)	(feet)	Health	Structure
2428	Valley Oak	1	10	15	Fair	Fair
2429	Interior Live Oak	1	11	15	Fair	Good
2430	Interior Live Oak	2	12,10	35	Fair-Good	Good
2431	Interior Live Oak	1	10	25	Fair-Good	Good
2432	Interior Live Oak	1	12	26	Fair-Good	Good
2434	Interior Live Oak	1	11	10	Poor	Poor
2435	Interior Live Oak	2	10,3	25	Fair	Fair
2436	Interior Live Oak	1	10	20	Fair	Fair
2437	Interior Live Oak	1	17	30	Fair-Good	Good
2438	Interior Live Oak	1	8	15	Fair	Fair
2439	Valley Oak	1	10	10	Poor	Poor
2440	Valley Oak	1	10,8	20	Fair	Poor
2441	Valley Oak	1	10	12	Fair	Poor
2443	Interior Live Oak	1	10	15	Fair	Poor
2443	Valley Oak	1	9	15	Fair	Fair
2444	Interior Live Oak	2	7,4	10	Fair-Poor	Poor
2445	Interior Live Oak	2	11,10	25	Fair	Good
2446	Interior Live Oak	2	16,14	15	Poor	Poor
2449	Valley Oak	1	8	15	Fair	Poor
2450	Interior Live Oak	3	8,6,6	30	Fair-Good	Good
2452	Valley Oak	1	6,3	5	Fair-Good	Poor
2867	Interior Live Oak	2	7,6	30	Fair	Good
2868	Interior Live Oak	1	12	40	Fair-Good	Good
2870	Interior Live Oak	1	8	20	Fair	Fair
2871	Interior Live Oak	1	6	10	Fair	Fair
2872	Interior Live Oak	2	7,7	15	Fair	Fair
2873	Interior Live Oak	1	6	10	Fair	Poor
2874	Interior Live Oak	2	12,5	30	Fair	Fair
2877	Interior Live Oak	1	10	20	Fair	Fair
2879	Interior Live Oak	1	9	20	Fair	Fair
2880	Interior Live Oak	4	12,7,9,7	30	Fair	Fair
2888	Interior Live Oak	1	10	40	Fair	Good
2890	Interior Live Oak	1	8	20	Fair	Fair
2891	Interior Live Oak	1	7	10	Fair-Poor	Poor
2894	Interior Live Oak	1	9	20	Fair	Fair
2895	Interior Live Oak	1	7	10	Fair	Fair
2896	Interior Live Oak	1	10	30	Fair	Good
2897	Interior Live Oak	2	14,12	40	Fair	Good
2905	Interior Live Oak	7	9,7,5,8,6,5,8	50	Fair	Fair
2915	Interior Live Oak	1	10	20	Fair	Fair
2916	Blue Oak	1	6	5	Fair-Poor	Poor
2946	Interior Live Oak	1	14	30	Fair-Good	Fair
2970	Interior Live Oak	1	11	30	Fair-Good	Good

		# of		DLR		
Tree #	Species	Trunks	DBH (inches)	(feet)	Health	Structure
2972	Interior Live Oak	2	19,8	10	Fair-Poor	Poor
2974	Interior Live Oak	1	14	20	Fair-Poor	Poor
2975	Interior Live Oak	1	8	20	Fair	Fair
2976	Interior Live Oak	1	11	20	Fair-Good	Good
2977	Interior Live Oak	2	14,13	50	Fair-Good	Good
2979	Interior Live Oak	1	6	16	Fair-Poor	Poor
2980	Interior Live Oak	1	14	60	Fair-Good	Good
2981	Interior Live Oak	2	5,2	10	Fair-Poor	Poor
2982	Interior Live Oak	1	10	20	Fair	Fair
2983	Interior Live Oak	1	7	10	Fair-Poor	Poor
2984	Interior Live Oak	1	7	10	Fair-Poor	Poor
2986	Valley Oak	1	16	50	Fair-Good	Good
2987	Interior Live Oak	2	13,5	30	Fair	Good
2989	Interior Live Oak	1	8	15	Fair-Poor	Poor
2990	Interior Live Oak	1	11	30	Fair-Good	Fair
2991	Interior Live Oak	3	10,6,4	20	Fair	Fair
2992	Interior Live Oak	3	9,14,9	50	Fair-Good	Fair
2993	Interior Live Oak	4	14,8,6,9	50	Fair	Good
2994	Interior Live Oak	1	10	40	Fair	Fair
2995	Interior Live Oak	3	10,8,5	20	Fair-Poor	Poor
2996	Interior Live Oak	3	7,9,9	25	Fair	Fair
2997	Interior Live Oak	1	10	15	Fair	Fair
2998	Interior Live Oak	2	11,14	30	Fair-Good	Good
2999	Interior Live Oak	1	11	20	Fair-Poor	Fair
3000	Interior Live Oak	3	6,6,4	20	Fair-Poor	Fair
3001	Interior Live Oak	1	9	10	Fair-Poor	Fair
3002	Interior Live Oak	3	8,8,3	25	Fair-Poor	Fair
3003	Interior Live Oak	4	10,8,8,7	30	Fair-Good	Good
3004	Interior Live Oak	2	10,7	20	Fair	Fair
3005	Interior Live Oak	2	11,8	30	Fair	Fair
3006	Valley Oak	1	15	20	Fair-Poor	Fair
3007	Interior Live Oak	1	15	25	Fair	Fair
3009	Interior Live Oak	2	8,5	15	Fair	Fair
3010	Interior Live Oak	1	6	10	Fair	Poor
3011	Interior Live Oak	3	8,7,6	25	Fair	Fair
3012	Interior Live Oak	1	11	15	Fair	Fair
3013	Interior Live Oak	1	9	20	Fair	Good
3014	Interior Live Oak	1	8	10	Fair	Poor
3015	Interior Live Oak	1	10	10	Fair	Fair
3016	Interior Live Oak	2	7,7	15	Fair	Poor
3017	Interior Live Oak	1	8	10	Fair	Poor
3018	Interior Live Oak	3	8,6,7	20	Fair	Fair
3019	Interior Live Oak	3	9,10,7	30	Fair	Fair

		# of	Tree Survey Da	DLR		
Tree #	Species	Trunks	DBH (inches)	(feet)	Health	Structure
3020	Interior Live Oak	1	16	35	Fair	Good
3021	Interior Live Oak	1	6	10	Fair	Poor
3022	Interior Live Oak	2	14,11	25	Fair-Poor	Fair
3023	Valley Oak	1	8	15	Fair	Fair
3024	Interior Live Oak	2	12,10	20	Fair	Fair
3025	Interior Live Oak	3	13,8,7	30	Fair	Fair
3026	Interior Live Oak	2	8,6	20	Fair-Good	Good
3027	Interior Live Oak	5	11,8,6,6,9	60	Fair-Good	Good
3032	Interior Live Oak	1	6	10	Fair	Fair
3034	Interior Live Oak	4	6,10,6,7	30	Fair	Fair
3036	Interior Live Oak	1	16	40	Fair	Fair
3037	Interior Live Oak	1	7	10	Fair	Poor
3038	Blue Oak	1	7	10	Fair	Poor
3040	Interior Live Oak	1	8	10	Fair	Poor
3041	Interior Live Oak	2	9,9	30	Fair	Fair
3042	Interior Live Oak	1	12	50	Fair-Good	Good
3043	Interior Live Oak	1	7	30	Fair	Good
3044	Interior Live Oak	4	7,6,10,12	30	Fair	Good
3045	Interior Live Oak	5	12,8,8,7,8	40	Fair	Fair
3046	Interior Live Oak	2	7,6	20	Fair	Fair
3047	Interior Live Oak	2	12,6	20	Fair	Fair
3048	Interior Live Oak	2	17,7	40	Fair-Good	Good
3049	Interior Live Oak	1	12	30	Fair	Good
3050	Interior Live Oak	1	9	20	Fair	Poor
3051	Interior Live Oak	3	13,9,7	50	Fair	Good
3052	Interior Live Oak	1	10	25	Fair	Fair
3053	Blue Oak	2	8,6	15	Fair	Fair
3054	Interior Live Oak	1	13	20	Fair-Good	Good
3055	Interior Live Oak	2	9,7	20	Fair	Good
3056	Interior Live Oak	1	11	15	Fair	Fair
3057	Interior Live Oak	3	7,5,5	15	Fair	Fair
3125	Interior Live Oak	1	7	5	Fair-Poor	Poor
3126	Interior Live Oak	1	8	15	Fair	Fair
3129	Interior Live Oak	2	7,5	15	Fair	Fair
3130	Interior Live Oak	2	9,5	15	Fair	Fair
3135	Interior Live Oak	2	9,4	20	Fair	Fair
3136	Interior Live Oak	3	9,6,3	30	Fair	Good
3137	Interior Live Oak	6	11,9,8,6,5,3	60	Fair	Good
3138	Interior Live Oak	1	10	15	Fair	Fair
3139	Interior Live Oak	1	7	15	Fair	Fair
3140	Interior Live Oak	1	6	10	Fair	Fair
3141	Interior Live Oak	1	9	20	Fair	Good
3142	Interior Live Oak	2	13,9	50	Fair-Good	Good

Tree #	Species	# of Trunks	DBH (inches)	DLR (feet)	Health	Structure
3144	Interior Live Oak	2	8,6	20	Fair	Good
3153	Interior Live Oak	3	22,15,8	50	Fair-Good	Good
3154	Interior Live Oak	2	15,13	40	Fair-Good	Good
3155	Interior Live Oak	1	6	10	Fair	Fair
3156	Valley Oak	1	9	10	Fair	Poor
3157	Valley Oak	2	12,5	20	Fair	Fair
3158	Interior Live Oak	1	12	30	Fair	Good
3159	Interior Live Oak	1	5	10	Fair-Poor	Poor
3160	Interior Live Oak	1	11	25	Fair	Good
3162	Interior Live Oak	2	10,9	30	Fair	Good
3163	Interior Live Oak	3	9,7,8	20	Fair-Poor	Poor
3164	Interior Live Oak	1	12	25	Fair-Good	Good
3165	Interior Live Oak	1	9	20	Fair	Fair
3166	Interior Live Oak	3	8,6,5	30	Fair	Fair
3167	Interior Live Oak	1	7	10	Fair-Poor	Poor
3168	Interior Live Oak	1	6	10	Poor	Poor
3169	Interior Live Oak	1	6	10	Poor	Poor
3170	Interior Live Oak	1	10	20	Fair-Good	Good
3176	Interior Live Oak	2	8,5	20	Fair	Fair
3177	Interior Live Oak	2	9,7	30	Fair-Good	Good
3178	Interior Live Oak	1	8	25	Fair	Fair
3179	Interior Live Oak	1	6	10	Fair-Poor	Poor
3184	Interior Live Oak	3	8,9,6	30	Fair	Good
3185	Interior Live Oak	1	7	15	Fair	Good
3221	Interior Live Oak	1	13	30	Fair-Good	Good
3222	Interior Live Oak	2	8,9	30	Fair	Poor
3223	Interior Live Oak	1	8	20	Fair-Poor	Poor
3224	Interior Live Oak	4	8,7,6,8	20	Fair	Fair
3225	Interior Live Oak	1	6	12	Fair-Poor	Poor
3226	Interior Live Oak	2	9,7	40	Fair	Good
3227	Interior Live Oak	1	7	10	Fair-Poor	Poor
3228	Interior Live Oak	1	16	30	Fair-Good	Good
3229	Interior Live Oak	1	8	10	Fair-Poor	Poor
3230	Interior Live Oak	2	13,11	30	Fair-Good	Good
3231	Interior Live Oak	2	7,16	30	Fair-Poor	Poor
3232	Interior Live Oak	1	18	40	Fair-Good	Good
3233	Interior Live Oak	1	15	20	Fair	Fair
3234	Interior Live Oak	1	10	10	Fair	Poor
3235	Interior Live Oak	3	22,11,6	40	Fair-Good	Good
3236	Interior Live Oak	2	19,15	40	Fair-Good	Good
3237	Interior Live Oak	2	8,7	20	Fair	Fair
3238	Interior Live Oak	1	7	15	Fair	Fair
3239	Interior Live Oak	1	7	10	Fair-Poor	Poor

		# of		DLR		
Tree #	Species	Trunks	DBH (inches)	(feet)	Health	Structure
3240	Interior Live Oak	2	8,7	40	Fair	Fair
3241	Interior Live Oak	1	9	15	Fair	Poor
3242	Valley Oak	1	10	20	Fair	Fair
3243	Interior Live Oak	1	9	30	Fair-Good	Good
3251	Interior Live Oak	1	9	20	Fair	Poor
3252	Interior Live Oak	1	11	25	Fair	Fair
3253	Interior Live Oak	1	12	20	Fair	Fair
3343	Valley Oak	1	12	15	Poor	Poor
3344	Interior Live Oak	1	8	20	Fair	Fair-Poor
3345	Valley Oak	1	9	15	Fair	Poor
3346	Valley Oak	1	6	5	Fair-Poor	Poor
3347	Valley Oak	1	13	20	Fair	Fair
3348	Interior Live Oak	4	9,10,7,6	30	Fair	Good
3349	Interior Live Oak	1	9	10	Fair	Poor
3350	Interior Live Oak	2	9,6	20	Fair	Fair
3351	Interior Live Oak	2	10,8	10	Fair	Poor
3352	Interior Live Oak	1	8	10	Fair	Poor
3353	Interior Live Oak	2	7,6	10	Fair	Poor
3354	Interior Live Oak	5	11,10,6,6,7	25	Fair	Fair
3355	Interior Live Oak	1	12	20	Fair	Good
3356	Interior Live Oak	1	9	10	Fair	Fair
3358	Interior Live Oak	5	9,13,4,4,6	50	Fair-Good	Good
3359	Interior Live Oak	3	7,7,7	30	Fair	Good
3360	Interior Live Oak	1	11	20	Fair-Good	Good
3361	Interior Live Oak	1	7	15	Fair	Poor
3362	Interior Live Oak	3	6,6	20	Fair	Poor
3364	Interior Live Oak	5	9,6,6,3,3	25	Fair	Fair
3377	Interior Live Oak	1	6	10	Fair-Poor	Poor
3378	Interior Live Oak	2	12,12	30	Fair-Good	Good
3379	Interior Live Oak	1	9	20	Fair	Fair
3380	Interior Live Oak	1	8	20	Fair	Fair
3396	Interior Live Oak	1	6	10	Fair-Poor	Poor
3397	Interior Live Oak	2	8,4	15	Fair	Poor
3399	Interior Live Oak	1	10	25	Fair	Fair
4045	Interior Live Oak	2	11,16	25	Fair	Fair
4501	Valley Oak	1	8	10	Fair	Poor
4502	Interior Live Oak	1	14	20	Fair-Good	Good
4503	Valley Oak	1	13	12	Fair	Fair
4504	Valley Oak	1	7	8	Fair	Poor
4601	Interior Live Oak	1	7	15	Fair	Fair
4602	Valley Oak	1	7	10	Fair	Poor
4603	Interior Live Oak	1	7	15	Fair	Fair
4604	Valley Oak	2	15,12	25	Fair	Good

Tree #	Species	# of Trunks	DBH (inches)	DLR (feet)	Health	Structure
4605	Interior Live Oak	2	9,4	10	Fair	Fair
4606	Valley Oak	1	7	10	Fair-Poor	Poor
4607	Interior Live Oak	4	7,4,4,3	15	Fair	Good
4608	Valley Oak	1	17	30	Fair	Good
4609	Valley Oak	1	7	12	Fair-Good	Good
4610	Valley Oak	1	6	10	Fair	Fair
4611	Valley Oak	1	6	5	Fair	Poor
4612	Valley Oak	1	7	10	Fair	Fair
4613	Interior Live Oak	1	7	12	Fair-Good	Fair
4614	Interior Live Oak	5	7,4,4,4,4	25	Fair	Fair
4615	Valley Oak	1	7	10	Fair	Poor
4616	Interior Live Oak	2	7,7	15	Fair-Poor	Poor
4617	Interior Live Oak	3	9,7,7	15	Fair	Fair-Good
4618	Valley Oak	1	8	15	Fair	Fair
4619	Interior Live Oak	1	7	10	Fair	Fair
4620	Valley Oak	1	7	8	Fair	Fair
4621	Interior Live Oak	2	6,5	15	Fair-Good	Good
4622	Interior Live Oak	1	7	10	Fair	Fair
4623	Interior Live Oak	1	7	15	Fair-Poor	Good
4624	Interior Live Oak	1	6	10	Fair	Poor
4625	Valley Oak	1	6	8	Fair	Poor
4626	Valley Oak	1	9	15	Fair	Good
4627	Valley Oak	1	9	15	Fair	Good
4628	Interior Live Oak	2	6,4	15	Fair	Fair
4629	Valley Oak	1	9	15	Fair	Fair
4630	Valley Oak	1	9	20	Fair	Fair
4631	Interior Live Oak	1	10	15	Fair	Good
4632	Interior Live Oak	1	7	10	Fair	Fair
4633	Interior Live Oak	1	7	10	Fair	Poor
4634	Interior Live Oak	1	6	15	Fair-Poor	Poor
4635	Interior Live Oak	1	7	10	Fair	Poor
4636	Interior Live Oak	1	7	15	Fair	Fair
4637	Interior Live Oak	1	20	8	Poor	Poor
4638	Interior Live Oak	1	6	10	Fair	Fair
4639	Valley Oak	1	7	10	Fair	Fair
4642	Interior Live Oak	1	6	12	Fair	Fair
4644	Interior Live Oak	2	8,8	20	Fair-Poor	Poor
4645	Interior Live Oak	2	7,5	10	Fair	Poor
4647	Interior Live Oak	1	7	10	Fair-Poor	Poor
4648	Interior Live Oak	2	10,8	20	Fair	Fair
4649	Interior Live Oak	2	7,6	10	Fair	Fair
4650	Interior Live Oak	2	10,6	10	Fair	Poor
4651	Interior Live Oak	2	8,6	15	Fair	Fair

Tree #	Species	# of Trunks	DBH (inches)	DLR (feet)	Health	Structure
4652	Valley Oak	1	8	10	Fair-Poor	Poor
4653	Interior Live Oak	1	7	15	Fair	Fair
4654	Interior Live Oak	2	7,3	10	Fair	Fair
4655	Interior Live Oak	2	8,5	15	Fair	Fair
4656	Interior Live Oak	1	9	15	Fair	Fair
4657	Interior Live Oak	1	10	12	Fair	Fair
4658	Interior Live Oak	2	7,4	10	Fair	Poor
4659	Interior Live Oak	1	7	12	Fair	Fair
4660	Interior Live Oak	2	7,7	17	Fair-Good	Good
4661	Valley Oak	1	6	10	Fair-Poor	Poor
4671	Interior Live Oak	2	6,6	15	Fair-Poor	Poor
5000	Interior Live Oak	1	6	15	Fair	Poor
5001	Interior Live Oak	1	8	20	Fair-Good	Good
B2	Valley Oak	1	33	50	Fair-Good	Good
B4	Valley Oak	1	7	10	Fair	Fair
B5	Valley Oak	2	14,13	20	Fair	Good
B7	Valley Oak	2	12,6	15	Fair	Fair-Poor
B8	Valley Oak	1	12	15	Fair	Fair
B9	Valley Oak	1	12	20	Fair	Fair
B10	Valley Oak	1	23	30	Fair	Good
B11	Valley Oak	2	16,13	25	Fair	Fair
B12	Interior Live Oak	1	16	20	Fair	Good
B14	Valley Oak	1	12	30	Fair	Good
B15	Valley Oak	2	11,6	20	Fair	Fair
B16	Valley Oak	1	16	30	Fair-Good	Good
B17	Interior Live Oak	2	18,23	25	Fair	Good
B18	Interior Live Oak	1	23	30	Fair	Good
B20	Valley Oak	1	17	25	Fair	Good
B21-C	Valley Oak	1	22	25	Fair	Good
B22	Valley Oak	1	14	15	Fair	Fair
B23	Valley Oak	1	11	15	Fair	Fair
B24	Valley Oak	1	8	15	Fair	Fair
B25	Valley Oak	1	11	15	Fair	Fair
B26	Valley Oak	1	10	12	Fair	Fair
B27	Valley Oak	2	15,14	25	Fair	Good
B29	Valley Oak	1	14	20	Fair	Fair
B30	Valley Oak	1	15	30	Fair	Fair-Good
B31	Valley Oak	2	16,14	40	Fair	Good
B32	Valley Oak	1	12	25	Fair	Good
B33	Valley Oak	1	16	40	Fair-Good	Good
B34	Valley Oak	1	12	10	Fair	Poor
B35	Valley Oak	1	11	20	Fair	Fair
B36	Valley Oak	1	10	15	Fair	Fair

		# of	Tee Survey Da	DLR		G
Tree #	Species	Trunks	DBH (inches)	(feet)	Health	Structure
B37	Valley Oak	1	14	30	Fair	Good
B38	Valley Oak	1	13	12	Fair	Fair
B39	Valley Oak	1	9	10	Fair-Poor	Poor
B40	Interior Live Oak	1	9	15	Fair	Fair
B41	Valley Oak	1	10	15	Fair	Fair
B42	Valley Oak	3	12,11,6	30	Fair	Fair
B43	Interior Live Oak	2	12,10	40	Fair-Good	Good
B44	Interior Live Oak	1	10	20	Fair	Fair
B45	Interior Live Oak	2	12,10	30	Fair	Good
B46	Interior Live Oak	2	9,8	20	Fair	Fair
B47	Valley Oak	1	12	15	Fair	Fair
B48	Valley Oak	1	12	15	Fair	Fair
B50	Valley Oak	1	12	20	Fair	Fair
B51	Valley Oak	1	12	10	Fair-Poor	Poor
B52	Valley Oak	2	10,10	15	Fair	Fair
B54	Valley Oak	1	7	10	Fair	Poor
B55	Valley Oak	1	6	5	Fair-Poor	Poor
B56	Valley Oak	1	7	10	Fair	Poor
B57	Valley Oak	1	9	10	Fair	Poor
B59	Valley Oak	1	6	10	Fair-Poor	Poor
B60	Valley Oak	2	8,8	15	Fair	Fair
B61	Valley Oak	1	10	15	Fair	Fair
B62	Valley Oak	1	10	10	Fair-Poor	Poor
B63	Valley Oak	1	8	10	Fair	Poor
B64	Interior Live Oak	3	9,7,5	20	Fair	Fair
B65	Valley Oak	1	12	30	Fair-Good	Good
B66	Valley Oak	1	15	20	Fair	Fair-Good
B67	Valley Oak	1	9	10	Fair	Poor
B68	Valley Oak	1	12	10	Fair	Poor
B69	Valley Oak	1	10	10	Fair	Poor
B70	Valley Oak	2	15,9	20	Fair	Fair
B71	Valley Oak	2	9,4	15	Fair	Poor
B72	Valley Oak	1	10	15	Fair	Poor
B73	Valley Oak	2	13,6	20	Fair	Fair
B74	Valley Oak	1	13	15	Fair	Fair
B75	Valley Oak	2	13,7	25	Fair	Good
B76	Valley Oak	1	11	15	Fair	Fair
B77	Valley Oak	1	12	15	Fair	Fair-Good
B78	Valley Oak	1	15	30	Fair-Good	Good
B79	Valley Oak	1	14	25	Fair-Good	Good
B80	Interior Live Oak	1	15	30	Fair-Good	Good
B81	Valley Oak	2	9,7	10	Fair	Fair
B82	Interior Live Oak	1	13	20	Fair	Fair

		# of	Tree Survey Da	DLR H		
Tree #	Species	Trunks	DBH (inches)	(feet)	Health	Structure
B84	Valley Oak	1	10	15	Fair	Fair
B85	Interior Live Oak	1	11	15	Fair	Fair
B86	Interior Live Oak	1	12	15	Fair-Good	Fair
B87	Interior Live Oak	2	15,14	30	Fair	Good
B88	Interior Live Oak	3	10,7,8	25	Fair	Good
B89	Interior Live Oak	4	11,10,9,8	25	Fair	Good
B90	Valley Oak	1	13	20	Fair	Fair-Good
B91	Valley Oak	2	12,10	20	Fair	Good
B92	Interior Live Oak	2	12,12	15	Fair	Good
B93	Interior Live Oak	5	13,13,11,10,9	30	Fair	Good
B94	Interior Live Oak	1	10	15	Fair-Good	Good
B95	Interior Live Oak	1	25	25	Fair	Good
B96	Interior Live Oak	4	14,14,6,14	25	Fair	Good
B97	Valley Oak	1	14	30	Fair-Good	Good
B98	Valley Oak	1	16	30	Fair-Good	Good
B99	Valley Oak	1	14	30	Fair-Good	Good
B100	Valley Oak	1	13	20	Fair	Good
B101	Valley Oak	1	13	20	Fair	Good
B102	Valley Oak	1	19	30	Fair	Good
B103	Valley Oak	1	22	40	Fair-Good	Good
B104	Valley Oak	1	16	40	Fair	Good
B105	Valley Oak	1	15	20	Fair-Good	Fair-Good
B106	Interior Live Oak	3	14,12,12	40	Fair-Good	Good
B107	Valley Oak	1	17	30	Fair	Good
B108	Valley Oak	1	16	40	Fair-Good	Good
B110	Valley Oak	1	12	15	Fair	Fair-Good
B111	Valley Oak	1	8	15	Fair	Fair
B112	Valley Oak	1	13	25	Fair	Good
B113	Valley Oak	1	18	40	Fair-Good	Good
B114	Valley Oak	1	14	20	Fair	Fair
B115	Valley Oak	1	10	20	Fair-Good	Good
B116	Valley Oak	1	10	10	Fair	Fair
B117	Valley Oak	1	13	20	Fair	Fair
B118	Valley Oak	2	12,8	30	Fair	Good
B119	Valley Oak	1	15	40	Fair	Good
B120	Valley Oak	1	20	50	Fair	Fair
B121	Interior Live Oak	1	8,8,6	30	Fair-Good	Good
B122	Interior Live Oak	1	17	25	Fair	Good
B123	Valley Oak	4	12,10,7,9	50	Fair	Good
B124	Valley Oak	1	10	20	Fair	Fair-Good
B125	Valley Oak	1	16	30	Fair-Good	Good
B126	Valley Oak	1	16	30	Fair	Good
B127	Valley Oak	1	16	30	Fair-Good	Good

		# of		DLR		
Tree #	Species	Trunks	DBH (inches)	(feet)	Health	Structure
B128	Valley Oak	2	13,9	25	Fair	Good
B129	Valley Oak	1	24	40	Fair-Good	Good
B130	Valley Oak	1	18	25	Fair	Good
B131	Interior Live Oak	2	11,14	40	Fair	Good
B132	Valley Oak	1	11	15	Fair-Good	Good
B133	Interior Live Oak	1	14	20	Fair-Poor	Fair
B134	Interior Live Oak	1	14	20	Fair-Poor	Good
B135	Valley Oak	1	10	12	Fair-Poor	Poor
B136	Valley Oak	2	9,8	10	Fair-Poor	Poor
B140	Interior Live Oak	2	19,15	45	Fair-Good	Good
B141	Valley Oak	1	13	25	Fair	Good
B142	Valley Oak	2	10,7	20	Fair	Good
B143	Interior Live Oak	4	16,14,10,10	40	Fair	Good
B144	Interior Live Oak	5	10,10,12,5,7	40	Fair	Good
B145	Interior Live Oak	4	20,11,5,5	40	Fair-Good	Good
B146	Interior Live Oak	2	20,12	35	Fair-Good	Good
B147	Valley Oak	1	23	50	Good	Good
B148	Valley Oak	1	10	12	Fair	Fair
B149	Valley Oak	1	25	40	Fair-Good	Good
B150	Valley Oak	1	17	30	Fair-Good	Good
B152	Interior Live Oak	3	16,12,8	30	Fair-Good	Good
B152	Valley Oak	1	9	20	Fair	Fair
B153	Interior Live Oak	2	10,8	20	Fair	Fair
B154	Interior Live Oak	1	8	10	Fair	Poor
B155	Valley Oak	1	12	20	Fair	Good
B156	Valley Oak	1	13	20	Fair	Good
B157	Valley Oak	1	12	15	Fair	Fair
B158	Interior Live Oak	4	10,10,7,10	30	Fair	Good
B159	Valley Oak	2	9,13	20	Fair	Fair
B160	Valley Oak	1	12	25	Fair-Good	Good
B161	Interior Live Oak	3	12,14,9	30	Fair	Good
B162	Valley Oak	1	7	15	Fair	Fair
B163	Valley Oak	1	8	10	Fair	Fair
B164	Interior Live Oak	3	12,10,7	25	Fair	Good
B165	Valley Oak	1	16	35	Fair	Fair-Good
B167	Interior Live Oak	2	25,9	25	Fair	Good
B168	Interior Live Oak	4	16,18,11,12	30	Fair	Good
B169	Valley Oak	3	10,7,7	20	Fair	Fair
B170	Valley Oak	1	16	25	Fair-Good	Good
B171	Valley Oak	1	10	10	Fair	Fair
B172	Valley Oak	1	14	30	Fair	Good
B172	Valley Oak	1	17	40	Fair	Good
B174	Interior Live Oak	2	24,7	40	Fair-Good	Good

		# of	Tree Survey Da	DLR		
Tree #	Species	Trunks	DBH (inches)	(feet)	Health	Structure
B175	Interior Live Oak	2	23,6	40	Fair	Good
B176	Interior Live Oak	6	7,7,7,6,4,3	20	Fair	Good
B177	Interior Live Oak	2	22,11	35	Fair-Good	Good
B178	Valley Oak	1	13	30	Fair	Fair-Good
B179	Interior Live Oak	3	14,14,7	30	Fair	Good
B180	Interior Live Oak	3	9,5,4	20	Fair	Good
B181	Valley Oak	1	15	20	Fair	Good
B183	Valley Oak	2	10,4	15	Fair	Fair-Good
B184	Interior Live Oak	4	14,14,8,12	40	Fair	Good
B185	Interior Live Oak	1	15	20	Fair-Good	Good
B186	Interior Live Oak	2	14,14	30	Fair	Good
B187	Interior Live Oak	3	19,10,10	40	Fair	Good
B188	Interior Live Oak	3	10,6,6	30	Fair	Good
B189	Interior Live Oak	2	18,16	40	Fair	Good
B190	Interior Live Oak	4	14,6,9,8	25	Fair	Good
B191	Interior Live Oak	2	22,9	25	Fair	Good
B192	Interior Live Oak	3	13,12,12	30	Fair	Good
B193	Interior Live Oak	2	21,23	30	Fair	Good
B194	Interior Live Oak	2	14,13	30	Fair	Good
B195	Interior Live Oak	2	9,3	10	Fair	Fair
B196	Interior Live Oak	2	17,7	20	Fair	Good
B197	Interior Live Oak	4	18,14,14,10	30	Fair	Good
B198	Interior Live Oak	2	14,14	30	Fair	Good
B199	Interior Live Oak	2	16,9	30	Fair	Good
B200	Interior Live Oak	3	16,10,10	25	Fair	Good
B201	Interior Live Oak	4	9,7,7,6	30	Fair-Good	Good
B202	Interior Live Oak	1	14	20	Fair-Good	Good
B203	Interior Live Oak	3	13,12,10	25	Fair	Good
B204	Interior Live Oak	4	12,10,7,8	20	Fair	Good
B205	Interior Live Oak	2	16,6	40	Fair-Good	Good
B206	Interior Live Oak	3	10,10,7	20	Fair	Good
B207	Interior Live Oak	2	15,10	25	Fair	Good
B208	Interior Live Oak	2	16,11	30	Fair	Good
B209	Interior Live Oak	4	11,11,3,10	35	Fair	Good
B210	Interior Live Oak	2	18,16	30	Fair	Good
B211	Valley Oak	1	17	35	Fair	Fair-Good
B212	Interior Live Oak	2	16,12	25	Fair	Good
B213	Valley Oak	1	21	15	Fair	Fair
B214	Interior Live Oak	2	13,7	30	Fair	Good
B215	Interior Live Oak	3	9,8,7	25	Fair	Good
B216	Interior Live Oak	4	17,12	30	Fair	Good
B217	Interior Live Oak	2	14,13	30	Fair	Good
B218	Interior Live Oak	1	16	30	Fair	Good

		# of	Tree Survey Da	DLR		
Tree #	Species	Trunks	DBH (inches)	(feet)	Health	Structure
B219	Interior Live Oak	1	14	20	Fair	Fair
B220	Interior Live Oak	1	14	10	Fair	Fair
B221	Interior Live Oak	1	8	10	Fair	Fair
B222	Interior Live Oak	3	20,11,12	30	Fair	Good
B223	Interior Live Oak	1	9	15	Fair	Fair
B224	Interior Live Oak	3	9,9,8	20	Fair	Fair
B225	Interior Live Oak	1	14	20	Fair-Good	Good
B226	Interior Live Oak	1	12	15	Fair	Fair
B227	Interior Live Oak	2	8,6	10	Fair	Fair
B228	Interior Live Oak	4	8,7,7,6	20	Fair-Poor	Fair
B229	Valley Oak	2	12,9	20	Fair-Good	Fair
B230	Interior Live Oak	5	11,8,6,6,10	20	Fair	Good
B231	Interior Live Oak	4	18,18,5,5	40	Fair	Good
B232	Valley Oak	1	10	15	Fair	Fair
B233	Valley Oak	1	17	30	Fair	Good
B234	Valley Oak	1	13	25	Fair-Good	Good
B235	Interior Live Oak	5	9,7,5,5,4	10	Fair	Fair-Poor
B236	Valley Oak	1	10	20	Fair	Fair-Good
B237	Interior Live Oak	2	13,13	35	Fair	Good
B238	Interior Live Oak	2	8,6	20	Fair-Good	Fair-Good
B239	Interior Live Oak	2	9,9	30	Fair	Good
B240	Interior Live Oak	3	16,12,9	40	Fair-Good	Good
B241	Valley Oak	1	11	20	Fair-Good	Good
B242	Valley Oak	1	10	15	Fair	Fair
B243	Interior Live Oak	3	7,6,5	25	Fair	Good
B244	Interior Live Oak	2	14,13	30	Fair	Good
B245	Valley Oak	1	14	25	Fair	Good
B246	Interior Live Oak	4	12,12,6,7	30	Fair	Good
B247	Valley Oak	1	14	25	Fair	Good
B248	Valley Oak	1	13	20	Fair	Fair
B250	Valley Oak	1	12	20	Fair-Poor	Fair
B251	Interior Live Oak	3	17,14,12	30	Fair	Good
B252	Valley Oak	1	12	25	Fair	Good
B253	Valley Oak	1	10	15	Fair	Fair-Good
B254	Valley Oak	1	12	25	Fair-Good	Good
B255	Interior Live Oak	1	17	25	Fair-Good	Good
B257	Interior Live Oak	1	11	20	Fair	Good
B258	Interior Live Oak	2	14,12	30	Fair	Good
B259	Interior Live Oak	1	14	20	Fair-Good	Fair
B260	Interior Live Oak	2	23	35	Fair-Good	Good
B261	Interior Live Oak	3	8,10,7	20	Fair	Good
B263	Valley Oak	2	9,6	10	Fair	Poor
B264	Valley Oak	1	12	20	Fair	Good

		# of		DLR		
Tree #	Species	Trunks	DBH (inches)	(feet)	Health	Structure
B265	Valley Oak	1	11	20	Fair	Fair
B265	Valley Oak	1	11	25	Fair	Fair
B266	Interior Live Oak	3	13,6,5	30	Fair-Good	Good
B267	Interior Live Oak	3	8,7,6	30	Fair-Good	Good
B268	Interior Live Oak	2	16,5	15	Fair	Fair
B269	Valley Oak	1	12	20	Fair-Good	Good
B270	Valley Oak	2	8,7	15	Fair	Fair
B270	Valley Oak	2	9,8	20	Fair	Fair
B271	Interior Live Oak	2	16,8	30	Fair-Good	Good
B272	Valley Oak	1	17	30	Fair	Fair
B273	Interior Live Oak	3	14,11,12	30	Fair-Good	Good
B274	Valley Oak	1	14	15	Fair	Fair
B275	Valley Oak	1	10	20	Fair	Fair
B276	Interior Live Oak	2	10,8	30	Fair	Good
B277	Interior Live Oak	4	12,6,7,8	40	Fair	Good
B278	Interior Live Oak	6	13,8,8,9,15,10	50	Fair-Good	Good
B279	Interior Live Oak	1	19	30	Fair-Good	Good
B280	Interior Live Oak	1	16	30	Fair	Good
B281	Interior Live Oak	2	15,10	20	Fair	Fair
B282	Interior Live Oak	4	10,8,7,4	20	Fair	Fair
B283	Interior Live Oak	1	10	15	Fair	Fair-Poor
B284	Valley Oak	1	9	10	Fair	Poor
B285	Interior Live Oak	1	12	20	Fair	Fair
B286	Interior Live Oak	2	13,8	25	Fair-Poor	Poor
B301	Valley Oak	1	12	20	Fair	Fair
B302	Valley Oak	2	7,7	10	Fair	Fair
B309	Interior Live Oak	4	13,10,10,10	50	Fair	Good
B310	Interior Live Oak	3	8,6,5	25	Fair	Good
B312	Interior Live Oak	3	7,4,4	15	Fair-Poor	Poor
B319	Interior Live Oak	1	11	10	Fair	Poor
B320	Interior Live Oak	3	14,10,8	30	Fair	Fair
B321	Valley Oak	2	12,13	30	Fair	Good
B322	Interior Live Oak	5	7,5,5,4,4	20	Fair	Fair
B323	Interior Live Oak	2	10,10	20	Fair	Good
B324	Interior Live Oak	2	15,12	30	Fair	Good
B325	Interior Live Oak	1	10	30	Fair	Good
B326	Interior Live Oak	1	13	30	Fair	Good
B327	Valley Oak	1	9	10	Fair-Poor	Poor
B328	Interior Live Oak	3	15,13,13	40	Fair	Good
B329	Interior Live Oak	2	9,6	15	Fair	Fair
B330	Valley Oak	1	11	15	Fair	Fair
B337	Interior Live Oak	2	15,10	25	Fair	Fair
B338	Interior Live Oak	2	23,13	30	Fair	Good

Tree #	Species	# of Trunks	DBH (inches)	DLR (feet)	Health	Structure
B339	Interior Live Oak	6	14,14,12,12,12,10	40	Fair	Good
B343	Interior Live Oak	2	13,7	30	Fair	Fair
B344	Interior Live Oak	3	19,12,6	30	Fair	Fair
B368	Valley Oak	2	8,9	15	Fair	Fair
B370	Valley Oak	1	26	50	Fair	Good
B371	Valley Oak	1	22	50	Fair-Good	Good
B372	Valley Oak	1	13	30	Fair-Good	Good
B373	Valley Oak	1	10	20	Fair	Fair
B374	Valley Oak	2	9,8	15	Fair	Fair
B375	Valley Oak	3	10,8,6	15	Fair	Fair
B376	Valley Oak	1	23	15	Fair	Poor
B377	Interior Live Oak	1	9	10	Fair-Poor	Fair
B379	Valley Oak	1	14	20	Fair	Fair
B380	Valley Oak	1	10	10	Fair	Fair
B381	Interior Live Oak	5	12,8,3,4,5	35	Fair	Good
B383	Interior Live Oak	2	14,9	30	Fair	Fair-Good
B384	Interior Live Oak	1	9	20	Fair	Fair
B385	Interior Live Oak	1	14	10	Fair	Fair
B386	Valley Oak	1	8	10	Fair	Poor
B387	Interior Live Oak	1	15	25	Fair	Fair
B388	Valley Oak	1	13	15	Fair	Fair
B389	Valley Oak	1	14	20	Fair	Fair
B390	Valley Oak	1	18	35	Fair-Good	Fair
B392	Valley Oak	1	14	25	Fair	Fair
B393	Valley Oak	1	13	15	Fair	Fair
B394	Valley Oak	2	9,5	15	Fair	Fair-Poor
B395	Interior Live Oak	2	10,4	20	Fair	Fair
B396	Interior Live Oak	1	8	10	Fair-Poor	Poor
B397	Interior Live Oak	4	13,10,10,4	40	Fair-Good	Good
B398	Valley Oak	1	16	35	Fair-Good	Good
B399	Interior Live Oak	1	16	35	Fair	Good
B400	Valley Oak	1	10	15	Fair	Poor
B401	Valley Oak	1	17	10	Fair	Poor
B403	Valley Oak	1	14	10	Fair	Poor
B404	Valley Oak	1	8	5	Poor	Poor
B405	Interior Live Oak	2	9,8	20	Fair	Fair
B406	Interior Live Oak	1	9	10	Fair	Fair
B407	Valley Oak	1	12	20	Fair	Fair
B408	Valley Oak	1	10	15	Fair	Fair
B409	Valley Oak	1	9	5	Poor	Poor
B410	Interior Live Oak	1	12	30	Fair-Good	Good
B411	Valley Oak	1	11	10	Fair	Poor
B412	Valley Oak	1	16	30	Fair	Good

		# of	Tree Survey Da	DLR		
Tree #	Species	Trunks	DBH (inches)	(feet)	Health	Structure
B413	Interior Live Oak	3	9,6,8	25	Fair	Fair
B414	Valley Oak	1	15	20	Fair-Good	Good
B415	Valley Oak	1	12	15	Fair-Good	Fair
B416	Valley Oak	2	10,6	10	Fair	Poor
B418	Interior Live Oak	3	9,9,6	20	Fair	Fair
B419	Interior Live Oak	2	23,23	30	Fair	Good
B420	Blue Oak	1	21	40	Fair	Good
B421	Interior Live Oak	4	18,18,13,6	25	Fair	Good
B423	Interior Live Oak	1	22	25	Fair	Good
B424	Valley Oak	1	18	25	Fair	Good
B425	Valley Oak	1	20	30	Fair-Good	Good
B426	Valley Oak	1	20	30	Fair-Good	Good
B427	Valley Oak	1	11	10	Fair	Poor
B429	Interior Live Oak	1	14	30	Fair	Good
B430	Valley Oak	1	27	50	Fair-Good	Good
B431	Interior Live Oak	1	7,3	12	Fair	Fair
B432	Interior Live Oak	2	14,14	25	Fair	Good
B433	Interior Live Oak	1	10	5	Fair-Poor	Poor
B434	Interior Live Oak	2	12,9	15	Fair	Fair
B435	Interior Live Oak	1	22	30	Fair	Good
B436	Interior Live Oak	3	14,12,12	15	Poor	Poor
B437	Interior Live Oak	1	12	20	Fair	Good
B439	Interior Live Oak	1	8	15	Fair	Fair
B440	Interior Live Oak	1	9	8	Poor	Poor
B441	Valley Oak	1	10	20	Fair-Good	Good
B442	Valley Oak	1	13	15	Fair	Fair
B443	Valley Oak	1	12	15	Fair	Fair
B444	Interior Live Oak	3	8,6,5	15	Fair	Fair
B445	Interior Live Oak	1	8	10	Fair	Poor
B446	Interior Live Oak	2	12,6	12	Fair	Fair
B447	Interior Live Oak	1	18	10	Fair-Poor	Poor
B449	Interior Live Oak	2	9,5	12	Fair	Fair
B450	Interior Live Oak	2	8,7	15	Fair	Fair
B452	Interior Live Oak	1	6	10	Fair	Poor
B455	Interior Live Oak	1	12	15	Fair	Fair
B456	Interior Live Oak	1	9	12	Fair	Fair
B457	Interior Live Oak	4	16,14,6,6	25	Fair	Good
B458	Interior Live Oak	1	17	25	Fair	Good
B459	Interior Live Oak	1	10	12	Fair	Fair
B460	Interior Live Oak	6	18,16,12,12,10,14	50	Fair	Good
B461	Interior Live Oak	1	27	50	Fair	Good
B463	Interior Live Oak	1	16	25	Fair	Fair
B464	Valley Oak	1	28	40	Fair-Good	Good

		# of	Tree Survey Da	DLR		
Tree #	Species	Trunks	DBH (inches)	(feet)	Health	Structure
B465	Valley Oak	2	14,14	10	Poor	Poor
B466	Valley Oak	1	6	8	Fair-Poor	Poor
B467	Interior Live Oak	1	10	20	Fair	Fair
B468	Blue Oak	2	18,9	30	Fair-Good	Good
B469	Blue Oak	1	17	20	Fair	Fair
B470	Interior Live Oak	3	29,13,9	55	Fair	Good
B471	Interior Live Oak	1	14	20	Fair	Fair
B473	Blue Oak	1	12	12	Fair	Poor
B474	Interior Live Oak	2	10,9	15	Fair	Fair
B475	Interior Live Oak	1	8	20	Fair	Poor
B476	Interior Live Oak	1	11	15	Fair	Fair
B477	Valley Oak	1	23	40	Fair-Good	Good
B479	Valley Oak	1	21	30	Fair	Fair-Good
B481	Interior Live Oak	1	32	60	Fair-Good	Good
B482	Valley Oak	1	18	25	Fair	Fair
B483	Interior Live Oak	3	22,14,14	30	Fair-Poor	Poor
B484	Interior Live Oak	3	20,18,14	40	Fair	Good
B485	Interior Live Oak	1	15	20	Fair-Good	Good
B486	Interior Live Oak	1	14	15	Fair	Fair
B487	Valley Oak	1	15	20	Fair	Fair
B489	Interior Live Oak	3	18,14,12	40	Fair	Good
B490	Interior Live Oak	1	23	10	Poor	Poor
B492	Valley Oak	1	10	10	Fair-Poor	Poor
B493	Valley Oak	1	15	15	Fair-Poor	Poor
B494	Valley Oak	1	16	10	Fair	Fair
B496	Valley Oak	1	17	10	Fair-Poor	Poor
B497	Interior Live Oak	1	17	30	Fair	Fair
B498	Valley Oak	1	9	15	Fair	Fair
B500	Interior Live Oak	3	16,8,8	30	Fair-Good	Good
B501	Valley Oak	1	7	10	Fair	Fair
B502	Valley Oak	2	8,8	20	Fair	Fair
B503	Valley Oak	1	8	10	Fair	Fair
B504	Valley Oak	1	11	25	Fair-Good	Good
B505	Valley Oak	1	14	20	Fair	Good
B506	Valley Oak	1	12	25	Fair-Good	Good
B507	Valley Oak	1	18	30	Fair-Good	Good
B508	Valley Oak	1	17	30	Fair-Poor	Good
B509	Valley Oak	1	18	30	Fair	Good
B510	Interior Live Oak	4	18,14,8,14	30	Fair	Good
B511	Valley Oak	1	13	20	Fair	Good
B512	Interior Live Oak	3	16,14,10	30	Fair	Good
B514	Interior Live Oak	1	25	35	Fair	Good
B515	Interior Live Oak	3	14,9,7	30	Fair	Good

		# of	Tree Survey Da	DLR		
Tree #	Species	Trunks	DBH (inches)	(feet)	Health	Structure
B516	Interior Live Oak	5	17,12,10,10,5	30	Fair	Good
B517	Valley Oak	1	13	25	Fair-Good	Good
B518	Interior Live Oak	2	18,12	30	Fair	Good
B519	Interior Live Oak	2	20,7	30	Fair	Good
B520	Interior Live Oak	4	15,15,12,9	30	Fair	Good
B522	Valley Oak	1	10	25	Fair	Good
B524	Valley Oak	1	11	20	Fair	Good
B527	Valley Oak	1	34	50	Fair-Good	Good
B528	Valley Oak	1	15	30	Fair-Good	Good
B529	Valley Oak	1	15	40	Fair-Good	Good
B530	Interior Live Oak	6	12,10,6,15,5,10	40	Fair-Good	Good
B531	Valley Oak	2	10,9	30	Fair	Good
B532	Valley Oak	1	14	20	Fair	Fair
B533	Interior Live Oak	1	11	15	Fair-Good	Good
B534	Interior Live Oak	4	11,5,8,7	30	Fair-Good	Good
B535	Interior Live Oak	1	15	30	Fair-Good	Good
B536	Valley Oak	1	16	30	Fair	Good
B537	Interior Live Oak	4	11,12,9,12	40	Fair-Good	Good
B538	Interior Live Oak	6	12,9,11,6,13,6	40	Fair-Good	Good
B541	Interior Live Oak	2	17,12	25	Fair-Good	Good
B542	Valley Oak	1	10	10	Fair	Poor
B543	Interior Live Oak	2	12,8	20	Fair	Good
B545	Valley Oak	1	17	30	Fair	Fair
B546	Valley Oak	1	8	12	Fair	Fair
B547	Interior Live Oak	5	10,8,6,6,7	25	Fair-Good	Good
B548	Interior Live Oak	3	8,6,4	25	Fair	Good
B549	Interior Live Oak	3	12,11,7	40	Fair-Good	Good
B551	Valley Oak	1	11	30	Fair	Fair
B552	Interior Live Oak	2	14,8	30	Fair	Good
B553	Interior Live Oak	3	16,6,6	30	Fair-Good	Good
B554	Interior Live Oak	4	11,15,9,7	40	Fair-Good	Fair
B555	Valley Oak	1	12	20	Fair	Fair-Good
B556	Valley Oak	1	15	20	Fair	Fair-Good
B557	Valley Oak	1	9	20	Fair-Good	Fair-Good
B559	Valley Oak	1	14	30	Fair	Good
B560	Valley Oak	1	23	50	Fair-Good	Good
B561	Valley Oak	1	25	50	Fair-Good	Good
B562	Valley Oak	1	21	30	Fair	Fair
B563	Valley Oak	2	15,13	30	Fair-Poor	Poor
B564	Valley Oak	2	14,13	25	Fair-Poor	Poor
B565	Valley Oak	1	14	25	Fair	Good
B566	Valley Oak	2	16,11	30	Fair	Good
B568	Valley Oak	2	12,12	25	Fair	Good

		# of	Tee Survey Da	DLR		
Tree #	Species	Trunks	DBH (inches)	(feet)	Health	Structure
B569	Valley Oak	1	10	12	Fair	Fair
B570	Valley Oak	1	11	15	Fair	Fair
B571	Valley Oak	2	13,12	25	Fair	Good
B572	Blue Oak	1	17	40	Fair-Good	Good
B573	Valley Oak	1	24	30	Poor	Poor
B574	Interior Live Oak	2	10,6	20	Fair-Poor	Fair
B575	Interior Live Oak	3	12,9,9	20	Fair	Fair
B576	Interior Live Oak	2	9,6	10	Fair-Poor	Poor
B577	Interior Live Oak	3	12,12,8	40	Fair	Good
B578	Interior Live Oak	2	7,6	10	Fair	Poor
B579	Interior Live Oak	4	18,16,6,8	30	Fair	Good
B580	Interior Live Oak	2	14,12	30	Fair	Good
B581	Interior Live Oak	2	9,6	20	Fair	Good
B584	Interior Live Oak	1	7	15	Fair	Fair
B585	Interior Live Oak	2	6,6	15	Fair	Fair
B586	Interior Live Oak	3	12,9,6	30	Fair-Good	Good
B587	Interior Live Oak	4	13,12,6,6	40	Fair	Good
B588	Interior Live Oak	2	13,7	15	Fair	Fair
B589	Valley Oak	1	12	15	Fair	Poor
B591	Interior Live Oak	1	7	5	Poor	Poor
B592	Interior Live Oak	2	23,17	60	Fair-Good	Good
B593	Interior Live Oak	2	17,20	25	Fair	Good
B594	Interior Live Oak	2	15,9	20	Fair	Fair
B596	Interior Live Oak	3	10,10,8	35	Fair	Good
B597	Interior Live Oak	2	16,14	20	Fair	Good
B598	Interior Live Oak	1	14	15	Fair	Fair
B599	Interior Live Oak	2	10,10	15	Fair-Poor	Poor
B600	Interior Live Oak	2	12,12	25	Fair-Poor	Poor
B602	Interior Live Oak	1	14	25	Fair	Good
B603	Valley Oak	1	15	25	Fair	Fair
B605	Interior Live Oak	2	7,6	15	Fair	Good
B606	Valley Oak	1	27	40	Fair	Good
B607	Valley Oak	1	17	10	Fair-Poor	Poor
B611	Interior Live Oak	1	15	15	Fair-Poor	Poor
B612	Valley Oak	1	12	15	Fair	Fair
B613	Interior Live Oak	2	12,14	20	Fair-Poor	Fair
B614	Interior Live Oak	1	24	40	Fair	Good
B615	Interior Live Oak	1	8	10	Fair	Poor
B616	Interior Live Oak	2	7,5	15	Fair	Fair
B617	Interior Live Oak	2	7,6	12	Fair	Fair
B618	Interior Live Oak	3	9,8,8	20	Fair	Good
B619	Interior Live Oak	1	8	10	Fair	Fair
B620	Interior Live Oak	3	14,12,9	20	Fair	Fair

Tree #	Species	# of Trunks	DBH (inches)	DLR (feet)	Health	Structure
B621	Interior Live Oak	2	21,14	25	Fair	Fair
B623	Interior Live Oak	1	6	5	Poor	Poor
B624	Interior Live Oak	1	16	30	Fair	Good
B625	Interior Live Oak	4	13,13,10,9	30	Fair-Poor	Fair
B626	Interior Live Oak	2	12,5	25	Fair	Fair
B627	Interior Live Oak	4	14,14,9,9	25	Fair	Good
B628	Interior Live Oak	1	9	10	Fair	Poor
B629	Interior Live Oak	1	18	35	Fair-Poor	Fair
B630	Interior Live Oak	2	14,14	40	Fair	Good
B632	Valley Oak	1	26	40	Fair	Fair
B633	Valley Oak	1	13	20	Fair	Fair
B634	Valley Oak	2	27,24	50	Fair	Good
B635	Interior Live Oak	1	24	40	Fair	Good
B636	Valley Oak	1	9	10	Fair-Poor	Poor
B637	Valley Oak	1	14	20	Fair	Good
B638	Valley Oak	1	10	8	Fair-Poor	Poor
B639	Valley Oak	1	9	15	Fair	Fair
B641	Valley Oak	1	9	12	Fair	Fair
B642	Valley Oak	1	9	10	Fair	Poor
B643	Valley Oak	1	9	15	Fair	Fair
B644	Interior Live Oak	4	16,13,9,9	40	Fair	Good
B645	Interior Live Oak	2	12,6	25	Fair	Good
B646	Valley Oak	1	16	30	Fair	Good
B646	Valley Oak	1	10	15	Fair	Fair
B647	Valley Oak	1	12	15	Fair	Fair
B648	Valley Oak	1	14	25	Fair	Good
B649	Valley Oak	1	15	35	Fair	Good
B650	Valley Oak	1	9	25	Fair	Fair
B651	Valley Oak	1	9	15	Fair	Poor
B652	Interior Live Oak	1	23	35	Fair-Good	Good
B653	Interior Live Oak	2	12,10	20	Fair	Fair
B655	Valley Oak	1	10	20	Fair	Fair-Good
B656	Valley Oak	1	18	30	Fair	Good
B659	Valley Oak	1	32	40	Fair-Poor	Good
B661	Interior Live Oak	1	12	20	Fair-Good	Good
B662	Interior Live Oak	2	11,6	20	Fair	Good
B663	Valley Oak	1	14	25	Fair	Good
B664	Valley Oak	1	9	15	Fair	Fair
B665	Valley Oak	1	21	30	Fair	Good
B666	Valley Oak	1	13	15	Fair	Fair
B667	Valley Oak	1	18	30	Fair	Good
B668	Valley Oak	1	14	25	Fair	Good
B669	Valley Oak	1	9	15	Fair-Good	Good

Tree #	Species	# of Trunks	DBH (inches)	DLR (feet)	Health	Structure
B670	Valley Oak	1	16	30	Fair-Good	Good
B671	Valley Oak	1	7	10	Fair-Poor	Poor
B672	Valley Oak	1	13	20	Fair-Good	Good
B673	Interior Live Oak	1	10	15	Fair-Good	Good
B674	Interior Live Oak	2	18,18	40	Fair	Good
B675	Interior Live Oak	2	16,9	30	Fair	Good
B676	Interior Live Oak	1	10	15	Fair	Fair
B677	Interior Live Oak	1	16	20	Fair	Fair
B678	Interior Live Oak	3	13,9,6	30	Fair	Good
B4640	Interior Live Oak	1	6	12	Fair-Poor	Poor
B4001	Interior Live Oak	2	6,4	15	Fair	Fair
B4010	Interior Live Oak	1	6	10	Fair	Poor
B4011	Interior Live Oak	1	6	10	Fair	Fair
B4012	Interior Live Oak	1	6	10	Fair-Poor	Poor
B4013	Interior Live Oak	1	8	20	Fair	Good
B4014	Interior Live Oak	1	8	15	Fair	Good
B4015	Valley Oak	1	6	10	Fair	Poor
B4016	Valley Oak	1	7	10	Fair-Poor	Poor
B4017	Interior Live Oak	2	10,10	30	Fair	Good
B4018	Interior Live Oak	4	7,7,6,5	30	Fair	Good
B4019	Valley Oak	1	6	10	Fair	Poor
B4020	Valley Oak	1	7	8	Fair-Poor	Poor
B4021	Interior Live Oak	4	7,8,6,7	25	Fair	Good
B4022	Interior Live Oak	3	8,6,5	20	Fair	Good
B4023	Interior Live Oak	1	13	15	Fair	Good
B4024	Interior Live Oak	1	7	10	Fair	Fair
B4025	Interior Live Oak	1	6	10	Fair	Fair
B4026	Interior Live Oak	2	9,7	20	Fair	Good
B4027	Interior Live Oak	1	7	15	Fair	Good
B4028	Interior Live Oak	1	9	15	Fair	Fair
B4029	Interior Live Oak	3	8,6,5	15	Fair	Poor
B4030	Interior Live Oak	1	17	30	Fair	Fair
B4031	Interior Live Oak	1	8	20	Fair-Good	Good
B4032	Interior Live Oak	2	10,8	25	Fair	Fair
B4033	Interior Live Oak	1	8	15	Fair	Fair
B4034	Interior Live Oak	2	9,5	10	Fair-Poor	Poor
B4035	Interior Live Oak	2	12,12	40	Fair-Good	Good
B4036	Interior Live Oak	1	8	15	Fair	Fair
B4037	Valley Oak	1	11	15	Fair-Poor	Poor
B4038	Interior Live Oak	1	8	15	Fair-Good	Good
B4039	Interior Live Oak	2	11,8	25	Fair	Good
B4040	Valley Oak	1	11	15	Fair	Poor
B4041	Valley Oak	1	8	10	Fair-Poor	Poor

Tree #	Species	# of Trunks	DBH (inches)	DLR (feet)	Health	Structure
B4042	Valley Oak	1	7	10	Fair	Fair-Good
B4043	Interior Live Oak	2	6,6	12	Fair-Good	Good
B4044	Interior Live Oak	2	8,5	15	Fair	Fair
B4045	Valley Oak	1	8	15	Fair	Good
B4046	Interior Live Oak	1	6	10	Fair	Poor
B4047	Interior Live Oak	5	8,5,5,5,4	20	Fair	Fair
B4048	Valley Oak	1	7	10	Fair	Fair
B4049	Interior Live Oak	2	7	15	Fair	Fair
B4050	Interior Live Oak	1	6	15	Fair	Fair
B4051	Valley Oak	1	13	25	Fair	Fair
B4052	Interior Live Oak	1	7	15	Fair-Good	Fair
B4053	Interior Live Oak	3	7,7,6	15	Fair	Poor
B4054	Interior Live Oak	1	7	15	Fair	Good
B4055	Valley Oak	2	7,7	15	Fair	Fair-Poor
B4056	Valley Oak	1	9	15	Fair	Fair
B4057	Interior Live Oak	4	10,8,7,6	25	Fair	Good
B4058	Valley Oak	1	7	10	Fair	Fair
B4059	Interior Live Oak	1	8	10	Fair	Fair
B4060	Valley Oak	1	12	20	Fair	Fair
B4061	Valley Oak	1	16	25	Fair-Good	Good
B4062	Interior Live Oak	4	12,10,9,4	25	Fair-Good	Fair
B4063	Interior Live Oak	2	12,7	30	Fair	Good
B4064	Valley Oak	3	8,7,5	15	Fair	Fair
B4067	Valley Oak	1	8	10	Fair	Fair
B4068	Valley Oak	1	8	15	Fair-Good	Fair
B4069	Valley Oak	2	8,8	10	Fair-Poor	Poor
B4070	Interior Live Oak	2	6,4	15	Fair-Poor	Fair
B4071	Valley Oak	1	7	15	Fair-Poor	Fair
B4072	Interior Live Oak	1	7	15	Fair-Good	Good
B4073	Valley Oak	1	10	15	Fair	Good
B4074	Valley Oak	1	11	15	Fair	Good
B4143	Valley Oak	1	13	20	Fair	Fair
B4144	Valley Oak	1	20	35	Fair	Good
B4145	Valley Oak	1	16	30	Fair	Good
B4146	Valley Oak	1	18	40	Fair	Good
B4147	Valley Oak	1	10	15	Fair	Fair
B4148	Valley Oak	1	10	15	Fair	Fair
B4149	Valley Oak	1	14	20	Fair-Good	Fair
B4150	Interior Live Oak	1	8	10	Fair	Fair
B4151	Valley Oak	1	7	12	Fair	Poor
B4155	Interior Live Oak	1	7	10	Fair	Poor
B4156	Interior Live Oak	1	6	10	Fair-Poor	Poor
B4157	Interior Live Oak	1	6	10	Fair-Poor	Poor

# of DDN a . DLR W						
Tree #	Species	Trunks	DBH (inches)	(feet)	Health	Structure
B4158	Interior Live Oak	1	9	15	Fair	Fair
B4160	Interior Live Oak	2	18,14	40	Fair	Good
B4161	Valley Oak	1	6	8	Fair-Poor	Poor
B4163	Interior Live Oak	2	6,8	15	Fair	Poor
B4165	Valley Oak	1	7	8	Fair-Poor	Poor
B4166	Valley Oak	1	6	5	Fair-Poor	Poor
B4167	Valley Oak	1	6	6	Fair-Poor	Poor
B4168	Valley Oak	1	10	20	Fair	Fair
B4169	Valley Oak	1	8	10	Fair	Poor
B4170	Valley Oak	1	11	15	Fair	Fair
B4171	Valley Oak	1	10	10	Fair	Fair
B4173	Valley Oak	1	12	15	Fair	Poor
B4174	Valley Oak	1	9	10	Fair	Poor
B4178	Valley Oak	1	12	10	Fair	Poor
B4179	Valley Oak	1	10	10	Fair-Poor	Poor
B4180	Valley Oak	1	12	20	Fair-Poor	Poor
B4181	Valley Oak	1	10	10	Fair-Poor	Poor
B4182	Valley Oak	1	7	8	Fair-Poor	Poor
B4193	Valley Oak	1	6	10	Fair-Poor	Poor
B4194	Valley Oak	1	12	10	Fair	Poor
B4195	Valley Oak	1	11	8	Fair-Poor	Poor
B4196	Valley Oak	1	9	20	Fair	Poor
B4197	Valley Oak	1	13	25	Fair	Fair
B4198	Valley Oak	1	9	12	Fair	Fair
B4199	Valley Oak	2	12,6	10	Fair-Poor	Poor
B4200	Valley Oak	1	12	30	Fair	Fair-Good
B4204	Valley Oak	1	10	8	Fair-Poor	Poor
B4205	Valley Oak	1	24	30	Fair	Fair
B4225	Valley Oak	1	15	25	Fair	Fair
B4226	Valley Oak	1	11	15	Fair	Fair
B4227	Valley Oak	1	7	10	Fair-Poor	Poor
B4228	Valley Oak	1	18	30	Fair	Fair-Good
B4233	Valley Oak	1	8	10	Fair-Poor	Poor
B4239	Valley Oak	1	12	15	Fair-Poor	Fair
B4240	Valley Oak	1	12	15	Fair	Fair
B4242	Valley Oak	1	22	25	Fair	Fair-Good
B4244	Valley Oak	1	18	20	Fair	Fair
B4246	Valley Oak	1	22	20	Fair	Good
B4248	Interior Live Oak	1	7	8	Fair	Poor
B4249	Valley Oak	1	12	15	Fair-Poor	Poor
B4250	Interior Live Oak	1	13	8	Poor	Poor
B4251	Valley Oak	1	20	30	Fair	Good
B4252	Valley Oak	1	12	10	Fair-Poor	Poor


Tree #	Species	# of Trunks	DBH (inches)	DLR (feet)	Health	Structure
B4253	Valley Oak	1	10	10	Fair-Poor	Poor
B4254	Valley Oak	1	25	30	Fair-Good	Good
B4255	Valley Oak	1	8	5	Poor	Poor
B4256	Valley Oak	1	23	25	Fair	Fair
B4258	Interior Live Oak	1	15	15	Fair-Poor	Poor
B4259	Valley Oak	1	7	5	Fair-Poor	Poor
B4260	Valley Oak	2	14,8	20	Fair	Fair
B4261	Valley Oak	2	12,4	10	Fair-Poor	Poor
B4262	Valley Oak	1	12	15	Fair	Fair
B4263	Valley Oak	1	14	20	Fair	Fair
B4264	Valley Oak	3	7,7,6	15	Fair-Poor	Poor
B4265	Valley Oak	2	7,4	10	Fair-Poor	Poor
B4266	Valley Oak	1	24	40	Fair	Fair
B4267	Valley Oak	1	10	13	Fair	Poor
B4268	Valley Oak	1	8	10	Fair-Poor	Poor
B4271	Valley Oak	1	12	15	Fair	Fair
B4273	Interior Live Oak	1	9	8	Fair-Poor	Poor
B4274	Valley Oak	1	23	30	Fair-Good	Good
B4275	Valley Oak	1	14	25	Fair	Fair
B4276	Valley Oak	1	8	8	Fair-Poor	Poor
B4278	Valley Oak	1	8	15	Fair	Fair
B4279	Valley Oak	1	8	15	Fair	Fair
B4366	Valley Oak	1	23	30	Fair-Good	Good
B4375	Valley Oak	1	9	10	Fair-Poor	Poor
B4376	Valley Oak	1	10	25	Fair	Good
B4377	Valley Oak	2	10,10	25	Fair	Poor
B4378	Valley Oak	1	8	10	Fair-Poor	Poor
B4379	Valley Oak	1	6	8	Fair-Poor	Poor
B4380	Valley Oak	1	12	20	Fair	Fair
B4381	Valley Oak	1	16	30	Fair	Fair
B4382	Valley Oak	1	9	15	Fair	Fair
B4383	Valley Oak	1	8	12	Fair	Fair
B4384	Valley Oak	1	9	10	Fair	Fair
B4385	Valley Oak	1	7	10	Fair	Good
B4387	Valley Oak	1	13	15	Fair	Fair
B4391	Valley Oak	1	30	60	Fair	Good
B4392	Interior Live Oak	2	10,3	15	Fair-Poor	Poor
B4394	Interior Live Oak	6	24,14,8,6,4,4	40	Fair	Fair
B4395	Interior Live Oak	1	6	5	Fair-Poor	Poor
B4397	Interior Live Oak	1	8	10	Fair-Poor	Poor
B4399	Interior Live Oak	1	7	8	Fair-Poor	Poor
B4490	Valley Oak	1	7	12	Fair	Poor
B4491	Valley Oak	1	16	30	Fair	Good

Tree #	Species	# of Trunks	DBH (inches)	DLR (feet)	Health	Structure
B4492	Valley Oak	1	17	40	Fair	Good
B4493	Interior Live Oak	1	9	15	Fair-Good	Good
B4494	Valley Oak	3	6,14,12	25	Fair	Good
B4495	Interior Live Oak	1	12	10	Fair-Poor	Poor
B4496	Valley Oak	1	12	15	Fair	Good
B4497	Valley Oak	1	23	25	Fair	Good
B4498	Interior Live Oak	2	9,4	20	Fair	Fair
B4499	Valley Oak	1	16	25	Fair	Fair
C526	Valley Oak	1	17	40	Fair-Good	Good


Appendix B — Dead Trees


Tree #	Species
2294	DEAD
2422	DEAD
2442	DEAD
2447	DEAD
2973	DEAD
2978	DEAD
2988	DEAD
3008	DEAD
3028	DEAD
3039	DEAD
3143	DEAD
4500	DEAD
4505	DEAD
4557	DEAD
B49	DEAD
B58	DEAD
B391	DEAD
B428	DEAD
B438	DEAD
B451	DEAD
B454	DEAD
B488	DEAD
B491	DEAD
B495	DEAD
B558	DEAD
B567	DEAD
B604	DEAD
B631	DEAD
B4153	DEAD
B4162	DEAD
B4175	DEAD
B4201	DEAD
B4272	DEAD
B4372	DEAD
B4374	DEAD
B4396	DEAD
B4398	DEAD

Appendix C — Tre	e Locations Maps
------------------	------------------




































6201 HORSESHOE BAR ROAD

Appendix C

Cultural Resources Report

Resource maps have been excluded to protect the listed resources; however, the complete report Cultural Resources Report is available for review on the website (http://www.loomis.ca.gov/loomis_projects.html) and at the Town office: 3665 Taylor Road, Loomis, CA 95650.

CULTURAL RESOURCES

To evaluate potential conflicts between the proposed project and cultural resources, Peak & Associates, Inc., conducted an Information Center Record Search for the project vicinity to identify recorded resources in the area and contacted the Native American Heritage Commission (NAHC) and individuals identified by the NAHC to identify Native American concerns regarding the project. This research was supervised by Melinda A. Peak assisted by Robert A. Gerry.

CULTURAL SETTING

Prehistory

The project area is at the edge of the Central Valley cultural area near the transition to the foothills of the Sierra Nevada. The archeological sequences defined for the Central Valley are relevant to this area, although the material culture may be simplified in comparison with the major sites along the Sacramento River and tributaries. Some influence from the montane cultures has been identified at nearby sites in similar settings (c.f. Chavez 1983), but the general pattern of cultural succession reflects the Central Valley sequence.

The Central Valley region was among the first in the state to attract intensive fieldwork, and research has continued to the present day. This has resulted in a substantial accumulation of data. In the early decades of the 1900s, E.J. Dawson explored numerous sites near Stockton and Lodi, later collaborating with W.E. Schenck (Schenck and Dawson 1929). By 1933, the focus of work was directed to the Cosumnes locality, where survey and excavation were conducted by the Sacramento Junior College (Lillard and Purves 1936). Excavation data, in particular from the stratified Windmiller site (CA-Sac-107), suggested two temporally distinct cultural traditions. Later work at other mounds by Sacramento Junior College and the University of California, Berkeley, enabled the investigators to identify a third cultural tradition, intermediate between the previously postulated Early and Late Horizons. The three-horizon sequence, based on discrete changes in ornamental artifacts and mortuary practices, as well as on observed differences in soils within sites (Lillard, Heizer and Fenenga 1939), was later refined by Beardsley (1954). An expanded definition of artifacts diagnostic of each time period was developed, and its application extended to parts of the central California coast. Traits held in common allow the application of this system within certain limits of time and space to other areas of prehistoric central California.

The Windmiller Culture (Early Horizon) is characterized by ventrally-extended burials (some dorsal extensions are known), with westerly orientation of heads; a high percentage of burials with grave goods; frequent presence of red ocher in graves; large projectile points, of which 60 percent are of materials other than obsidian; rectangular *Haliotis* beads; *Olivella* shell beads (types A1a and L); rare use of bone; some use of baked clay objects; and well-fashioned charmstones, usually perforated.

The Cosumnes Culture (Middle Horizon) displays considerable changes from the preceding cultural expression. The burial mode is predominately flexed, with variable cardinal orientation and some cremations present. There is a lower percentage of burials with grave goods, and ocher staining is common in graves. *Olivella* beads of types C1, F and G predominate, and there is abundant use of green *Haliotis sp.* rather than red *Haliotis sp.* Other characteristic artifacts include perforated and canid teeth; asymmetrical and "fishtail" charmstones, usually unperforated; cobble mortars and evidence of wooden mortars; extensive sue of bone for tools and ornaments; large projectile points, with considerable use of rock other than obsidian; and use of baked clay.

Hotchkiss Culture (Late Horizon) -- The burial pattern retains the use of the flexed mode, and there is wide spread evidence of cremation, lesser use of red ocher, heavy sue of baked clay, *Olivella* beads of Types E and M, extensive use of *Haliotis* ornaments of many elaborate shapes and forms, shaped mortars and cylindrical pestles, bird-bone tubes with elaborate geometric designs, clam shell disc beads, small projectile points indicative of the introduction of the bow and arrow, flanged tubular pipes of steatite and schist, and use of magnesite. (The above adapted from Moratto 1984:181-183). The characteristics noted are not all-inclusive, but cover the more important traits.

The general chronology associated with this cultural succession has been revised on several occasions and there is regional variation as well. An extensive re-examination by Ragir (1972) made use of the large number of radiocarbon dates available by that time. The beginning of Windmiller (at least the mature expression--there is evidence of earlier beginnings) was dated at about 2000 B.C., much later than estimates by most earlier investigators. Ragir also found a considerable overlap between Windmiller and Cosumnes. In different geographic areas, these cultures appear to have coexisted for about a thousand years. The transition to Hotchkiss is much more clearly marked, coinciding with the introduction of the bow and arrow at about A.D. 500, but even so, there is persistence of the earlier culture for another 500 years or so in some localities.

The problems of dealing with this complex chronological and geographic situation have led to revisions in the Central California Taxonomic System (the Early, Middle and Late Horizon system) in order to provide a more flexible system. The above trait lists would now be considered characteristic of the Windmiller, Berkeley and Augustine Patterns, respectively, in the Cosumnes District. The concept of pattern, a general adaptive pattern that may be found over a large area and is independent of chronology, allows discussion of these trait associations without implying a linear progression or specific time span.

Ethnology

The Nisenan, or Southern Maidu, occupied the upper drainages and the adjacent ridges of the Yuba, the north, middle, and south forks of the American, and at least the upper north side of the Cosumnes River. The eastern limit of the territory is conventionally believed to extend to the crest of the Sierra. As well, the Nisenan in the valley proper occupied some area west of the lower reaches of the Feather River (Wilson and Towne 1978).

The Nisenan linguistically are grouped with the Northern Maidu and Konkow within the Penutian family (Riddell 1978:387). Kroeber distinguished three dialects within the larger territory occupied by the Nisenan, but Riddell indicated more distinctions are possible. Wilson and Towne (1978) distinguished several "centers" presumably linguistic and social groupings.

The Nisenan were socially integrated at the village or community group level (Wilson and Towne 1978), with the group participating in the decision-making process. The villages would range in size from 15 to 25 people to, at least in the Valley Nisenan, villages over 500 people (Kroeber 1925:821). A very large settlement consisted of a major village and associated smaller camps, whether general or specialized in nature. A headman, respected by all, residing in the major village had the authority to call upon the smaller associated groups in times of need, although the smaller groups did not have to always obey.

The villages for the Hill Nisenan were located on ridges and flats along the major streams and rivers within their territory. The satellite encampments and villages were probably located on the smaller water courses surrounding or nearby the major village.

The Nisenan, as with other Sierran groups, moved into the higher elevations during the hot summer months. The main activity was the collecting of pine nuts and numerous other species of nuts, roots,

and berries. This was done primarily by women and children. The foraging groups in a locale could range from small, extended family groups, composed of a woman, her immediate female kin, and their adolescent children to whole villages (Wilson and Towne 1978:389). The men spent most of their time hunting or fishing for a wide variety of fish and animals. Hunting was noted as often involving communal drives, with the best archers of the village posted to do the killing (Wilson and Towne 1978:389). Individual hunters made extensive use of decoys and imitative sounds.

Most Nisenan never left the territory used by their own village group. However, there were, in most large villages, at least some individuals who engaged in rather extensive trade with several valley groups as well as Sierra groups, such as the Washoe. The Hill Nisenan probably acquired obsidian and basketry from the east, in exchange for acorns from the Washoe but it is presently unclear whether they were visited by the Washoe or they visited the Washoe or both. Presumably, the exchange network functioned in the summer and fall.

History

The name Loomis was not used until the designation was applied to the Southern Pacific station in 1884. Previously, the place names of the area referred to small mining communities working the gravels near Secret Ravine. These communities included Placer, an area near Auburn that had a post office from October 1861 through January 1862. In 1862 the post office was moved to another town, Smithville (previously Pine Grove), in Secret Ravine, approximately six miles southwest of Newcastle (Gudde 1975: 268-325).

When the Smithville post office closed in 1869, the Postal Service reopened it in Pino, an old mining camp that formed in Secret Ravine in 1850. In 1884 the Postal Service and the railroad changed the town's name to Loomis, after Jim Loomis, the local railroad agent, apparently because the name "Pino" was often confused with Reno (Gudde 1969:182; Frickstad 1955:121).

As gold mining spread throughout the region, mining districts formed. One such district was the Rocklin District, a placer-mining district in Southwestern Placer County two miles east of Rocklin and two miles south of Loomis (Clark 1970). This district was not unusually active in the main mining era of California, but like many other mining areas saw a resurgence of small scale mining during and, to a lesser extent, after the Depression.

Although gold mining and quarrying remained important industries in Placer County, the value of the land for cultivation was recognized very early. An orchard was planted at Illinoistown as early as 1850. A variety of grains were experimented with in the valley -- including wheat, barley, oats, and hay. A number of vineyards were planted in both the valley and foothills. Orchards were extremely successful in the foothills, and the Central Pacific Railroad provided a much wider market in the east for California's agricultural products. A wide variety of fruits were raised -- including citrus, apples, peaches, pears, plums, cherries, olives, almonds, and walnuts (Thompson and West 1882:24-248; Lardner and Brock 1924:228-237).

In the project area, a patent was issued by U.S. Land Office on May 5, 1884 to Albert G. Bradshaw (Certificate No.1833). County assessor's records show Bradshaw proving up on land beginning in 1882. There is no mention of Bradshaw or his farm in local or regional histories.

INFORMATION CENTER RECORD SEARCH

A record search was conducted for the project area in January of 2015 by the North Central Information Center of the California Historical resources Information System. The record search

covered the area of all the alternatives then under consideration plus a 1/8 mile buffer zone around them. As a result, the record search covered much more land than would be affected by the preferred alternative.

Seven resources were identified by the Information as being in or near the project. Two of these are large, and partly overlapping, resources that occupy all of the project area north of Brace Road.

P-31-0123 (CA-PLA-807H) consists of the remains of the Bradshaw farm, as mentioned above, with concrete foundations, a cellar and down or nearly down sheds.

P-31-0126 (CA-PLA-810/H) is recorded in two discontiguous loci that occupy much of the project area between Brace Road and the northern project boundary. It includes the remains of a placer mining operation (sluicing) with associated badly eroded features. Most of the site features are located nearer to Secret Ravine than the area that will be affected by the preferred alternative. Three prehistoric bedrock milling stations are also incorporated into this site.

South of the above sites, the project alignment follows built roadways, Brace Road and Dias Lane, to the southern boundary of the project area. Although there have been several surveys in the vicinity, Only a small section of the preferred alternative along Dias Lane has been surveyed. The sites recorded nearby include P-31-0179 (CA-PLA-53), a bedrock milling feature east of Secret Ravine, and four resources near each other south of the project area. Two of these relate to more placer mining in the area and the other two are bedrock milling stations.

All of the current project area north of Brace Road was surveyed by Windmiller in 1995 and resurveyed by Vallaire and Windmiller (with updates of the site records) in 2014. The one section of Dias Lane that was examined was part of a larger project surveyed by Wadsworth in 2006.

Native American Communication

Peak & Associates contacted the NAHC in December of 2014 to determine if any resources recorded in their sacred lands file were located near the project area. Their reply of December 19, 2014 indicated that no such resources were known in the area. The NAHC included a list of knowledgeable individuals who could be contacted for further information on Native American concerns. Letters were written to the following individuals requesting any information they might care to contribute regarding the project. A map was included which, like the request to the Information Center, covered a larger area than the current project area.

Organization

[individual]

United Auburn Indian Community of the Auburn Rancheria

Shingle Springs Band of Miwok Indians

[individual] T'si-Akim Maidu

Colfax-Todds Valley Consolidated Tribe

Individual

Rose Enos
Gene Whitehouse
Marcos Guerrero
Jason Camp
Nicholas Fonseca
Daniel Fonseca
Hermo Olanio
April Wallace Moore
Eileen Moon
Grayson Coney
Don Ryburg
Pamela Cubbler
Judith Marks

Letter replies were received from Shingle Springs (Daniel Fonseca) and United Auburn (Gene Whitehouse). Both groups were unaware of specific resources in the area but did claim it as ancestral territory and asked to remain a consulting party to all further operations or decision making that could affect Native American resources. T'si-Akim Maidu (Grayson Coney) replied by telephone that once he had been shown a very large site near the southern end of the project area that had numerous artifacts on the surface. This would likely be nearer Secret Ravine than the preferred alternative is in this area or, possibly, in the Croftwood area south of the current project. He too requested continuing consultation regarding the project.

Evaluations of Significance

Both of the sites that could be impacted by the proposed project were evaluated by Ric Windmiller (M.A., RPA) and found not eligible for the National Register of Historic Places.

P-31-0123, the Bradshaw place, is associated with the fruit business in western Placer County, which is a significant economic activity, but Bradshaw is an almost unknown individual in this business. The deteriorated state of the site detracts from potential significance and artifacts observed at the site did not appear to provide any likelihood of illuminating the history of the site.

P-31-0126, the placer mining remains plus bedrock mortars is related to gold mining and, therefore, satisfies one criterion for inclusion on the register. In addition, it includes evidence of sluicing for placer gold and could satisfy another criterion in displaying the characteristics of a technology. However, it has been very heavily impacted by recent housing construction and has suffered severe erosion over the years. Windmiller felt that it did not retain sufficient integrity of design, setting and workmanship to satisfy the requirements for National Register eligibility.

We see no reason to dispute these findings.

Recommendations

There are no known significant cultural resources that will be impacted by the project. The record search and Native American communication both indicate that this is a sensitive region for cultural resources, both historic and prehistoric. Recommended mitigation measures are, therefore preventative.

- <u>CR-1</u> Before any construction takes place the South Placer Municipal Utility District should initiate consultation with the three Native American groups that have expressed a concern with the project. Ideally, one group could be identified as most likely descendants and further consultation would continue with that group to insure that Native American concerns are mitigated.
- <u>CR-2</u> When construction plans are complete, areas identified for staging area, equipment storage, spoils disposal and any other off-site impacts should be examined by a qualified archeologist/historian to identify any cultural resources that might be present.
- <u>CR-3</u> Trenching along Brace Road and Dias Lane should be monitored by a qualified archeologist/historian. These areas have not been surveyed and there is the potential for subsurface resources. The monitor should have the authority to halt trenching, if necessary, in order to evaluate any finds. Trenching could continue in other areas. Further actions would depend on whether or not the resource appears significant.
- <u>CR-4</u> Should artifacts, exotic rock (particularly obsidian), or concentrations of bone or shell be uncovered during any construction activities, an archeologist should be consulted for on-the-spot

evaluation. If the bone appears to be human, the Placer County Coroner must be contacted. If the coroner determines that the bone is most likely Native American in origin, he will contact the Native American Heritage Commission to identify most likely descendants for consultation regarding further treatment of the remains (if this has not already been accomplished..

References

Beardsley, Richard K.

Temporal and Areal Relationships in Central California Archeology (parts 1 and 11). *University of California Archaeological Survey Reports* 24, 25. Berkeley.

Chavez, David

1983 Archaeological Resource Investigations for the Southeast Placer County Wastewater Project, Placer County, California. Report on file: State Water Resources Control Board (Project # C-06-1271-010), Sacramento.

Clark, William B.

1970 Gold Districts in California. California Division of Mines and Geology, Sacramento.

Frickstad, Walter N.

1955 A Century of California Post Offices. Walter N. Frickstad, Oakland.

Gudde, Edwin G.

1969 California Place Names. University of California Press, Berkeley.

1975 California Gold Camps. University of California Press, Berkeley.

Kroeber, Alfred L.

1925 Handbook of the Indians of California. *Bureau of American Ethnology Bulletin 78*. Washington.

Lillard, Jeremiah B., Robert F. Heizer and Franklyn Fenenga

1939 An Introduction to the Archaeology of Central California. *Sacramento Junior College, Department of Anthropology Bulletin* 2. Sacramento.

Lillard, Jeremiah B. and William K. Purves

The Archeology of the Deer Creek-Cosumnes Area, Sacramento County, California. Sacramento Junior College, Department of Anthropology Bulletin 1. Sacramento.

Moratto, Michael J.

1984 California Archaeology. Academic Press, New York.

Ragir, Sonia

1972 The Early Horizon in Central California Prehistory. *University of California Research Contributions* 15. Berkeley.

Riddell, Francis A.

Maidu and Konkow. In *Handbook of North American Indians* (vol. 8), edited by Robert F. Heizer, pp. 370-387. Smithsonian Institution, Washington, D.C.

Schenck, W. Egbert and Elmer Dawson

1929 Archaeology of the Northern San Joaquin Valley. *University of California Publications in American Archaeology and Ethnology* 25(4):289-413. Berkeley.

Wilson, Norman L., and Arlean Towne

1978 Nisenan. In *Handbook of North American Indians* (vol. 8), edited by Robert F. Heizer. Smithsonian Institution, Washington, D.C.

APPENDIX 1

Information Center Results

California Historical Resources Information System



AMADOR EL DORADO NEVADA PLACER SACRAMENTO YUBA California State University, Sacramento 6000 J Street, Folsom Hall, Suite 2042 Sacramento, California 95819-6100 phone: (916) 278-6217 fax: (916) 278-5162 email: ncic@csus.edu

1/15/2015

NCIC File No.: PLA-14-150

Robert A. Gerry Peak & Associates, Inc. 3941 Park Drive, Suite 20-329 El Dorado Hills, CA 95762

Re: Loomis Diversion Line Alternatives

The North Central Information Center received your record search request for the project area referenced above, located on the Rocklin USGS 7.5' quad. The following reflects the results of the records search for the project area and a 1/8-mile radius:

As indicated on the data request form, the locations of reports and resources are provided in the following format: \boxtimes custom GIS maps \square shapefiles \square hand-drawn maps

Resources within search area:	P-31-123 P-3 P-31-1533 P-		P-31-1006 P-31-1009
Reports within search area:	401 2092 3° 8767	772 3909 3924	3932 3945 5980 6991

Resource Database Printout (list):	□ enclosed	\square not requested	\square nothing listed
Resource Database Printout (details):	\square enclosed	\square not requested	\boxtimes nothing listed
Resource Digital Database Records:	\square enclosed	\square not requested	⊠ nothing listed
Report Database Printout (list):	\boxtimes enclosed	\square not requested	\square nothing listed
Report Database Printout (details):	\square enclosed	\square not requested	⊠ nothing listed
Report Digital Database Records:	\square enclosed	\square not requested	⊠ nothing listed
Resource Record Copies:	□ enclosed	\square not requested	\square nothing listed
Report Copies:	\square enclosed	□ not requested	\square nothing listed

OHP Historic Properties Directory:	⊠ enclosed	□ not requested	□ nothing listed
Archaeological Determinations of Eligibility:	\boxtimes enclosed	\square not requested	\square nothing listed
CA Inventory of Historic Resources (1976):	\square enclosed	\boxtimes not requested	\square nothing listed
Caltrans Bridge Survey:	\square enclosed	\boxtimes not requested	\square nothing listed
Ethnographic Information:	\square enclosed	\boxtimes not requested	\square nothing listed
Historical Literature:	\square enclosed	□ not requested	\square nothing listed
Historical Maps:	\square enclosed	□ not requested	\square nothing listed
Local Inventories:	$\hfill\Box$ enclosed	\boxtimes not requested	\square nothing listed
GLO and/or Rancho Plat Maps:	\square enclosed	\boxtimes not requested	\square nothing listed
Shipwreck Inventory:	\square enclosed	\boxtimes not requested	\square nothing listed
Soil Survey Maps:	$\hfill\Box$ enclosed	\boxtimes not requested	\square nothing listed

Please forward a copy of any resulting reports from this project to the office as soon as possible. Due to the sensitive nature of archaeological site location data, we ask that you do not include resource location maps and resource location descriptions in your report if the report is for public distribution. If you have any questions regarding the results presented herein, please contact the office at the phone number listed above.

The provision of CHRIS Data via this records search response does not in any way constitute public disclosure of records otherwise exempt from disclosure under the California Public Records Act or any other law, including, but not limited to, records related to archeological site information maintained by or on behalf of, or in the possession of, the State of California, Department of Parks and Recreation, State Historic Preservation Officer, Office of Historic Preservation, or the State Historical Resources Commission.


Due to processing delays and other factors, not all of the historical resource reports and resource records that have been submitted to the Office of Historic Preservation are available via this records search. Additional information may be available through the federal, state, and local agencies that produced or paid for historical resource management work in the search area. Additionally, Native American tribes have historical resource information not in the California Historical Resources Information System (CHRIS) Inventory, and you should contact the California Native American Heritage Commission for information on local/regional tribal contacts.

Should you require any additional information for the above referenced project, reference the record search number listed above when making inquiries. Requests made after initial invoicing will result in the preparation of a separate invoice.


Sincerely,

Nathan Hallam Coordinator, North Central Information Center

Loomis Diversion Line Alternatives



Loomis Diversion Line Alternatives



Report List	List				
Report No.	Other IDs Year	ır Author(s)	Title	Affiliation	Resources
000401	1979	9 Eleanor H. Derr and Michael F. Rondeau	An Intensive Archeological Survey of the Stonegate Development Project, Placer County, California.	Archaeological Study Center	31-000423
002092	1989	9 Alfred Farber	Archaeological Survey of the Town of Loomis Westside Specific Plan Area, Placer County, California.	Professional Archaeological Services	
003772					
606200	1990	0 Steve Heipel	Cultural Resources Investigation Of The Proposed Croftwood Development Project, Placer County California Final Report	PAR Environmental Services, Inc.	31-001532, 31-001533
003924	1989	9 Susan Lindstrom	A Cultural Resource Evaluation Of The Croftwood Project Near Rocklin, California Placer County	Consultant	31-001005, 31-001006, 31- 001007, 31-001008, 31-001009, 31-001010, 31-001531
003932	1996	6 Ric Windmiller	Final Report On A Cultural Resources Inventory Of The Turtle Island Project Loomis, Placer County, California	Consulting Archaeologist	31-000122, 31-000123, 31- 000124, 31-000125, 31-000126
003945	1989	9 Melinda Peak	Cultural Resource Assessment Of The Rocklin Regional Mall Project Placer County, Calfornia	Peak & Associates, Inc.	31-001520, 31-001521, 31- 001554, 31-001555, 31-001556, 31-001557, 31-001568, 31- 001559, 31-001560, 31-001561, 31-001562, 31-001563
005980	2004	4 Ric Windmiller	Croftwood, Updated Cultural Resources Study, Rocklin, Placer County, California and April 2005 Supplement	Consulting Archaeologist	31-001005, 31-001007, 31- 001008, 31-002461, 31-002462, 31-002463, 31-003865
006991	2006	6 Jensen, Sean	Archaeological Inventory Survey Turtle Island Development Project, c. 60 acres at Loomis, Placer County, CA		
008767	2006	6 Sandra L. Wadsworth	Cultural Resources Assessment Rocklin 60, Placer County, California, Project 2005-090	ECORP Consulting, Inc.	31-001555, 31-001556, 31- 001557, 31-001558, 31-001562, 31-001563, 31-003182

Page 1 of 1

Resource List

Primary No.	Trinomial	Other IDs	Type	Age	Attribute codes	Recorded by	Reports
P-31-000123	СА-РLА-000807Н	Other - Site 1: Historic Farm Site	Site	Historic	AH02 (Foundations/structure pads); AH03 (Landscaping/orchard); AH11 (Walls/fences)	1995 (Ric Windmiller, Unknown); 2014 (Katherine Vallaire, Ric Windmiller Consulting Archaeologist)	003932
P-31-000126	CA-PLA-000810/H	Other - Site 4: Historic Mining Landscape	Site	Prehistoric, Historic	AH04 (Privies/dumps/trash scatters); AH08 (Dams); AH09 (Mines/quarries/tailings); AP04 (Bedrock milling feature)	1995 (Ric Windmiller, Consulting Archaeologist); 2014 (Katherine Vallaire, Ric Windmiller Consulting Archaeologist)	003932
P-31-000179	CA-PLA-000053	Other - 40/4	Site	Prehistoric	AP04 (Bedrock milling feature)	1957 (D.P. Jewell, Unknown)	
P-31-001006	CA-PLA-000880/H	Resource Name - Secret Ravine Placer Mine Complex; Other - Croftwood Project Site 2: Placer Mining Complex	Site	Historic	AH06 (Water conveyance system); AH09 (Mines/quarries/tailings)	1989 (S.G. Lindstrom, Unknown); 1990 (Neal Neuenschwander, Peak and Associates, Inc.); 1998 (Susan Lindstrom, Lizzie Bennett, Consulting Archaeologist); 1999 (S.G. Lindstrom, Unknown)	003924
P-31-001009	CA-PLA-000883/H	Resource Name - Secret Ravine Placer Mine Ditch; Other - CW- LF1	Site	Prehistoric, Historic	AH06 (Water conveyance system)	1998 (Susan Lindstrom, Lizzie Bennett, Consulting Archaeologist)	003924
P-31-001533	CA-PLA-001191	Other - Croftwood #2	Other	Prehistoric	AP04 (Bedrock milling feature)	1990 (J. Dougherty, K.R. Bethard, PAR Environmental Services, Inc.)	606800
P-31-001555	CA-PLA-001213	Other - PA-88-18	Site	Prehistoric	AP04 (Bedrock milling feature)	1988 (M Peak, N Neuenschwander, Peak & Associates, Inc.); 2005 (Saundra Wadsworth, Kyle Johnson, ECORP Consulting, Inc.); 2005 (Saundra Wadsworth, Kyle Johnson, ECORP Consulting, Inc.)	003945, 008767

Page 1 of 1

APPENDIX 2

Native American Communication

PEAK & ASSOCIATES, INC.

CONSULTING ARCHEOLOGY

30 Years: 1975-2005



December 11, 2014

Ms. Debbie Pilas-Treadway Native American Heritage Commission 915 Capitol Mall, Room 288 Sacramento, CA 95814

Dear Ms. Treadway:

Peak & Associates, Inc. has contracted with Hauge Brueck Associates to perform a cultural resources assessment for the proposed Loomis Diversion Pipeline Alternates in Placer County. The project involves several different alignments for a proposed pipeline between Secret Ravine and I80 south of Loomis. The project area lies in T11N, R7E, Sections 15 and 16 and is mapped on the Elk Grove 7.5' USGS quadrangle, which is the base for the attached map.

Because of federal grant funding, the project is a federal undertaking. In accordance with the Secretary of the Interior's Guidelines for implementing Section 106, we are requesting a list of appropriate Native American contacts for the project area. We also request a check of the Sacred Lands Inventory for any potential conflicts.

Thank you for your assistance.

Sincerely,

Robert A. Gerry, Consulting Archeologist


Peak & Associates, Inc. 3941 Park Drive, Suite 20-329

El Dorado Hills, CA 95762 (916)283-5238

Molat a Leny

FAX: (916)283-5239 peakinc@surewest.net

//RG Encl.



STATE OF CALIFORNIA

Edmund G. Brown, Jr., Governor

NATIVE AMERICAN HERITAGE COMMISSION

1550 Herbor Blvd., ROOM 100 West SACRAMENTO, CA 95691 (916) 373-8710 Fax (916) 373-5471



December 19, 2014

Robert A Gerry Peak & Associates, Inc. 3941 Park Drive, Suite 20, #329 El Dorado Hills, CA 95762

Sent By Fax: (916) 283-5239

Number of Pages: 3

Re: Loomis Diversion Pipeline Alternates, Placer County.

Dear Mr. Gerry,

A record search of the sacred land file has failed to indicate the presence of Native American cultural resources in the immediate project area. The absence of specific site information in the sacred lands file does not indicate the absence of cultural resources in any project area. Other sources of cultural resources should also be contacted for information regarding known and recorded sites.

Enclosed is a list of Native Americans individuals/organizations who may have knowledge of cultural resources in the project area. The Commission makes no recommendation or preference of a single individual, or group over another. This list should provide a starting place in locating areas of potential adverse impact within the proposed project area. I suggest you contact all of those indicated, if they cannot supply information, they might recommend others with specific knowledge. By contacting all those listed, your organization will be better able to respond to claims of failure to consult with the appropriate tribe or group. If a response has not been received within two weeks of notification, the Commission requests that you follow-up with a telephone call to ensure that the project information has been received.

If you receive notification of change of addresses and phone numbers from any of these individuals or groups, please notify me. With your assistance we are able to assure that our lists contain current information. If you have any questions or need additional information, please contact me at (916) 373-3712.

Sincerely,

Katy Sanchez

Associate Government Program Analyst

Native American Contacts Placer County December 16, 2014

Shingle Springs Band of Miwok Indians Hermo Olanio, Vice Chairperson

P.O. Box 1340

Miwok

Shingle Springs. CA 95682

Shingle Springs, CA 95682 Maidu

Miwok Maidu

holanio@ssband.org

(530) 676-8010 Office

T' si-Akim Maidu

P.O. Box 1340

(530) 676-8033 Fax

nfonseca@ssband.org (530) 676-8010 Office (530) 676-8033 Fax

Shingle Springs Band of Miwok Indians Nicholas Fonseca, Chairperson

Rose Enos

15310 Bancroft Road

Maidu

Grayson Coney, Cultural Director P.O. Box 1316

Maidu

, CA 95603 Auburn

Washoe

Colfax - CA 95713 akimmaidu@att.net

(530) 878-2378

(530) 383-7234

United Auburn Indian Community of the Auburn Rancheria

Gene Whitehouse, Chairperson

10720 Indian Hill Road Auburn

Maidu , CA 95603

Miwok

(530) 883-2390 Office

(530) 883-2380 Fax

United Auburn Indian Community of the Auburn Rancherla Marcos Guerrero, Tribal Preservation Committee

10720 Indian Hill Road

Maidu

Auburn

- CA 95603

Miwok

mguerrero@auburnrancheria.com

(530) 883-2364 Office

(530) 883-2320 Fax

T' si-Akim Maidu

Eileen Moon, Vice Chairperson

P.O. Box 1246

Maidu

Grass Valley, CA 95945

(530) 274-7497

April Wallace Moore

19630 Placer Hills Road

CA 95713

Nisenan - So Maidu

(530) 637-4279

Colfax

Konkow Washoe

This list is current only as of the date of this document.

Distribution of this list does not relieve any person of the statutory responsibility as defined in Section 7050.5 of the Health and Safety Code, Section 5097.94 of the Public Resources Code and Section 5097.98 of the Public Resources Code.

This list is only applicable for contacting locative Americans with regard to cultural resources for the proposed Loomis Diversion Pipeline Alternatives, Piecer County.

Native American Contacts Placer County December 16, 2014

Shingle Springs Band of Miwok Indians Daniel Fonseca, Cultural Resource Director

P.O. Box 1340

Miwok

Shingle

, CA 95682

Maidu

(530) 676-8010 Office

(530) 676-8033 Fax

T' si-Akim Maidu Don Ryberg, Chairperson

P.O. Box 1246

Grass Valley, CA 95945

Maidu

(530) 274-7497

Coffax-Todds Valley Consolidated Tribe **Judith Marks**

1068 Silverton Circle

Miwok

Lincoln

. Ca 95648

Maidu

(916) 580-4078

Colfax-Todds Valley Consolidated Tribe Pamela Cubbler

P.O. Box 734

Miwok

Foresthill

, Ca 95631

Maidu

(530) 320-3943

(530) 367-2093 home

United Auburn Indian Community of the Auburn Rancheria

Jason Camp, THPO

10720 Indian HIII Road

Maidu

Auburn

. CA 95603

Miwok

jcamp@auburnrancheria.com

(916) 316-3772 Cell

(530) 883-2390

(530) 888-5476 - Fax

This list is current only as of the date of this document.

Distribution of this list does not relieve any person of the statutory responsibility as defined in Section 7050.5 of the Health and Safety Code, Section 5097.94 of the Public Resources Code and Section 5097.98 of the Public Resources Code.

This list is only applicable for contacting locative Americans with regard to cultural resources for the proposed Loomis Diversion Pipeline Alternatives, Placer County.



SHINGLE SPRINGS RANCHERIA P.O. BOX 1340; SHINGLE SPRINGS, CA 95682

(530) 676-8010; FAX (530) 676-3582

January 14, 2015

Peak & Associates, Inc. 3941 Park Drive, Suite 20-329 El Dorado Hills, CA 95762

RE: Proposed Loomis Diversion Pipeline Alternates

Dear Robert A. Gerry

Thank you for your letter dated December 22, 2014 in regard to the Proposed Loomis Diversion Pipeline Alternates in Placer County. Based on the information provided, the Shingle Springs Band of Miwok Indians is not aware of any known cultural resources on this site. However, SSR would like to have continued consultation through updates, as the project progresses this will foster a greater communication between the Tribe and your agency.

SSR would also like to request any and all completed record searches and or surveys that were done in or around the project area up to and including environmental, archaeological and cultural reports.

If during the progress of the project new information or human remains are found we would like to be able to go over our process with you that we currently have in place to protect such important and sacred artifacts (especially near rivers and streams).

Please contact the following individuals if such finds are made:

Kara Perry, Administrative Assistant (530) 488-4049 kperry@ssband.org

And copy all communications to: Andrew Godsey, Assistant Cultural Resource Director / NAI agodsey@ssband.org

Thank you for providing us with this notice and opportunity to comment.

Sincerely,

Daniel Fonseca

Cultural Resource Director

Tribal Historic Preservation Officer (THPO)

Most Likely Descendent (MLD)











MIWOK MAIDU

United Auburn Indian Community of the Auburn Rancheria

Gene Whitehouse Chairman John L. Williams Vice Chairman Danny Rey Secretary Brenda Adams Treasurer Calvin Moman Council Member

January 27, 2015

Robert Gerry Peak & Associates 3941 Park Drive, Suite 20-329 El Dorado Hills, CA 95762

Subject: Loomis Diversion Pipeline Alternates Cultural Resources Assessment

Dear Robert Gerry,

Thank you for requesting information regarding the above referenced project. The United Auburn Indian Community (UAIC) of the Auburn Rancheria is comprised of Miwok and Southern Maidu (Nisenan) people whose tribal lands are within Placer County and whose service area includes El Dorado, Nevada, Placer, Sacramento, Sutter, and Yuba counties. The UAIC is concerned about development within its aboriginal territory that has potential to impact the lifeways, cultural sites, and landscapes that may be of sacred or ceremonial significance. We appreciate the opportunity to comment on this and other projects in your jurisdiction.

In order to ascertain whether the project could affect cultural resources that may be of importance to the UAIC, we would like to receive copies of any archaeological reports that are completed for the project. We also request copies of future environmental documents for the proposed project so that we have the opportunity to comment on potential impacts and proposed mitigation measures related to cultural resources. And, we would like the opportunity to have our tribal monitors accompany you during the field survey. The information gathered will provide us with a better understanding of the project and cultural resources on site and is invaluable for consultation purposes.

The UAIC's preservation committee would like to set up a meeting and begin consulting on the proposed project. Thank you again for taking these matters into consideration, and for involving the UAIC early in the planning process. We look forward to reviewing the documents requested above and consulting on your project. Please contact Marcos Guerrero, Cultural Resources Manager, at (530) 883-2364 or by email at mguerrero@auburnrancheria.com if you have any questions.

Sincerely,

Gene Whitehouse,

Chairman

CC: Marcos Guerrero, CRM

Tribal Office 10720 Indian Hill Road Auburn, CA 95603 (530) 883-2390 FAX (530) 883-2380

Telephone Communication 1/5/2015

Grayson Coney T'si Akim Maidu

He says that the T'si Akim are close to gaining federal recognition, therefore, they are getting more active in monitoring construction projects in their traditional area.

He was shown, a few years ago, a very large site somewhere near the southern end of the area shown on our map. There were a large number of lithic artifacts on the surface. He considers the general area of Secret Ravine to be very sensitive for sites of heritage importance to him and his people and, therefore, wishes to be consulted regarding future stages of this project.

Appendix D

General Plan Consistency Table

General Plan Consistency:

Tables 1 and 2 provide an analysis of the consistency of the Project with the applicable Town of Loomis 2001 General Plan and 2012 City of Rocklin General Plan. The goals, policies, and action programs relevant to the Project are listed in each table, along with the consistency analysis related to each goal, policy, and action program. As shown in the tables, the Project is consistent with most general plan goals, policies, and action programs. In relation to cultural resources and biological resources, consistency is achieved with the implementation of mitigation measures. There are no instances where the Project is inconsistent with the General Plans and unmitigable. Goals, policies, and programs not relevant to the Project are not included in the consistency analysis

Tab	le 1
Town of Loomis 2001 Ge	eneral Plan Consistency
Relevant Goals, Policies, & Programs	Consistency Analysis
Chapter III – Land Use and	Community Development
Goal 1: To preserve, maintain, and enhance creeks and riparian areas for both their aesthetic and wildlife habitat values. Goal 2. To protect groundwater and surface water quality.	Consistent. The Project supports this goal by locating the pipeline away from Secret Ravine Creek and the associated riparian habitat. Consistent. The Project does not propose use of groundwater or surface waters, but includes best management practices in accordance with the SWPPP to protect these resources.
Goal 3. To protect oak woodlands and significant stands of native trees.	Consistent with Mitigation. The Project would result in the removal of protected trees as discussed in the biological resources analysis of the IS/MND. Mitigation Measure BIO-7 addresses tree protection, removal, and replacement and mitigates this impact.
Goal 4. To protect major landscape features within Loomis, including significant topography and rock outcroppings, open meadows and grazing areas.	Consistent. The majority of the alignment is located within existing roadways, tunnels under sensitive areas, and is located within proposed roadway. Although the alignment would cut through undeveloped land on the Turtle Island property, the pipeline would be underground and located in an area planned for development.
Policy E.1. Loomis shall maintain a balance between residential building density and the capacity of the circulation system, schools, fire and police services, and other public service facilities.	Consistent. The Project supports this goal by providing adequate capacity to serve existing customers as well as planned and approved development in the area. The Project addresses an existing capacity deficiency and is sized to address the surrounding developments that have been approved for development.
Policy E.2. New residential development shall be required to bear the full financial burden for new public service capital improvements required to serve the residents of the development, through impact fees, environmental mitigation fees, and other appropriate measures. Policy E.8. Loomis shall promote the full utilization of land already committed to urban development	Consistent. New residential developments in the Project area financially support the Project. Consistent. The Project is located within the SPMUD Urban Service Boundary and serves areas
before utilities and public services are extended to	identified in the General Plan for growth.

Tab	le 1
Town of Loomis 2001 G	
Relevant Goals, Policies, & Programs	Consistency Analysis
areas without existing urban infrastructure	,
Policy E.18. All new development in Loomis shall	Consistent. Underground sanitary sewer lines are
conform to the land use map, land use categories and	allowed in the area land use categories.
development intensities set forth in this General Plan.	
Chapter IV.	Circulation
Goal LOS: To strive for service levels that reflect a	Consistent. The Project will tunnel under I-80 and
balance between mobility, cost-effectiveness, and	Horseshoe Bar Road and will not affect LOS.
financial resources.	Traffic controls during construction will ensure
	safety on Brace Road and Dias Lane and effects on
LOS Policy: In order to minimize congestion,	LOS would be temporary (less than one year).
maintain Level of Service C on all roads and	
intersections within the Town of Loomis. Level of	
Service D may be allowed in conjunction with	
development approved within the Town as an	
exception to this standard, at the intersections of	
King and Taylor, Horseshoe Bar Road and Taylor,	
Horseshoe Bar Road and I-80, Sierra College and	
Brace Road, and Webb and Taylor, when: The	
deficiency will be temporary (less than three years),	
and a fully-funded plan is in place to provide the	
improvements needed to remedy the substandard	
condition.	
Chapter VI – Public Servic	es, Facilities, and Finance
Goal 1: To achieve and maintain high levels of	Consistent. The Project proposes to maintain
public services and facilities for Loomis residents,	adequate capacity in the SPMUD sanitary sewer
when appropriate through coordination with outside	line serving the Loomis area. Currently, the line
service agencies.	operates at capacity during storm events, and will
	exceed operating capacity with the development of
Policy 1. Loomis will work toward achieving and	approved residential and commercial projects in the
maintaining acceptable levels of municipal services,	service area.
including public safety, roadway maintenance, and	
administrative services. Loomis will cooperate with	
regional public service agencies to attain adequate	
service levels for water distribution, sewerage	
services, flood management, and solid waste	
collection	
Policy 2. Non-residential and higher density	Consistent. The Project serves areas planned for
residential development shall not be expanded into	development within the contiguous development
areas lacking public services infrastructure until	area around I-80 and Horseshoe Bar Road.
existing vacant land with these services within the	Developers will finance the SPMUD improvements
Town limits is utilized, or proposed development	to the sanitary sewer line.
ensures the extension of necessary infrastructure	
through actual construction or payment of fees	
Policy 4: Proposed development shall be connected	Consistent. The Project proposes to maintain
to public water supply and sewage disposal systems	adequate capacity in the SPMUD sanitary sewer
as follows:	line serving the Loomis area. Currently, the line
1. Any dwelling unit proposed within 300 feet of	operates at capacity during storm events, and will
existing community water supply or sewage	exceed operating capacity with the development of
disposal service shall be connected to that	approved residential and commercial projects in the
service prior to occupancy	service area. Developers will finance the SPMUD

Tab	le 1
Town of Loomis 2001 Ge	eneral Plan Consistency
Relevant Goals, Policies, & Programs	Consistency Analysis
 All development proposed in nonresidential land use designations shall be connected to the community water supply and sewage Residential subdivisions proposing parcels of 2.2 acres or less shall be connected to the community water supply and sewage 	improvements to the sanitary sewer line.
Chapter VII. Conser	vation of Resources
Natural Resources	
Goal 1. To protect areas rich in wildlife of a fragile ecological nature, including areas of rare or endangered species and riparian areas, from land development impacts	Consistent with Mitigation. The Project has the potential to affect protected species, and wetlands and waters of the U.S. as discussed in the biological resources analysis of the IS/MND. Mitigation Measures BIO-1, 2, 3, 4, 5, and 6 mitigate potential impacts to protected species, wetlands and waters of the U.S. and wildlife nursery sites. Additional surveys shall be conducted to verify presence or absence and if needed, measures enforced to mitigate potential impacts.
Goal 2. To preserve, maintain, and enhance creeks and riparian areas for their aesthetic, wildlife habitat, and recreational values	Consistent with Mitigation. The Project does not propose to construct within Secrete Ravine Creek, but has the potential to affect wetlands and waters of the U.S. as discussed in the biological resources analysis of the IS/MND. Mitigation Measures BIO-5 mitigate potential impacts to wetlands and waters of the U.S. Additional surveys shall be conducted to verify the extent of impact and additional measures enforced to mitigate potential impacts.
Goal 3. To help protect groundwater and air quality within the Sacramento region	Consistent. The Project will not use groundwater or emit air pollutants during operation. Construction will temporarily emit air pollutants; however, the emission levels would not exceed thresholds and the Project includes construction measures to reduce emissions during construction.
Goal 4. To protect major open space areas and natural features within the Town, including significant topography and rock outcroppings, oak woodlands and significant specimens of native trees	Consistent. The majority of the alignment will be located within existing roadway pavement or ROW and will be located below ground. There are no significant topographical features in the area, and oak woodlands and other significant trees will be avoided where feasible. Some tree removal will occur on a case by case basis where the individual tree cannot be avoided. The affected areas are planned for future development.
Policy 1. Loomis will contribute toward the attainment of State and Federal air quality standards in the Sacramento Valley Air Basin through the following, and other feasible measures. a. Site preparation and development activities shall incorporate effective measures to minimize dust emissions and the emissions of pollutants by motorized construction equipment and vehicles. b. During the review of development plans, the	Consistent. The Project will not emit air pollutants during operation. Construction will temporarily emit air pollutants; however, the emission levels would not exceed thresholds and the Project includes construction measures to reduce emissions during construction.

Tab	le 1	
Town of Loomis 2001 General Plan Consistency		
Relevant Goals, Policies, & Programs	Consistency Analysis	
Town should require that project proponents conduct their own air quality analysis to determine air quality impacts and potential mitigation measures. Policy 2. Prior to approval of discretionary	Consistent. Biological resource and wetland	
development permits involving parcels near significant ecological resource areas, the Town shall require, as part of the environmental review process, a biotic resources evaluation by a qualified biologist. The biologist shall follow accepted protocols for surveys (if needed) and subsequent procedures that may be necessary to complete the evaluation.	surveys have been conducted for the project area.	
Policy 3. The Town shall discourage grading activities during the rainy season, unless adequately mitigated, to avoid sedimentation of creeks and damage to riparian areas.	Consistent. The Project includes project measures that address erosion control, runoff, and sedimentation. A SWPPP with BMPs and temporary construction control measures will be prepared and implemented as part of the construction phase of the Project. See Regulatory Compliance Measure 2.6.4 Stormwater Pollution Prevention Plan.	
Policy 5. Individual heritage trees and significant stands of heritage trees shall be preserved. Healthy heritage trees shall be removed or significantly trimmed only when necessary because of safety concerns, conflicts with utility lines and other infrastructure, the need for thinning to maintain a healthy stand of trees, or where there is no feasible alternative to removal. Proposed development shall be designed, constructed, and maintained to preserve individual heritage trees and significant stands of heritage trees, and provide for the protection of root zones and the continuing health of the trees. When trees are removed, they shall be replaced in sufficient numbers to maintain the volume of the Town's overall tree canopy over a 20-year period. Tree removal within stream corridors is also subject to the above policy on stream corridor protection	Consistent with Mitigation. The Project would result in the removal of protected trees as discussed in the biological resources analysis of the IS/MND. Mitigation Measure BIO-7 addresses tree protection, removal, and replacement and mitigates this impact.	
Policy 6. The streams of Loomis are among the most significant and valuable of the Town's natural resources. Development adjacent to streams shall be designed, constructed, and maintained to avoid adverse impacts on riparian vegetation, stream bank stability, and stream water quality to the maximum extent feasible. These policies shall apply to all watercourses shown as blue lines on the most recent United States Geological Survey (USGS) 7.5-minute topographic quadrangle maps applicable to the Town.	Consistent with Mitigation. The Project would not be located adjacent to streams or Secret Ravine Creek. Although nearby, the Project would not affect these resources and would be sufficiently distant so as not to affect stream banks. The General Plan states that public utilities are not subject to the 100-foot riparian vegetation setback. No staging or spoil disposal would occur within riparian areas. The affected wetland and riparian habitat would be mitigated through Mitigation Measure BIO-5.	
Policy 7. The Town will contribute toward the maintenance of high quality in the local surface and groundwater resources through the following, and	Consistent. The Project includes project measures that address erosion control, runoff, and sedimentation. A SWPPP with BMPs and	

Tab	le 1	
Town of Loomis 2001 General Plan Consistency		
Relevant Goals, Policies, & Programs	Consistency Analysis	
other feasible measures	temporary construction control measures will be prepared and implemented as part of the construction phase of the Project. See Regulatory Compliance Measure 2.6.4 Stormwater Pollution Prevention Plan. The Project does not propose to use or discharge to surface or groundwaters. Operation would not affect runoff or discharge to surface waters.	
 Policy 8. The following policies apply to properties with wetland areas: a. The environmental review of development on sites with wetlands shall include a wetlands delineation, and the formulation of appropriate mitigation measures. The Town shall support the "no net loss" policy b. The Town shall require new development to mitigate wetland lossto achieve "no net loss" through any combination of the following, in descending order of desirability: 1. Avoidance of riparian habitat; 2. Where avoidance is not feasible, minimization of impacts; 3. Companyation including use of a mitigation 	Consistent with Mitigation. Biological resource and wetland surveys have been conducted for the project area. The Project has been designed to avoid wetland features where feasible. The affected wetland areas would be mitigated through implementation of Mitigation Measure BIO-5.	
 3. Compensation, including use of a mitigation banking programthat are encouraged to be located within the Town; or 4. Replacement of a degraded or destroyed wetland at a ratio of from 1:1 to 4:1 c. The Town will require project-by-project review of sites where vernal pools exist d. The Town will require the preservation of native riparian and wetland areas as open space to the maximum extent feasible 		
Policy 9. Loomis will work cooperatively with state, regional, and local agencies in protecting natural resources.	Consistent. The Project will be reviewed by federal, state, and local agencies with jurisdiction over natural resources. Necessary permits and approvals will be obtained prior to construction as described in the Project Description.	
Cultural R		
Goal 1. To preserve and where appropriate replicate historic areas, such as the Downtown district and fruit sheds, that contribute to Loomis' distinct character. Policy 5. As part of the environmental review process, the Town shall review all development	Consistent. The record search identified resources within the project; however these resources have been found ineligible for the National Register of Historic Places. Consistent with Mitigation. The Cultural Resources evaluation conducted for the project revealed no	
proposals for their potential to disturb cultural resources. In areas where cultural resources are known to occur, give special consideration to development of facilities that enhance the operation, enjoyment, and maintenance of these areas	resources listed or eligible for listing under the National Register of Historic Places. Because the area is a sensitive region for historic and prehistoric cultural resources, preventative measures are proposed for the project to ensure resources are protected. These measures include a preconstruction Native American consultation, staging	

Tab	le 1
Town of Loomis 2001 Ge	eneral Plan Consistency
Relevant Goals, Policies, & Programs	Consistency Analysis
	area, storage, and spoil disposal site review, and trench monitoring during the construction phase of the Project.
Chapter VIII. Public	
Safe	
Goal 1. To reduce risks associated with natural and man-made hazards through compliance with State and Federal safety programs Goal 2. To reduce the risks associated with wildland	Consistent. The Project would not generate hazards. Wastewater would be delivered to the existing treatment facility. Consistent. Operation of the Project would not
and urban edge fires in the Town's rural areas	result in a fire hazard. Construction methods include spark arrestors and fire extinguishers on construction machinery and equipment.
Goal 3. To reduce the potential for and damage resulting from storm flooding hazards within the community	Consistent. The Project would not contribute to flood hazards. Construction near the 100-year flood zone would be conducted through tunneling. The Project would not impede or redirect flood flows.
Goal 4. To reduce the risks associated with potential seismic activity, including groundshaking, liquefaction, and landslides	Consistent. The Project would not induce seismic activity, and includes no habitable structures that would place persons or property at risk during seismic events. Soils are not prone to liquefaction and there is no landslide risk in the project area. The pipeline is designed and engineered to ensure the line does not fail during a seismic event.
Policy 2. Engineering analysis of new development proposals shall be required in areas with possible soil instability, flooding, earthquake faults, or other hazards, and prohibit development in high danger areas.	Consistent. The pipeline is designed and engineered to ensure the line does not fail due to soil instability or other hazard. The Project is an underground pipeline and would not utilize hazardous materials during operation.
Policy 4. No new structures or additions to existing structures shall be permitted in areas identified by the federal Flood Insurance Rate Maps (FIRMs) or the Town Engineer as being subject to innundation in a 100-year or more frequent flood event. Exceptions may be granted for public facilities and utilities.	Consistent. The Project would not contribute to flood hazards. Construction near the 100-year flood zone around I-80 and Horseshoe Bar Road would be conducted through tunneling. The Project would not impede or redirect flood flows. Development within Dias Lane and Brace Road would not affect flows as the pipeline would be located underground beneath existing roadway pavement with no change in the roadway grade or slope. The roadways would be restored to match existing grade and slope following installation of the pipeline and filling of the trench.
Policy 8. Loomis shall cooperate with Federal, State, and local authorities to ensure that loss due to seismic activity and other natural and man-made disasters is minimized.	Consistent. Federal, state, and local regulatory agencies will review the proposed project documentation and their concerns integrated into the Project. Necessary permits will be acquired prior to construction as discussed in the Project Description.
Noi	
Goal 1. To protect Town residents and workers from the harmful and annoying effects of noise	Consistent. Project operations will not generate noise. Project construction activities will be limited to between the hours of 7:00 am and 7:00 pm

Tab	le 1
Town of Loomis 2001 Ge	eneral Plan Consistency
Relevant Goals, Policies, & Programs	Consistency Analysis
Policy 4. Individual noise exposure analysis shall be required for proposed development projects as part of the environmental review process, to ensure that the Town's noise standards are meet. The use of mitigation measures (noise buffers, sound insulation) may be required to reduce noise impacts to acceptable levels	Monday through Friday in accordance with Municipal Code Section 13.30.070 (Project Measure 2.6.2) and shrouding or shielding of impact tools and muffling or shielding intake and exhaust ports on construction equipment will be implemented to reduce construction noise levels.
Policy 18. Require that the hours of truck deliveries to industrial and commercial properties adjacent to residential uses be limited to daytime hours unless there is no feasible alternative or there are overriding transportation benefits by scheduling deliveries at night	
Policy 19. Require that construction activities adjacent to residential units be limited as necessary to prevent adverse noise impacts	

Table 2	
City of Rocklin 2012 General Plan Consistency	
Relevant Goals, Policies, & Programs	Consistency Analysis
Chapter IV.B – Open Space, Conservation and Recreation Element	
Policy OCR-8. Encourage public utility companies and agencies to consult with the City prior to undertaking projects that may affect open space and natural resource areas to minimize impacts to these areas. Goal. Conserve and protect natural resources while permitting their managed use, consistent with City, State and Federal requirements	Consistent. The Project is proposed in response to existing capacity limitations and proposed and approved developments in the area that will require additional sanitary sewer capacity. The Project is developed in response to those existing needs. Consistent. Within the City of Rocklin, the Project would be limited to the ROW and area adjacent to the Dias Lane ROW. As discussed in the Project Description, the Project will be reviewed by the regulatory agencies and necessary permits or
Policy OCR-39. Require the protection of wetlands, vernal pools, and rare, threatened and endangered species of both plants and animals through either avoidance of these resources, or implementation of appropriate mitigation measures where avoidance is not feasible, as determined by the City of Rocklin.	mitigation will be obtained prior to construction. Consistent with Mitigation. The Project has the potential to affect protected species, and wetlands and waters of the U.S. as discussed in the biological resources analysis of the IS/MND. Mitigation Measures BIO-1, 2, 3, 4, 5, and 6 mitigate potential impacts to protected species, wetlands and waters of the U.S. and wildlife nursery sites. Additional surveys shall be conducted to verify presence or absence and if needed, measures enforced to mitigate potential impacts.
Policy OCR-40. Require compliance with the State and Federal Endangered Species Acts and the Clean Water Act as conditions of development project approval.	Consistent. As discussed in Section 2.7 of the Project Description, the Project will be reviewed by the appropriate regulatory agencies and the necessary permits and approvals will be acquired

Table 2		
City of Rocklin 2012 General Plan Consistency		
Relevant Goals, Policies, & Programs	Consistency Analysis	
-	and implemented prior to Project construction.	
Policy OCR-41. Recognize that onsite protection of natural resources may not always be feasible and that offsite methods, such as use of mitigation banks, may be used.	Consistent. Biological resource and wetland surveys have been conducted for the project area. The Project has been designed to avoid wetland features where feasible. The affected wetland areas would be mitigated through implementation of Mitigation Measure BIO-5.	
Policy OCR-42. Encourage projects to be designed in a manner that protects heritage oak trees and other botanically unique vegetation designated to be retained.	Consistent with Mitigation. The Project would result in the removal of protected trees as discussed in the biological resources analysis of the IS/MND. Mitigation Measure BIO-7 addresses tree protection, removal, and replacement and mitigates	
Policy OCR-43. Mitigate for removal of oak trees and impacts to oak woodlands in accordance with the City of Rocklin's Oak Tree Preservation Ordinance, or for projects located in zones not directly addressed by the Oak Tree Preservation Ordinance mitigation measures, on a project-by-project basis through the planning review and entitlement process.	this impact.	
Policy OCR-49. Minimize the degradation of water quality through use of erosion control plans and Best Management Practices.	Consistent. The Project includes project measures that address erosion control, runoff, and sedimentation. A SWPPP with BMPs and temporary construction control measures will be	
Policy OCR-50. Maintain a grading ordinance that minimizes erosion and siltation of creeks and other watercourses.	prepared and implemented as part of the construction phase of the Project. See Regulatory Compliance Measure 2.6.4 Stormwater Pollution Prevention Plan. The Project does not propose to use or discharge to surface or groundwaters. Operation would not affect runoff or discharge to surface waters. The Project would not discharge into creeks or watercourses in Rocklin.	
Policy OCR-55. Consider the visual qualities of development projects and project compatibility with surrounding areas, especially when projects are proposed in urbanizing areas abutting rural or semi-rural areas where significant natural resource values exist.	Consistent. The Project proposes an underground sanitary sewer pipeline needed to address existing capacity issues as well as proposed and approved developments within the area. Construction of the pipeline within and around Dias Lane would not result in substantial visual change in the area as most of the alignment would be beneath existing pavement. The only visible changes would result from the manholes located in the roadway that would serve the pipeline.	
Policy OCR-58. Require development projects to incorporate stationary and mobile source control measures recommended by the Placer County Air Pollution Control District and approved by the City for protection of air quality during construction and subsequent operations.	Consistent. The Project will not emit air pollutants during operation. Construction will temporarily emit air pollutants; however, the emission levels would not exceed thresholds and the Project includes construction measures to reduce emissions during construction. See Regulatory Compliance Measure 2.6.1 which includes measures to comply with PCAPCD Fugitive Dust Control directives.	
Goal. Conserve and protect unique community	Consistent with Mitigation. The Cultural Resources	

Table 2

City of Rocklin 2012 General Plan Consistency

Relevant Goals, Policies, & Programs

features such as geologic, historic and culturally significant sites

Policy OCR-62. Preserve historically significant resources in place if feasible, or provide mitigation prior to further disturbance.

Policy OCR-65. Preserve significant archaeological resources (including Native American remains) and paleontological resources in place if feasible, or provide mitigation prior to further disturbance.

Consistency Analysis

evaluation conducted for the project revealed no resources listed or eligible for listing under the National Register of Historic Places. Because the area is a sensitive region for historic and prehistoric cultural resources, preventative measures are proposed for the project to ensure resources are protected. These measures include a preconstruction Native American consultation, staging area, storage, and spoil disposal site review, and trench monitoring during the construction phase of the Project.

Chapter IV.C – Circulation Element

Policy C-17. Keep truck traffic away from residential areas and streets not structurally designed for truck traffic by designating truck routes.

Policy C-19. Maintain existing streets in a safe condition and require that new streets be built to City standards.

<u>Consistent.</u> Project construction will include some traffic along Dias Lane. Traffic controls during construction will ensure safety on Dias Lane and effects on LOS would be temporary (less than one year). Following installation and coverage of the pipeline Dias Lane would be repaved and restored.

Chapter IV.D - Community Safety Element

Goal. To minimize danger from hazards and to protect residents and visitors from earthquake, fire, flood, other natural disasters, and human-created hazards such as train derailment, industrial accidents, acts of war or terrorism, and accidental release of harmful materials

Policy S-1. Require engineering analysis of new development proposals in areas with possible soil instability, flooding, earthquake faults, or other hazards, and to prohibit development that cannot mitigate the applicable hazard

Policy S-9. Ensure that the 100-year floodplain, based upon the most current information, both upstream and downstream, is not adversely affected by new development.

Policy S-10. Require that new development detain on-site drainage such that the rate of runoff flow is maintained at pre-development levels, except where detention is not recommended in plans and policies adopted by the PCFCWCD, and to require coordination with other projects' master plans to ensure no adverse cumulative effects. In lieu of detention, the City may require retention and/or off-site drainage improvements that are more beneficial

Consistent. The Project would not induce seismic activity, and includes no habitable structures. Soils are not prone to liquefaction and there is no landslide risk in the project area. The Project would not impede or redirect flood flows. Development within Dias Lane would not affect flows as the pipeline would be located underground beneath existing roadway pavement with no change in the roadway grade or slope. The roadways would be restored to match existing grade and slope following installation of the pipeline and filling of the trench. The Project would not contribute to flood flows as the only new impervious surface would be the proposed manholes. The pipeline is designed and engineered to ensure the line does not fail during a seismic event or other natural disaster.

Consistent. The Project proposes an underground pipeline, portions of which would be below existing paved ROW. Those portions outside existing paved ROW would not increase impervious coverage other than new manholes and the existing drainage patterns and rates would persist following construction.

Table 2		
City of Rocklin 2012 General Plan Consistency		
Relevant Goals, Policies, & Programs	Consistency Analysis	
to the community's overall drainage system.		
Policy S-11. Ensure that new development does not		
result in on-site flooding or increase flooding of off-		
site properties.		
Policy S-14. Require that construction activities	<u>Consistent</u> . There are no listed sites within the	
cease if contamination is discovered on construction	project area and no historical uses that suggest	
projects until the contamination is reported, and its	contamination may be present.	
extent is assessed, delineated, and isolated, as		
appropriate. Remediation shall occur to the		
satisfaction of the appropriate responsible agency Chapter IV. E –	Noise Flement	
Goal 1. To protect City residents from the harmful	Consistent. Project construction activities will be	
and annoying effects of exposure to excessive noise	limited to between the hours of 7:00 am and 7:00	
and annoying effects of exposure to excessive noise	pm Monday through Friday, and shrouding or	
	shielding of impact tools and muffling or shielding	
	intake and exhaust ports on construction equipment	
	will be implemented to reduce construction noise	
	levels.	
Chapter IV F – Public Servi		
Goal. To provide high quality public facilities and a	Consistent. The Project proposes to maintain	
full range of public services to all areas and residents	adequate capacity in the SPMUD sanitary sewer	
of the City, and to ensure that new development does	line serving the Loomis/Rocklin area. Currently,	
not cause the inefficient use of such facilities and services	the line operates at capacity during storm events,	
Services.	and will exceed operating capacity with the development of approved residential projects in the	
	service area. The project would be installed in	
Policy PF-1. Provide for adequate lead time in the	conjunction with proposed residential development	
planning of needed expansions of public services and	and prior to residential occupancy. Developers will	
facilities.	finance the SPMUD improvements to the sanitary	
Delia DE 2 Description de description	sewer line.	
Policy PF-3. Require that any development that		
generates the need for public services and facilities,		
including equipment, pay its proportional share of providing those services and facilities		
providing those services and facilities		
Policy PF-5. Require that construction of private		
development projects be coordinated with the		
construction of public facilities and services that are		
needed to serve the project.		
Policy PF-11. Ensure that new development will not	Consistent. Construction and operation of the	
create a significant negative impact on the existing	pipeline would not increase demand for police or	
level of police and fire protection services.	fire protection services.	
Policy PF-38. Coordinate roadway maintenance and	Consistent. Following installation and coverage of	
construction projects with utility companies and	the pipeline, Dias Lane would be repaved and	
private developers to minimize pavement cuts in new	restored.	
or resurfaced streets.		